PACIFIC TORQUE

ORIGINAL

Invoice

Invoice No:	084704	
Invoice Date:	Due Date:	Terms:
10/31/12	10/31/12	CASH to SHIP

Customer PO No.

CREDIT CARD

Contact

JUSTIN WEYMOUTH

PACIFIC TORQUE LLC
18060 DES MOINES MEMORIAL DR S
SEATTLE, WA 98148-1950

Page: 1

Order Date	Our Order No.	Ship Date	Shipping Terms	Pkg Tracking #	Shipped Via	Cust. Phone:	SalesPerson
10/15/12	SO-014425	10/31/12	EXW-Seattle		DELIVER		
Master Job	**Manufacturer**	**Model #**	**Assembly #**	**Serial #**			
R043046	DZ	F4L1011F	NA	21503912			
Vehicle Make	**Vehicle Model**	**Unit #**	**License #**	**VIN**	**Mileage / Hours**	**In Service**	
					0.00		

Item No.	Description	Ordered Quantity	Invoiced Quantity	Unit Price	Total Price
	EXCHANGE SALE DEUTZ F4L1011F ENGINE Warranted by Deutz Corporation's 36 month Limited Warranty			5,950.00	5,950.00

PAID BY CREDIT CARD

Subtotal:	5,950.00
Total Sales Tax:	565.25
Total:	**6,515.25**

Thank you for your business

Phone: 206-241-8300 **North America: 800-726-5300** **FAX: 206-244-5299** **www.pacifictorque.com**

PACIFIC TORQUE

ORIGINAL

Invoice

Invoice No:	084705	
Invoice Date:	Due Date:	Terms:
10/31/12	10/31/12	CASH to SHIP

Customer PO No.

CREDIT CARD

Contact

JUSTIN WEYMOUTH

PACIFIC TORQUE LLC
18060 DES MOINES MEMORIAL DR S
SEATTLE, WA 98148-1950

Page: 1

Bill To:

Ship To:

Order Date	Our Order No.	Ship Date	Shipping Terms	Pkg Tracking #	Shipped Via	Cust. Phone:	SalesPerson
10/15/12	SO-014426	10/31/12	EXW-Seattle			[redacted]	[redacted]
Master Job	**Manufacturer**	**Model #**	**Assembly #**	**Serial #**			
R043046	DZ	F4L1011F	NA	21503912			
Vehicle Make	**Vehicle Model**	**Unit #**	**License #**	**VIN**	**Mileage / Hours**	**In Service**	
					0.00		

Item No.	Description	Ordered Quantity	Invoiced Quantity	Unit Price	Total Price
	CORE CHARGE DEUTZ F4L1011F ENGINE	1	1	1,300.00	1,300.00

CORE RETURN POLICY:
For any core credit refund, the returned core must arrive Pacific Torque-Seattle, free of all charges within 30 days of the exchange unit being shipped. For a full core credit the core must be (i) complete, (ii) without external damage (iii) the same configuration as the rebuilt exchange unit and (iv) must not have been disassembled. The core must not have been involved in fire or flood.

Subtotal:	1,300.00
Total Sales Tax:	123.50
Total:	**1,423.50**

Thank you for your business