

# KENWORTH NORTHWEST

WASHINGTON & ALASKA'S FULL SERVICE KENWORTH TRUCK DEALER

<b>SEATAC</b>	2022D International Blvd. SeaTac, WA 98198	(206) 433-5911 (800) 562-0060		<b>MARYSVILLE</b>	11300 31 <sup>st</sup> Drive N.E. Marysville, WA 98271	(360) 658-7049 (800) 561-7753
<b>ABERDEEN</b>	120 South Maple Aberdeen, WA 98520	(360) 533-3356 (800) 228-9332		<b>BELLINGHAM</b>	929 Thomas Road Bellingham, WA 98226	(360) 733-9400 (800) 733-9403
<b>YAKIMA</b>	907 South 18 <sup>th</sup> Street Yakima, WA 98907	(509) 452-8564 (800) 831-4629		<b>LAKEWOOD</b>	12507 Pacific Hwy SW Lakewood, WA 98499	(253) 536-8800 (855) 436-8800

Customer: R/O CASH SALE ICC  
00012 Z N Z  
  
, WA 98271

Ship To: R/O CASH SALE ICC  
, WA 98271

**CUSTOMER INVOICE**  
Work Order  
**MS74827**  
Invoice Date: 11-30-17

4-8 72--1566

Tax ID:

Tax ID Data:

Page 1 of 4

Year	Make / Model	VIN	License	Mileage	Unit / Stock	Authorization
2010	KENWORTH / T660	1XKAD48X4AJ268969		729639	148	
Open Date / Time	Delivery Date	Delivery Mileage	Engine Hours	Reefer Hours	Standby Hours	P.O. Number
11-16-17 / 07:36AM	12-28-09					
Complete	Engine Model / Serial #	Transmission Model/Serial #	Key Tag	Service Writer		
11-30-17	ISX / 79406721	/		JA*EP		
<b>Memo</b>						

1 CHECK ENGINE LIGHT ON. CHECK AND ADVISE  
ENGINE HOURS: 22410  
HOOKED UP INSIGHT AND CHECKED CODES. HAS ACTIVE CODE 2639 AND 1667.  
UNIT ALSO HAS A ENGINE MISS AND EXHAUST LEAK AT TURBO PIPE. CHECKED  
FOR ENGINE MISS AND FOUND CYL #4 NOT FIRING. #4 INJECTOR WILL NEED TO  
BE REPLACED AND DPF AND DOC REMOVED AND CLEANED.  
PULL AIR CLEANER AND VALVE COVER, FOUND INTAKE CROSSOVER FELL OUT ,  
ROCKER HAS FLAT SPOT ON ROLLER, AND CAM IS DAMAGED.ON #4 CYL. PRICED  
PARTS OUT  
MOVED TRUCK UNDER HOIST. REMOVED RADIATOR. STARTED REMOVING OVERHEAD.  
FOUND #4 INTAKE ROCKER ARM AND CAM LOBE BAD, FOUND INJECTOR LOBE AT #2  
BAD ALSO. REMOVED INTAKE MANIFOLD AND FUEL MANIFOLD. REMOVED FRONT  
COVER,TIMING GEARS AND CAMSHAFTS.  
INSTALLED BOTH NEW VALVE AND INJECTOR CANSHAFTS. SET TIMING. INSTALLED  
TIMING COVER,FAN HUB,FAN AND SHROUD. INSTALLED ROCKER ARMS. REPLACED  
#2 AND #3 INJECTOR ROCKERS AND #4 AND #5 INTAKE ROCKERS.  
ADJUSTED OVERHEAD. INSTALLED FUEL MODULE,INTAKE MANIFOLD AND CRANKCASE  
FILTER HSG. INSTALLED RADIATOR. HOOK UP HOSES AND FILLED COOLING  
SYSTEM. VACUUM AND RECHARGE AC.

TOTAL LABOR	2,370.00
TOTAL PARTS	4,639.06
TOTAL CONSUMABLES	8.39
TOTAL FREIGHT	48.00
TOTAL MACHINE CHARGE	59.95

Qty	Part Number	Desc	Unit	Extended
-----	-------------	------	------	----------

**TERMS, WARRANTIES, RETURN POLICY**

1. Any warranties on the product sold hereby are those made by the manufacturer. The seller hereby expressly disclaims all warranties, either express or implied, including any warranty of merchantability or fitness for a particular purpose, and the seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sales of said products. Any limitation herein does not apply where prohibited by law. 2. NO REFUNDS WITHOUT THIS INVOICE. 15% HANDLING CHARGE ON ALL RETURNED ITEMS. NO RETURNS ON ELECTRICAL OR SPECIAL ORDERED ITEMS. ALL PARTS MUST BE RETURNED WITHIN 30 DAYS. 3. Customer agrees Kenworth Northwest Inc. is not liable for down time. Customer has read and agrees with all charges on this invoice. Customer agrees to pay all collections fees, attorney fees, and all other legal costs incurred by Kenworth Northwest Inc. Should any matter related to this invoice be referred to an attorney or collection agency 4. TERMS: NET CASH 10TH OF THE MONTH FOLLOWING DATE OF CHARGE 1.5% WILL BE CHARGED ON PAST DUE ACCOUNTS. PAST DUE ACCOUNTS WILL BE PLACED ON C.O.D.

<p><b>Remit To Address:</b> PO Box 98967 Seatac, WA 98198-0967</p>
--

Customer: X \_\_\_\_\_

Date: \_\_\_\_\_

**CUSTOMER INVOICE**

**Work Order  
MS74827**

Invoice Date: 11-30-17

Page 2 of 4

Year	Make / Model	VIN	License	Mileage	Unit / Stock	Authorization
2010	KENWORTH / T660	1XKAD48X4AJ268969		729639	148	
Open Date / Time	Delivery Date	Delivery Mileage	Engine Hours	Reefer Hours	Standby Hours	P.O. Number
11-16-17 / 07:36AM	12-28-09					
Complete	Engine Model / Serial #	Transmission Model/Serial #	Key Tag	Service Writer		
11-30-17	ISX / 79406721	/		JA*EP		
Memo						

1	4298626CUM	CAMSHAFT	1,643.69	1,643.69
1	4985660CUM	SEAL-RECT	6.69	6.69
1	3330537	SEAL,O RI	2.99	2.99
1	3330538	SEAL,O RI	2.99	2.99
1	3684306CUM	CAMSHAFT	1,815.69	1,815.69
1	3679931CUM	SEAL-O RI	11.69	11.69
1	4299124CUM	SEAL-O RI	10.29	10.29
2	4311990CUM	LEVER,ROC	251.99	503.98
2	4386048CUM	LEVER, RO	65.99	131.98
1	4965689CUM	GASKET-CO	37.49	37.49
1	3678770CUM	GASKET-CO	20.69	20.69
1	3683526CUM	HOSE,FLEX	69.99	69.99
1	4010600CUM	SEAL,O RI	3.99	3.99
2	3052586CUM	SEAL,O RI	3.99	7.98
1	3347939CUM	SEAL-O RI	2.99	2.99
1	3679932CUM	SEAL,O RI	8.39	8.39
1	4299125CUM	SEAL-REAR	13.29	13.29
1	3688114CUM	PLUG-GEAR	7.39	7.39
1	4962721CUM	SEAL-RECT	26.49	26.49
1	3689465CUM	PULLEY-ID	82.29	82.29
22	71386	WIRETIEBL	0.59	12.98
1	3347937	SEAL,O RI	3.09	3.09
2	EC3501	COOLANT-T	11.84	23.68
1	AT010	FUSE-PLUG	1.09	1.09
1	3886396	6.2 CALIB	82.29	82.29
1	2892782	HOSE,PLAI	69.99	69.99
1	3683537	GASKET,EX	10.99	10.99
1	90-0013	CLAMP-V B	17.29	17.29
1	2866337CUM	GASKET-EX	6.69	6.69
1	105LUB	LUBRPLA	8.39	8.39
1	FREIGHT	UPSG	48.00	48.00
1	MACHINE CHARGE	MCHG	59.95	59.95
	LAPTOP FEE			

- 2 REMOVE DOC AND DPF FOR CLEANING  
REMOVED DOC AND DPF FOR CLEANING. DOC HAD SEVERAL DEEP GOUGES IN IT.  
INSTALLED DPF AND DOC. NEEDS CPL/CALIBRATION CHANGE. ORDERED FLEET  
CAL.  
CALIBRATED ECM TO UPDATED REVISION FOR NEW DPF.
- |                    |          |
|--------------------|----------|
| TOTAL LABOR        | 675.00   |
| TOTAL PARTS        | 2,302.41 |
| TOTAL SUBLET LABOR | 175.00   |
| TOTAL CORE CREDIT  | -155.00  |
| TOTAL CORE CHARGE  | 155.00   |

**TERMS, WARRANTIES, RETURN POLICY**

1. Any warranties on the product sold hereby are those made by the manufacturer. The seller hereby expressly disclaims all warranties, either express or implied, including any warranty of merchantability or fitness for a particular purpose, and the seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sales of said products. Any limitation herein does not apply where prohibited by law. 2. NO REFUNDS WITHOUT THIS INVOICE. 15% HANDLING CHARGE ON ALL RETURNED ITEMS. NO RETURNS ON ELECTRICAL OR SPECIAL ORDERED ITEMS. ALL PARTS MUST BE RETURNED WITHIN 30 DAYS. 3. Customer agrees Kenworth Northwest Inc. is not liable for down time. Customer has read and agrees with all charges on this invoice. Customer agrees to pay all collection fees, attorney fees, and all other legal costs incurred by Kenworth Northwest Inc. Should any matter related to this invoice be referred to an attorney or collection agency. 4. TERMS: NET CASH 10TH OF THE MONTH FOLLOWING DATE OF CHARGE. 1.5% WILL BE CHARGED ON PAST DUE ACCOUNTS. PAST DUE ACCOUNTS WILL BE PLACED ON C.O.D.

<b>Remit To Address:</b>
PO Box 98967
Seatac, WA 98198-0967

Customer: X \_\_\_\_\_

Date: \_\_\_\_\_

CUSTOMER INVOICE

**Work Order  
MS74827**

Invoice Date: 11-30-17

Page 3 of 4

Year	Make / Model	VIN	License	Mileage	Unit / Stock	Authorization
2010	KENWORTH / T660	1XKAD48X4AJ268969		729639	148	
Open Date / Time	Delivery Date	Delivery Mileage	Engine Hours	Reefar Hours	Standby Hours	P.O. Number
11-16-17 / 07:36AM	12-28-09					
Complete	Engine Model / Serial #	Transmission Model/Serial #		Key Tag	Service Writer	
11-30-17	ISX / 79406721	/			JA*EP	
Memo						

Qty	Part Number	Desc	Unit	Extended
1	2866337CUM	GASKET-EX	6.69	6.69
1	2866636CUM	GASKET-EX	6.69	6.69
1	90-0012	CLAMP-V B	15.29	15.29
1	4388409RXCUM	MODULE, PA	2,178.69	2,178.69
1	2866337CUM	GASKET-EX	6.69	6.69
2	2871453CUM	GASKET-DP	23.69	47.38
1	2871453CUM	GASKET-DP	23.69	23.69
1	90-0013	CLAMP-V B	17.29	17.29
1	SUBLET LABOR		175.00	175.00
PLEASE CLEAN AND INSPECT				
-1	4388409RXCUM*	CORE TBRB	155.00	-155.00
1	4388409RXCUM#	CORE	155.00	155.00

3 REPLACE TURBO PIPE  
 PULL BROKE TURBO PIPE AND INSTALL NEW ONE CUT OFF CLAMP BOLTS AND  
 INSTALL NEW ONES  
 REMOVED STEP AND BRACKET. LOOSENED UP EXHAUST. REPLACED CLAMP AND  
 GASKET AT REAR OF FLEW. STARTED A REGEN AGAIN. FOUND V-CLAMP LEAKING  
 AT DPF INLET. REPLACED V-BAND CLAMP AND STARTED REGEN AGAIN.  
 TOTAL LABOR 240.00  
 TOTAL PARTS 409.68  
 TOTAL FREIGHT 23.00

Qty	Part Number	Desc	Unit	Extended
1	M66-1862	PIPE-EXHA	402.99	402.99
1	2866636CUM	GASKET-EX	6.69	6.69
1	FREIGHT	IN COMING	23.00	23.00

4 COUNTER PARTS  
 TOTAL PARTS 28.49  
 TOTAL FREIGHT 18.00

Qty	Part Number	Desc	Unit	Extended
1	591456	CYLINDER	28.49	28.49
1	FREIGHT		18.00	18.00
				MISCELLANEOUS SUPPLIES 229.95
				ENVIRONMENTAL CHARGES 88.60

R/O CORE SLS ICC 155.00

**TERMS, WARRANTIES, RETURN POLICY**

1. Any warranties on the product sold hereby are those made by the manufacturer. The seller hereby expressly disclaims all warranties, either express or implied, including any warranty of merchantability or fitness for a particular purpose, and the seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sales of said products. Any limitation herein does not apply where prohibited by law. 2. NO REFUNDS WITHOUT THIS INVOICE. 15% HANDLING CHARGE ON ALL RETURNED ITEMS. NO RETURNS ON ELECTRICAL OR SPECIAL ORDERED ITEMS. ALL PARTS MUST BE RETURNED WITHIN 30 DAYS. 3. Customer agrees Kanworth Northwest Inc. is not liable for down time. Customer has read and agrees with all charges on this invoice. Customer agrees to pay all collection fees, attorney fees, and all other legal costs incurred by Kanworth Northwest Inc. Should any matter related to this invoice be referred to an attorney or collection agency. 4. TERMS: NET CASH 10TH OF THE MONTH FOLLOWING DATE OF CHARGE 1.5% WILL BE CHARGED ON PAST DUE ACCOUNTS. PAST DUE ACCOUNTS WILL BE PLACED ON C.O.D.

<b>Remit To Address:</b>
PO Box 98967
Seatac, WA 98198-0967

Customer: X \_\_\_\_\_

Date: \_\_\_\_\_

CUSTOMER INVOICE

**Work Order  
MS74827**

Invoice Date: 11-30-17

Page 4 of 4

<b>Year</b>	<b>Make / Model</b>	<b>VIN</b>	<b>License</b>	<b>Mileage</b>	<b>Unit / Stock</b>	<b>Authorization</b>
2010	KENWORTH / T660	1XKAD48X4AJ268969		729639	148	
<b>Open Date / Time</b>	<b>Delivery Date</b>	<b>Delivery Mileage</b>	<b>Engine Hours</b>	<b>Reefer Hours</b>	<b>Standby Hours</b>	<b>P.O. Number</b>
11-16-17 / 07:36AM	12-28-09					
<b>Complete</b>	<b>Engine Model / Serial #</b>	<b>Transmission Model/Serial #</b>		<b>Key Tag</b>	<b>Service Writer</b>	
11-30-17	ISX / 79406721	/			JA*EP	
<b>Memo</b>						

R/O CORE CREDITS ICC	-155.00
RO PTS ICC SVC SALES	7,379.64
RO SUB ICC SVC SALES	175.00
MACH EARN ICC	59.95
RO L&F ICC SVC SALES	8.39
RO LAB ICC SVC SALES	3,285.00
CUS FRGT RECOV RESAL	89.00
SHOP SUPPLIES - ICC	229.95
RECYCLE CHARGE ICC	88.60
SALES TAX	0.75
<b>PLEASE PAY THIS TOTAL</b>	<b>11,316.28</b>

**TERMS, WARRANTIES, RETURN POLICY**

1. Any warranties on the product sold hereby are those made by the manufacturer. The seller hereby expressly disclaims all warranties, either express or implied, including any warranty of merchantability or fitness for a particular purpose, and the seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sales of sold products. Any limitation herein does not apply where prohibited by law. 2. NO REFUNDS WITHOUT THIS INVOICE. 15% HANDLING CHARGE ON ALL RETURNED ITEMS. NO RETURNS ON ELECTRICAL OR SPECIAL ORDERED ITEMS. ALL PARTS MUST BE RETURNED WITHIN 30 DAYS. 3. Customer agrees Kenworth Northwest Inc. is not liable for down time. Customer has read and agrees with all charges on this invoice. Customer agrees to pay all collections fees, attorney fees, and all other legal costs incurred by Kenworth Northwest Inc. Should any matter related to this invoice be referred to an attorney or collection agency. 4. TERMS: NET CASH 10TH OF THE MONTH FOLLOWING DATE OF CHARGE. 15% WILL BE CHARGED ON PAST DUE ACCOUNTS. PAST DUE ACCOUNTS WILL BE PLACED ON C.O.D.

**Remit To Address:**  
**PO Box 98967**  
**Seatac, WA 98198-0967**

Customer: X \_\_\_\_\_

Date: \_\_\_\_\_

**CUSTOMER INVOICE**