

CUSTOMER COPY

PAGE 1 OF 3

Porsche Seattle North

18600 Hwy 99 Lynnwood, WA 98037 www.porscheseattlenorth.com



The Reynolds and Reynolds Company ERAINTINVE SF725417 Q (07/24)

1759964	JOE K	136!	5278 TAG NO	258	10/31/24	P3CS817733
1700004		LICENSE NO.	MILEAGE		COLOR	STOCK NO.
Y	YEAR / MAKE / MODEL 14/PORSCHE/	011/2DP CA	B CAPPE		DELIVERY DATE	DELIVERY MILES
	VEHICLE I,D, NO. W P O C B 2				SELLING DEALER NO.	PRODUCTION DATE
	F.T.E.NO.		P.O. NO.	4 3 7	R.O. DATE 10/30/24	
RUSINESS PHONE	COMMENTS			72	10/30/24	MO: 1650
B# 1 CHARGES					DISCLAIMER OF	WARRANTIES AND
BOR					LIMITATION All parts and service	OF LIABILITY as provided in conne
CLIENT STATES THEIR VEHICLE IS DEA ABOUT 3 YEARS. PLEASE CHECK AND ADVISE. Verified battery does not hold cha replace battery.	TECH(S): D. STATES THE CAR	1365350 S SAT FOR		0.00	warranties, either including implied w ability or fitness for Dealership is not damage or loss th	pressly disclaims a express or implie arranties of merchar a particular purpos responsible for a at may occur to yo
B# 1 TOTALS					vehicle or its conten You agree that by	ts during or after repa using our services y
JOB# 1 DB# 2 CHARGES	JOURNAL PREFIX F	3CS J0B# 1	TOTAL 	0.00	release Dealership damages, injury,	from any liability or losses. The or lay apply are tho
AMCO Re-programming DME and transmissio Performed and completed campaign.	TECH(S): n control units Performed scope 1	: 1365350 L	*****	WARRANTY	provided by the madoes not assume person to assume connection with this	anufacturer. Dealersl or authorize any oth for it any liability transaction.
DB# 2 TOTALS			TOTAL	0.00	ANY DIRECT, INCONSEQUENTIAL,	NOT BE LIABLE FO DIRECT, INCIDENTA SPECIAL, OR PUNITI FROM THIS TRAN
ABOR					ACTION, INCLUDING	DAMAGES FOR LOT
# 3 05PSZ-91 DRIVEABILITY CAMPAIG WLA4 Retrofit heat shield Performed and completed campaign.	TECH(S): Performed scope :	: 1365350 1		WARRANTY	BASED IN CONTRAING NEGLIGENCE	CT OR TORT, INCLU IN NO EVENT WI TAL LIABILITY ON A CEED THE AMOUNT
ARTSQTYFP-NUMBERDESCRI	MEMBER VET	TOTAL -		WARRANTY WARRANTY WARRANTY 0.00	to perform the service invoice and that yo opportunity to inspe- you made such a rec	authorize the Dealers es/repairs itemized in to u received (or had ot) any replaced parts uest. The vehicle is be change for your paym
DB# 3 TOTALS					of amounts owed.	onange for your paying
DB# 4 CHARGES	JOURNAL PREFIX	P3CS J0B# 3	TOTAL	0.00	DATE CUST	OMER SIGNATURE
ABOR	TECH(S) module not have parts i	:1365350 n stock.	******	INTERNAL	added a charge ed cost of labor and \$35.00, to the R	COSTS: We had used to 3.5% of the to parts, not to exceepair Order for shoonnection with
ARTSQTYFP-NUMBERDESCRI 0 000-043-210-07 AIR FI PART ON SPECIAL ORDER	LTER	UNIT	PRICE-	INTERNAL		RE NEW UNLESS SE INDICATED.
** QUANTITY 1 IS SPECIAL C 0 000-043-211-10 PRESSU	RDERED ** JRE SWITC			INTERNAL	Jen K.	Inkail

[CONTINUED ON NEXT PAGE] 09:09am



CUSTOMER COPY

PAGE 2 OF 3

Porsche Seattle North

18600 Hwy 99 Lynnwood, WA 98037 www.porscheseattlenorth.com

The Reynolds and Reynolds Company ERAINTINVE SF725417 Q (07/24)

1759964	JOE K		65278		10/31/24	P3CS817733
	LABOR RATE	LICENSE NO.	MIL	16,501	COLOR	STOCK NO.
ZCO COMEDCET IN	YEAR / MAKE / MODEL 14/PORSCHE/	O11/2DP /	CAR CA		DELIVERY DATE	DELIVERY MILES
	VEHICLE LD NO				SELLING DEALER NO.	PRODUCTION DATE
	W P O C B	2 A 9 / E	P.O. NO.	3 4 4 5 7	R.O. DATE	
					10/30/24	
RESIDENCE PHONE BUSINESS PHONE	COMMENTS	¥2			•	MO: 16502
PARTSQTYFP-NUMBER	PTIONRDERED **		r PRICE- - PARTS		LIMITATION All parts and service	WARRANTIES AND OF LIABILITY es provided in connec- action are provided AS
JOB# 4 TOTALS				0.00	IS. Dealership ex warranties, either	pressly disclaims all express or implied, varranties of merchant-
JOB# 4 .					ability or fitness fo	r a particular purpose, responsible for any
LABOR J# 5 OOPSZ-00 MULTIPOINT INSPECT PERFORM MULTIPOINT VEHICLE SAFETY INCLUDES VISUAL INSPECTION OF ENGI DRIVETRAIN, BRAKING SYSTEM, COOLIN ITEMIZED IN THE MPI REPORT CARD.	TECH(S) INSPECTION. NE. SUSPENSION.	:1365350		INTERNAL	damage or loss the vehicle or its content You agree that by release Dealership damages, injury, warranties that in	nat may occur to your to state during or after repair. using our services you from any liability for or losses. The only nay apply are those
JOB# 5 TOTALS					provided by the m does not assume person to assume	anufacturer. Dealership or authorize any other e for it any liability in
JOB# 5 JOB# 6 CHARGES	JOURNAL PREFIX	P3CS JOB#	5 TOTAL	0.00	connection with this	s transaction.
LARON	TECH(S)	:1365350			DEALERSHIP WILL ANY DIRECT, IN CONSEQUENTIAL, DAMAGES ARISIN ACTION, INCLUDIN OF USE OR LOS	NOT BE LIABLE FOR DIRECT, INCIDENTAL SPECIAL, OR PUNITIVE G FROM THIS TRANS G DAMAGES FOR LOSS T PROFIT, WHETHER ACT OR TORT, INCLUD
CANAL A VENEZUE			6 TOTAL	0.00	ING NEGLIGENCE	. IN NO EVENT WILL TAL LIABILITY ON ALL
JOB# 6 JOB# 7 CHARGES					CLAIMS, IF ANY, EX THE REPAIR ORDE	CEED THE AMOUNT OF
Added Operation (33JK5278 @ 10/30/2024 15:12) CLIENT REQUESTS TO INSTALL NEW BAT removed and replaced 12volt engine battery to vehicle after installin designed.	TECH(S) TERY. start battery. g new battery. w	:1365350 programmed orks as		446.95	to perform the service invoice and that yo opportunity to inspect you made such a re-	u authorize the Dealership ces/repairs itemized in this ou received (or had the out) any replaced parts i quest. The vehicle is being xchange for your paymen
PARTSQTYFP-NUMBERDESCRI 1 992-915-105-A BATTER	Y P110N		234.7 - PARTS	6 234.76	DATE CUS	TOMER SIGNATURE
JOB# 7 TOTALS		LABOR PARTS	7 TOTAL	446.95 234.76	added a charge ed cost of labor and \$35.00, to the F	COSTS: We have qual to 3.5% of the total parts, not to excee Repair Order for should connection with this
JOB# 7	JOURNAL PREFIX	13C2 70R#	/ IUIAL	681.71	repair.	CONTROCTION WITH THE
LABOR				295.00	OTHERWI	ARE NEW UNLESS SE INDICATED.
Added Operation (33JK5278 @ 10/30/2024 16:53) CLIENT REQUESTS TO PERFORM STEERIN RECALIBRATION.	IG ANGLE SENSOR					Inkard RD AUTO GROUP

[CONTINUED ON NEXT PAGE] 09:09am



Porsche Seattle North

18600 Hwy 99 Lynnwood, WA 98037 www.porscheseattlenorth.com



CUSTOMER NO. 1759964	JOE K	1365	278 TAG	258	10/31/24	INVOICE NO. P3CS817733
	LABOR RATE	LICENSE NO.	MILEAGE	16,501	COLOR	STOCK NO.
ZOO COMEDOET IN	YEAR / MAKE / MODEL 14/PORSCHE	/911/2DR CA	B CARR		DELIVERY DATE	DELIVERY MILES
Zanonae, mr. covae zano	VEHICLE I,D, NO, W P O C B	2 A 9 7 E S	1 5 4	4 4 5 7	SELLING DEALER NO.	PRODUCTION DATE
	F. T. E, NO		O. NO.		R, O, DATE 10/30/24	
RESIDENCE PHONE	COMMENTS					MO: 16502
after installing new battery faul sensor calibration was active. pe sensor calibration. JOB# 8 TOTALS	rformed steering	angle			LIMITATION All parts and service tion with this transaction. Dealership exp	WARRANTIES AND OF LIABILITY as provided in connec- ction are provided AS pressly disclaims all
		LABOR		295.00		express or implied, arranties of merchant-
JOB# 8	JOURNAL PREFIX			295.00	ability or fitness for Dealership is not	a particular purpose. responsible for any
JOB # A F15 THANK YOU! JOB # A F14 THANK YOU! JOB # A F05 PORSCHE SHOP SUPPLIES		TOTAL - M		30.00 -30.00 34.18 34.18	vehicle or its content You agree that by u release Dealership damages, injury, o	at may occur to your s during or after repair. sing our services you from any liability for or losses. The only
COMMENTSTOW IN 10/29 NO VIN NO QUOTES OR TIME -LOCATION RECOMMENDED NOT DONE/ DECLINED SERVICES	N VERTETED LA			\$4808.84	provided by the ma does not assume o	ay apply are those nufacturer. Dealership or authorize any other for it any liability in transaction.
TOTALS		TOTAL LABOR TOTAL PARTS TOTAL SUBLE TOTAL G.O.G TOTAL MISC TOTAL MISC TOTAL TAX	T CHG. DISC	741.95 234.76 0.00 0.00 64.18 -30.00 107.15	DEALERSHIP WILL ANY DIRECT, IND CONSEQUENTIAL, S DAMAGES ARISING ACTION, INCLUDING OF USE OR LOST BASED IN CONTRAI ING NEGLIGENCE. DEALERSHIP'S TOTA CLAIMS, IF ANY, EXC THE REPAIR ORDER	
CUSTOMER SIGNATURE					to perform the service invoice and that you opportunity to inspec	authorize the Dealership s/repairs itemized in this u received (or had the t) any replaced parts i

you made such a request. The vehicle is being returned to you in exchange for your payment of amounts owed.

CUSTOMER SIGNATURE

SHOP SUPPLY COSTS: We have added a charge equal to 3.5% of the total cost of labor and parts, not to exceed \$35.00, to the Repair Order for shop supplies used in connection with this repair.

ALL PARTS ARE NEW UNLESS OTHERWISE INDICATED.

> LMK. Inkard SWICKARD AUTO GROUP

PAGE 3 OF 3

CUSTOMER COPY

[END OF INVOICE] 09:09am

The Reynolds and Reynolds Company ERAINTINVE SF725417 Q (07/24)

Porsche Seattle North Multipoint

Custo	ome	r Na	me	Vehicle Year/Model: 14 PORSCI	HE 911		1/2024 09:08:06
Phon	_			VIN: WP0CB2A97ES154457		Odometer: 18	
Servi	ice A	dvis	or: JOE K	Technician: MIKE MORALES	16	RO: 817733	Tag: 258
			PECTION RESULT - OK	WILL REQUIRE FURTHER ATTENT		REQUIRES IMMEDIA	TE ATTENTION
Green	Yellov	v Red			Serviced	Front / Rear B	raka Linings
V			Horn operation			LF	RF
Y	片		Headlights / tail lights / turn s		ㅡ붜	Green	Green 🔽
Y	Щ		Windshield wiper and washer	operation	뷰	Yellow	Yellow
V		볼	Windshield glass		ㅡ붜	Red	Red 📕
V	<u></u>		Fuel tank cap gasket	W-2 - 28	_붜	4	
Y			Dome light / amp light / dimm	er combination meter	ㅡ붜		
V		ينيا	Cabin air filter			LR	RR
V			Parking brake operation			Green Yellow	Green Yellow
V			Check installation of driver's fl	oormat		Red	Red
V			Air filter			Serviced	
V			Battery condition (cables / cla	mps / corrosion)			Not Takon
V			Cooling system (leaks)				Not Taken
\checkmark			Hoses (cracks / damage / leak	(S)		6MM AND	
\checkmark			Drive belts (cracks / damage /	leaks)		3MM AND	
V			Radiator core / air condition co	ondenser (if equipped)		Charle Tires	Tuesd Death
M			Windshield washer			LF Crieck Tires /	Tread Depth
V			Coolant			Green	Green 🔽
V			Power steering (if equipped)			Yellow	Yellow
V			Brake reservoir			Red Red	Red 📕
V			Clutch reservoir (if equipped)			觀看了	
V			Transmission / transaxle				97
M			Differential (if equipped)			LR	RR
M			Propeller / driveshaft (damage	e / leaks / U-joints)		Yellow	Yellow
M			Drive/CV shaft (damage / leak	ss / boots)		Red	Red
V			Axle hub and bearing (damag	e / leaks / noise)		Serviced	-
V			Steering linkage (damage / le	aks / worn components)		6MM AND	HIGHER
V			Suspension (damage / leaks /	worn components)		4MM TO	5MM
V			Fluid leaks (engine / transmiss	sion / differential)		3MM AND	LOWER
V			Exhaust system (damage / lea	aks / corrosion)		Check Battery	Performance
V			Fuel lines & connections / fuel	tank bands / fuel tank vapor			ood Serviced
	\checkmark		Recommended maintenance			The second second	air Serviced
Bral	ce Li	ning	Measurements: LF: 8 mm RF: 8	3 mm LR: 8 mm RR: 8 mm		Ba	
_	_	_	leasurements: LF: 10/32" RF: 10				
Tire	Pre	ssur	e Measurements: LF: 36psi RF: 3	36psi LR: 44psi RR: 44psi		Actual Cold Crankin	g Amps
						Factory Cold Cranki	ng Amps
						1	



PAY TYPE:CREDIT CARD DATE/TIME:2024-10-31 09:10:08 CARD:Visa XXXXXXXXXXXXXXXXXXXX

RC:00 / Approved APP:00931D TRN ID:0D0001 BILLING NAME:CARDHOLDER/VISA

EM:Contactlessicc AC:ARQC 38C9F723C70106 ATC:0412 AID:A0000000031010 VISA CREDIT

Porsche Seattle North

18600 Hwy 99 Lynnwood, WA 98037 www.porscheseattlenorth.com



CUSTOMER NO. 1759964	ADVISOR JOE K	13652	78 TAG NO. 258	INVOICE DATE 10/31/24	INVOICE NO. P3CS817733
	LABOR RATE	LICENSE NO.	MILEAGE 16,501	COLOR	STOCK NO.
	YEAR / MAKE / MODE 14/PORSCH	E/911/2DR CAB	DELIVERY DATE	DELIVERY MILES	
EDMUNDS, WA 90020-2040	W P O C I	B 2 A 9 7 E S :	SELLING DEALER NO.	PRODUCTION DATE	
	F. T. E. NO.	F. T. E. NO. P. O. NO.		10/30/24	
RESIDENCE PHONE BUSINESS PHONE	COMMENTS				MO: 16502
, , , , , , , , , , , , , , , , , , ,					WARRANTIES AND OF LIABILITY
	RECEIPT			All parts and service tion with this transa IS. Dealership ex	es provided in connec- ction are provided AS pressly disclaims all express or implied,
RECEIPT DATE: 10/31/24 CUSTOMER NUMBER: 1759964					express or implied arranties of merchant

CARDHOLDER AUTHORIZATION

APPROVED TOTAL:\$1118.04 ORDER ID:457732900

CUSTOMER NAME:

All parts and services provided in connection with this transaction are provided AS IS. Dealership expressly disclaims all warranties, either express or implied, including implied warranties of merchantability or fitness for a particular purpose. Dealership is not responsible for any damage or loss that may occur to your vehicle or its contents during or after repair. You agree that by using our services you release Dealership from any liability for damages, injury, or losses. The only warranties that may apply are those provided by the manufacturer. Dealership does not assume or authorize any other person to assume for it any liability in connection with this transaction.

LIMITATION OF LIABILITY
DEALERSHIP WILL NOT BE LIABLE FOR
ANY DIRECT, INDIRECT, INCIDENTAL,
CONSEQUENTIAL, SPECIAL, OR PUNITIVE
DAMAGES ARISING FROM THIS TRANSACTION, INCLUDING DAMAGES FOR LOSS
OF USE OR LOST PROFIT, WHETHER
BASED IN CONTRACT OR TORT, INCLUDING NEGLIGENCE. IN NO EVENT WILL
DEALERSHIP'S TOTAL LIABILITY ON ALL
CLAIMS, IF ANY, EXCEED THE AMOUNT OF

By signing below, you authorize the Dealership to perform the services/repairs itemized in this invoice and that you received (or had the opportunity to inspect) any replaced parts if you made such a request. The vehicle is being returned to you in exchange for your payment of amounts owed.

DATE CUSTOMER SIGNATURE

THE REPAIR ORDER.

*SHOP SUPPLY COSTS: We have added a charge equal to 3.5% of the total cost of labor and parts, not to exceed \$35.00, to the Repair Order for shop supplies used in connection with this repair.

ALL PARTS ARE NEW UNLESS OTHERWISE INDICATED.

LMK. Sinkard
SWICKARD AUTO GROUP

PAGE 1 OF 1 CUSTOMER COPY

[END OF INVOICE] 09:10am

The Reynolds and Reynolds Company ERAINTINVE SF725417 Q (07/24)