



Mercedes-Benz

9131

Mercedes-Benz of Lynnwood

17800 HIGHWAY 99

LYNNWOOD, WA 98037

425-673-0505

e-mail: service@mercedesbenzoflynnwood.com



0101IM4CS220306

CUSTOMER NO. 26170		ADVISOR GARRETT GRAHAM	754	TAG NO. 866B	INVOICE DATE 07/14/23	INVOICE NO. M4CS220306	
[REDACTED]		LABOR RATE	LICENSE NO.	MILEAGE 80,254	COLOR STEEL GREY/	STOCK NO.	
[REDACTED]		YEAR / MAKE / MODEL 11/MERCEDES LIGHT TRUCK/ML350BTC			DELIVERY DATE 03/04/11	DELIVERY MILES	
[REDACTED]		VEHICLE I.D. NO. 4 J G B B 2 F B 0 B A 6 4 1 0 4 9			SELLING DEALER NO. 05102	PRODUCTION DATE 08/09/10	
[REDACTED]		F.T.E. NO.			P.O. NO.	R.O. DATE 07/07/23	
RESIDENCE PHONE 206-310-5830	BUSINESS PHONE 206-404-4088	COMMENTS E# 642820				MO: 80265	

JOB# 1 CHARGES

LABOR

J# 1 98MBZ2019030018 DRIVER'S AIRBAG UNITS: 0.30 TECH(S):880 **WARRANTY**
 PERFORM OPEN RECALL 2019030018, REPLACE THE DRIVER'S SIDE AIRBAG PER THE CAMPAIGN BULLETIN.
 SCAN ID:35C7AB
 AS DIRECTED IN CAMP 2019030018 REPLACED DRIVERS AIR BAG

PARTS

QTY	FP-NUMBER	DESCRIPTION	UNIT PRICE
1	000-860-52-02-059116	DRIVER S AIRBA	
			TOTAL - PARTS 0.00

JOB# 1 TOTALS

JOB# 1 JOURNAL PREFIX M4CS JOB# 1 TOTAL 0.00

JOB# 2 CHARGES

LABOR

J# 2 98MBZ2020050020 EMP W164 10-11 UNITS: 16.50 TECH(S):880 **WARRANTY**
 CLIENT STATES PERFORM OPEN EMISSION CAMPAIGN 2020050020, MY 2010-2011 ML W164 MODIFICATION TO EMISSION CONTROL SYSTEM PER CAMPAIGN BULLETIN.
 AS DIRECTED PERFORMED CAMP 2020050020 REPALCED ALL REQUIRED COMPONENTS PERFORMED ALL REQUIRED PROGRAMMING AND CODING AS NEEDED. ATTACHED THE AEM LABEL AND PERFORMED ROAD TEST FUNCT ION CHECKS ALL CHECKS GOOD. DURING ROAD TEST ESP LIGHT CAME BACK RESCANED FOR CODES FAULT IS NOT RELATED TO WORK PERFOR MED DIAG IS NEEDED
 PLEASE NOTE: AFTER EMP THE CHECK ENGINE LIGH RETURNED CHECK ENGINE LIGHT IS BEING TRIGGERED BY THE ABS/ESP FAULT DIAG IS NEEDED AND IS NOT COVERED UNDER THE EMP

PARTS

QTY	FP-NUMBER	DESCRIPTION	UNIT PRICE
1	642-905-10-00-85	TS NOX SENSOR	
-1	642-905-10-00-85	CORE RETURN	
1	164-490-23-00-05	TS CATALYTIC C	
1	164-490-17-00-80	PRIMARY CAT. C	
-1	164-490-17-00-80	CORE RETURN	
1	164-490-08-00-80	SCR CATALYTIC	
-1	164-490-08-00-80	CORE RETURN	
1	642-900-98-01	CONTROL UNIT,	
1	164-490-26-00-80	INJECTION NOZZ	
-1	164-490-26-00-80	CORE RETURN	
1	000-584-63-15	INFORMATION LA	
1	642-090-19-00	PARTS KIT, CH.	
1	642-090-21-00	PARTS KIT, CH.	
2	000000-001116	SCREW	
1	642-090-23-00	PARTS KIT, CH.	
1	000-990-43-37	HEXAGON NUT	
1	642-090-82-37-80	CLEAN AIR LINE	
-1	642-090-82-37-80	CORE RETURN	
1	642-010-74-15	PARTS KIT, VEN	
1	642-140-02-75	EXHAUST GAS CO	
1	020-997-47-45	O RING	

EXCELLENCE IS OUR GOAL

Thank you for this opportunity to serve you. It is our aim to perform all repairs requested on this repair order to your complete satisfaction. If our service was "EXCELLENT" tell your friends; if not, please tell us immediately. OUR GOAL IS THAT YOU WILL BE VERY SATISFIED WITH MERCEDES-BENZ of LYNNWOOD, AS A PLACE TO PURCHASE AND SERVICE A VEHICLE.

DISCLAIMER OF WARRANTIES

The only warranties applying to this part(s) are those which may be offered by the manufacturer. MERCEDES-BENZ of LYNNWOOD hereby expressly disclaims all warranties, either express or implied, including any implied warranties of merchantability or fitness for a particular purpose and neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of this part(s) and/or service. Buyer shall not be entitled to recover from MERCEDES-BENZ of LYNNWOOD any consequential damages, damages to property, damages for loss of use, loss of time, loss of profit or income, or any other incidental damages.

The information contained on the estimate, worksheet and/or repair order is incorporated herein by reference.

TERMS

NO RETURNS ON ELECTRICAL PARTS OR SPECIAL ORDER ITEMS. PARTS RETURNED SUBJECT TO 10% HANDLING CHARGE. NO RETURNS WITHOUT THIS INVOICE. NO REFUNDS AFTER 15 DAYS. SPECIAL ORDER PARTS MUST BE PAID FOR IN ADVANCE. PACKAGING MUST BE IN NEW OR LIKE NEW CONDITION.

A CHARGE HAS BEEN ADDED WHERE APPROPRIATE FOR THE DISPOSAL OF ENVIRONMENTAL WASTES SUCH AS ENGINE OIL, ANTIFREEZE, SOLVENTS, ATF, ETC.

Thank You

The Reynolds and Reynolds Company ERANTINVE CC648427 Q. (08/10)



Mercedes-Benz

Mercedes-Benz of Lynnwood

17800 HIGHWAY 99

LYNNWOOD, WA 98037

425-673-0505

e-mail: service@mercedesbenzoflynnwood.com



0101IM4CS220306

CUSTOMER NO. 26170		ADVISOR GARRETT GRAHAM	754	TAG NO. 866B	INVOICE DATE 07/14/23	INVOICE NO. M4CS220306	
[REDACTED]		LABOR RATE	LICENSE NO.	MILEAGE 80,254	COLOR STEEL GREY/	STOCK NO.	
[REDACTED]		YEAR / MAKE / MODEL 11/MERCEDES LIGHT TRUCK/ML350BTC			DELIVERY DATE 03/04/11	DELIVERY MILES	
[REDACTED]		VEHICLE I.D. NO. 4 J G B B 2 F B 0 B A 6 4 1 0 4 9			SELLING DEALER NO. 05102	PRODUCTION DATE 08/09/10	
[REDACTED]		F.T.E. NO.			P.O. NO.	R.O. DATE 07/07/23	
RESIDENCE PHONE 206-310-5830	BUSINESS PHONE 206-404-4088	COMMENTS E# 642820				MO: 80265	

PARTS	QTY	FP-NUMBER	DESCRIPTION	UNIT PRICE
	3	000000-001114	SCREW	WARRANTY
	1	642-142-05-80	GASKET	WARRANTY
	4	000000-001117	SCREW	WARRANTY
	2	140-995-01-05	CLAMP	WARRANTY
	1	642-140-24-08-64	EXHAUST PIPE	WARRANTY
	3	910143-006001	SCREW	WARRANTY
	1	642-090-24-00	PARTS KIT, TUR	WARRANTY
	1	642-070-15-00	PARTS KIT, FUE	WARRANTY
	1	000000-006288	CLAMP	WARRANTY
	1	642-140-19-60-64	EXCHANGE VALVE	WARRANTY
	-1	642-140-19-60-64	CORE RETURN	WARRANTY
	1	642-142-05-80	GASKET	WARRANTY
	1	642-141-05-80	GASKET	WARRANTY
TOTAL - PARTS				0.00

EXCELLENCE IS OUR GOAL
Thank you for this opportunity to serve you. It is our aim to perform all repairs requested on this repair order to your complete satisfaction. If our service was "EXCELLENT" tell your friends; if not, please tell us immediately. OUR GOAL IS THAT YOU WILL BE VERY SATISFIED WITH MERCEDES-BENZ of LYNNWOOD, AS A PLACE TO PURCHASE AND SERVICE A VEHICLE.

DISCLAIMER OF WARRANTIES
The only warranties applying to this part(s) are those which may be offered by the manufacturer. MERCEDES-BENZ of LYNNWOOD hereby expressly disclaims all warranties, either express or implied, including any implied warranties of merchantability or fitness for a particular purpose and neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of this part(s) and/or service. Buyer shall not be entitled to recover from MERCEDES-BENZ of LYNNWOOD any consequential damages, damages to property, damages for loss of use, loss of time, loss of profit or income, or any other incidental damages.

The information contained on the estimate, worksheet and/or repair order is incorporated herein by reference.

TERMS
NO RETURNS ON ELECTRICAL PARTS OR SPECIAL ORDER ITEMS. PARTS RETURNED SUBJECT TO 10% HANDLING CHARGE. NO RETURNS WITHOUT THIS INVOICE. NO REFUNDS AFTER 15 DAYS. SPECIAL ORDER PARTS MUST BE PAID FOR IN ADVANCE. PACKAGING MUST BE IN NEW OR LIKE NEW CONDITION.

A CHARGE HAS BEEN ADDED WHERE APPROPRIATE FOR THE DISPOSAL OF ENVIRONMENTAL WASTES SUCH AS ENGINE OIL, ANTIFREEZE, SOLVENTS, ATF, ETC.

Thank You

JOB# 2 TOTALS	JOB# 2 JOURNAL PREFIX M4CS	JOB# 2 TOTAL	0.00
JOB# 3 CHARGES			

LABOR
J# 3 98MBZSA-EMP EMP NOTES AND INFO UNITS: 0.00 TECH(S):592 INTERNAL
CONGRATULATIONS ON COMPLETING THE EMISSION MODIFICATION ON YOUR VEHICLE. THIS PROVIDES ADDITIONAL BENEFITS INCLUDING A BLUETEC WARRANTY EXTENSION AND POSSIBLE INCENTIVE PAYMENT FOR COMPLETION AND SUBMISSION OF DOCUMENTATION PRIOR TO 07/31/2023. VISIT [HTTPS://MBEMPAYMENT.COM](https://mbempayment.com) FOR CLAIM DETAILS. PLEASE NOTE DURING THE FINAL ROAD TEST AFTER EMP ABS AND ESP WARNING CAME ON AND THE ABS SYSTEM STARTED ACTING UP. RAN QUICK TEST AFTER ROAD TEST AND VERIFIED A FAULT IN THE RIGHT FRONT WHEEL SPEED SENSOR. THIS CODE WAS PRESENT ON THE INITIAL CHECK IN QUICK TEST AND IS IN NO WAY RELATED TO THE REPAIRS PERFORMED AT THIS TIME DURING THE PERFORMANCE OF THIS CAMPAIGN. ABS TRACTION CONTROL SYSTEM DIAGNOSIS IS REQUIRED

JOB# 3 TOTALS	JOB# 3 JOURNAL PREFIX M4CS	JOB# 3 TOTAL	0.00
JOB# 4 CHARGES			

LABOR
J# 4 98MBZZ2022050015 BRAKE BOOSTER W/O PE UNITS: 0.20 TECH(S):880 WARRANTY
CLIENT STATES PERFORM OPEN RECALL 2022050015 INSPECT BRAKE BOOSTER WITHOUT PEDAL REWORK PER RECALL DOCUMENT. SEE UPDATED CAMPAIGN DOCUMENT. PICTURES STILL REQUIRED, REFER TO DOCUMENT FOR EXAMPLES. PERFORM ADDITIONAL MEASURES AS NEEDED. PERFORMED BOOSTER SLEEVE INSPECTION FOUND NO SIGNS OF RUST ON THE SLEEVE APPLIED INSPECTION MARK AND RETURNED VEHICLE TO SERVICE AT THIS TIME NO FURTHER ACTION IS NEEDED

JOB# 4 TOTALS	JOB# 4 JOURNAL PREFIX M4CS	JOB# 4 TOTAL	0.00
---------------	----------------------------	--------------	------

The Reynolds and Reynolds Company ERANTINVE CCG49427 Q (08/10)



Mercedes-Benz

Mercedes-Benz of Lynnwood

17800 HIGHWAY 99

LYNNWOOD, WA 98037

425-673-0505

e-mail: service@mercedesbenzoflynnwood.com



0101IM4CS220306

CUSTOMER NO. 26170		ADVISOR GARRETT GRAHAM	754	TAG NO. 866B	INVOICE DATE 07/14/23	INVOICE NO. M4CS220306	
LABOR RATE		LICENSE NO.	MILEAGE 80,254		COLOR STEEL GREY/	STOCK NO.	
YEAR / MAKE / MODEL 11/MERCEDES LIGHT TRUCK/ML350BTC		DELIVERY DATE 03/04/11			DELIVERY MILES		
VEHICLE I.D. NO. 4 J G B B 2 F B 0 B A 6 4 1 0 4 9		SELLING DEALER NO. 05102			PRODUCTION DATE 08/09/10		
F. T. E. NO.		P. O. NO.		R. O. DATE 07/07/23			
RESIDENCE PHONE 206-310-5830	BUSINESS PHONE 206-404-4088	COMMENTS E# 642820				MO: 80265	

JOB# 5 CHARGES-----

LABOR-----
J# 5 02MBZCOUPON COUPON UNITS: 0.00 TECH(S):592 WARRANTY
 VEHICLE HAS OPEN EMP. \$1,500.00 COUPON OFFER TO PERFORM EMP.
 COUPON MUST BE USED DURING INSTALLATION OF THE EMP. IF THE
 VEHICLE DOES NOT QUALIFY FOR EMP THE COUPON CANNOT BE USED.
 COUPON RECEIVED ON 06/30/2023.
 APPLIED COUPON AS APPLICABLE.

SUBLET-----PO#-----VEND INV#-INV.DATE-DESCRIPTION-----
 71957 07/14/23 \$1500 MB DISCOUNT -1500.00
 71957 07/14/23 \$1500 FROM MB WARRANTY
 TOTAL - SUBLET -1500.00

JOB# 5 TOTALS-----
 SUBLET -1500.00
 JOB# 5 JOURNAL PREFIX M4CS JOB# 5 TOTAL -1500.00

JOB# 6 CHARGES-----

LABOR-----
J# 6 01MBZ01 CHECK FOR OIL LEAKS UNITS: 3.50 TECH(S):880 857.50
 IF OIL COOLER IS LEAKING, PLEASE REPAIR AT SAME TIME AS EMP
 REPAIR.
 DURING EMP RESEALED ENGINE OIL COOLER. FLUSHED AND REFILLED
 COOLING SYSTEM. PERFORMED OIL AND FILTER CHANGE. PEROFMRED
 ENGINE BAY CLEANING AN DDEGREASING AND RECHECKED FOR LEAKS
 NO LEAKS DETECTED RETURNED TO SERVICE
 ALSO DURING EMP PROICEDDURE REPLACED THE LEAKING VACUUM PUMP

PARTS-----QTY---FP-NUMBER-----DESCRIPTION-----UNIT PRICE-
 1 642-230-01-65-87 REMAN VACUUM P 555.50 555.50
 -1 642-230-01-65-87 CORE RETURN 29.00 -29.00
 1 642-141-01-80 GASKET 2.59 2.59
 2 028-997-45-48 SEAL RING 7.76 15.52
 1 Q-6-88-0187 ZEREX G 48 ANT 37.32 37.32
 1 642-180-00-09 TS FILTER INSE 28.35 28.35
 9 000-989-10-08-19BBDU MERCEDES BENZ 8.67 78.03
 1 007603-012102 RING,GENERAL,M 6.60 6.60
 TOTAL - PARTS 694.91

MISC-----CODE-----DESCRIPTION-----CONTROL NO-----
 GD LOYAL CUSTOMER SAVINGS -52.41
 TOTAL - MISC -52.41

JOB# 6 TOTALS-----
 LABOR 857.50
 PARTS 694.91
 MISC -52.41

JOB# 6 JOURNAL PREFIX M4CS JOB# 6 TOTAL 1500.00

EXCELLENCE IS OUR GOAL

Thank you for this opportunity to serve you. It is our aim to perform all repairs requested on this repair order to your complete satisfaction. If our service was "EXCELLENT" tell your friends; if not, please tell us immediately. OUR GOAL IS THAT YOU WILL BE VERY SATISFIED WITH MERCEDES-BENZ of LYNNWOOD, AS A PLACE TO PURCHASE AND SERVICE A VEHICLE.

DISCLAIMER OF WARRANTIES

The only warranties applying to this part(s) are those which may be offered by the manufacturer. MERCEDES-BENZ of LYNNWOOD hereby expressly disclaims all warranties, either express or implied, including any implied warranties of merchantability or fitness for a particular purpose and neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of this part(s) and/or service. Buyer shall not be entitled to recover from MERCEDES-BENZ of LYNNWOOD any consequential damages, damages to property, damages for loss of use, loss of time, loss of profit or income, or any other incidental damages.

The information contained on the estimate, worksheet and/or repair order is incorporated herein by reference.

TERMS

NO RETURNS ON ELECTRICAL PARTS OR SPECIAL ORDER ITEMS. PARTS RETURNED SUBJECT TO 10% HANDLING CHARGE. NO RETURNS WITHOUT THIS INVOICE. NO REFUNDS AFTER 15 DAYS. SPECIAL ORDER PARTS MUST BE PAID FOR IN ADVANCE. PACKAGING MUST BE IN NEW OR LIKE NEW CONDITION.

A CHARGE HAS BEEN ADDED WHERE APPROPRIATE FOR THE DISPOSAL OF ENVIRONMENTAL WASTES SUCH AS ENGINE OIL, ANTIFREEZE, SOLVENTS, ATF, ETC.

Thank You

The Reynolds and Reynolds Company BRAUNTIVE CC64842Z Q (08/10)



Mercedes-Benz

Mercedes-Benz of Lynnwood

17800 HIGHWAY 99
LYNNWOOD, WA 98037
425-673-0505

e-mail: service@mercedesbenzoflynnwood.com



0101IM4CS220306

CUSTOMER NO. 26170		ADVISOR GARRETT GRAHAM	754	TAG NO. 866B	INVOICE DATE 07/14/23	INVOICE NO. M4CS220306
[REDACTED]		LABOR RATE	LICENSE NO.	MILEAGE 80,254	COLOR STEEL GREY/	STOCK NO.
		YEAR / MAKE / MODEL 11/MERCEDES LIGHT TRUCK/ML350BTC		DELIVERY DATE 03/04/11	DELIVERY MILES	
[REDACTED]		VEHICLE I.D. NO. 4 J G B B 2 F B 0 B A 6 4 1 0 4 9		SELLING DEALER NO. 05102	PRODUCTION DATE 08/09/10	
		F.T.E. NO.	P.O. NO.	R.O. DATE 07/07/23		
RESIDENCE PHONE 206-310-5830	BUSINESS PHONE 206-404-4088	COMMENTS E# 642820			MO: 80265	

ESTIMATE-----
 CLIENT HEREBY ACKNOWLEDGES RECEIVING
 ORIGINAL ESTIMATE OF \$0.00 (+TAX)
 COMMENTS-----

TOTALS-----
 We at Mercedes-Benz of Lynnwood would like to thank-you for allowing us the opportunity to serve you. In approximately 10 days Mercedes-Benz may be sending you a survey experience, we ask that you please complete the survey, as it will help our efforts to provide you with a world-class Customer Service Experience. In the meantime if you have any questions or concerns, please contact your Service Advisor or the Service Manager at (425) 673-0505

TOTAL LABOR....	857.50
TOTAL PARTS....	694.91
TOTAL SUBLET...	-1500.00
TOTAL G.O.G....	0.00
TOTAL MISC CHG.	0.00
TOTAL MISC DISC	-52.41
TOTAL TAX.....	0.00
TOTAL INVOICE \$	0.00

EXCELLENCE IS OUR GOAL
 Thank you for this opportunity to serve you. It is our aim to perform all repairs requested on this repair order to your complete satisfaction. If our service was "EXCELLENT" tell your friends; if not, please tell us immediately. OUR GOAL IS THAT YOU WILL BE VERY SATISFIED WITH MERCEDES-BENZ of LYNNWOOD, AS A PLACE TO PURCHASE AND SERVICE A VEHICLE.

DISCLAIMER OF WARRANTIES
 The only warranties applying to this part(s) are those which may be offered by the manufacturer. MERCEDES-BENZ of LYNNWOOD hereby expressly disclaims all warranties, either express or implied, including any implied warranties of merchantability or fitness for a particular purpose and neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of this part(s) and/or service. Buyer shall not be entitled to recover from MERCEDES-BENZ of LYNNWOOD any consequential damages, damages to property, damages for loss of use, loss of time, loss of profit or income, or any other incidental damages.

The information contained on the estimate, worksheet and/or repair order is incorporated herein by reference.

TERMS
 NO RETURNS ON ELECTRICAL PARTS OR SPECIAL ORDER ITEMS. PARTS RETURNED SUBJECT TO 10% HANDLING CHARGE. NO RETURNS WITHOUT THIS INVOICE. NO REFUNDS AFTER 15 DAYS. SPECIAL ORDER PARTS MUST BE PAID FOR IN ADVANCE. PACKAGING MUST BE IN NEW OR LIKE NEW CONDITION.

A CHARGE HAS BEEN ADDED WHERE APPROPRIATE FOR THE DISPOSAL OF ENVIRONMENTAL WASTES SUCH AS ENGINE OIL, ANTIFREEZE, SOLVENTS, ATF, ETC.

Thank You

CLIENT SIGNATURE

The Reynolds and Reynolds Company ERA111NVE CC648427 Q (08/10)



Mercedes-Benz

9131

Mercedes-Benz of Lynnwood

17800 HIGHWAY 99

LYNNWOOD, WA 98037

425-673-0505

e-mail: service@mercedesbenzoflynnwood.com



0101IM4CS220422

CUSTOMER NO. 26170		ADVISOR GARRETT GRAHAM	754	TAG NO. 866B	INVOICE DATE 07/14/23	INVOICE NO. M4CS220422	
LABOR RATE		LICENSE NO.	MILEAGE 80,254		COLOR STEEL GREY/	STOCK NO.	
YEAR / MAKE / MODEL 11/MERCEDES LIGHT TRUCK/ML350BTC		DELIVERY DATE 03/04/11		DELIVERY MILES			
VEHICLE I.D. NO. 4 J G B B 2 F B 0 B A 6 4 1 0 4 9		SELLING DEALER NO. 05102		PRODUCTION DATE 08/09/10			
F.T.E. NO.		P.O. NO.		R.O. DATE 07/10/23			
RESIDENCE PHONE 206-310-5830	BUSINESS PHONE 206-404-4088	COMMENTS E# 642820				M0: 80265	

JOB# 1 CHARGES-----

LABOR-----

J# 1 07MBZ-DIAG DIAG. FUEL SYSTEM UNITS: TECH(S):880 WARRANTY

DURING EMP FOUND A FAUT IN THE ADBLUE SYSTEM. PLEASE REPAIR. FP-INTANK LEVEL SENSOR (SENSOR NO LONGER AVAILBLE ENTIRE EF TANK WAS REPLACED) CONNECTED BATTERY CHARGER AND SDS. PERFORMED QUICK TEST DTC 203D17 Fill level sensor 'AdBlue' has a short circuit to positive. performed guided testing and testing verified that the short is internal to the level sensor itself. the intank unit is no longer available. entire tank was replaced. drianed old tank and prepped for return shipping refilled the adblue and rechecked fault code is now stored and cleared properly performed actual value checks all checks good returned vehicle to service

PARTS-----	QTY---	FP-NUMBER-----	DESCRIPTION-----	UNIT PRICE-	WARRANTY
	1	164-470-76-01	ADDITIVE TANK		
	14	Q-1-47-0002	DIESEL EXHAUST		
				TOTAL - PARTS	0.00

JOB# 1 TOTALS-----

JOB# 1 JOURNAL PREFIX M4CS JOB# 1 TOTAL 0.00

ESTIMATE-----

CLIENT HEREBY ACKNOWLEDGES RECEIVING ORIGINAL ESTIMATE OF \$0.00 (+TAX)

COMMENTS-----

TOTALS-----

We at Mercedes-Benz of Lynnwood would like to thank-you for allowing us the opportunity to serve you. In approximately 10 days Mercedes-Benz may be sending you a survey experience, we ask that you please complete the survey, as it will help our efforts to provide you with a world-class Customer Service Experience. In the meantime if you have any questions or concerns, please contact your Service Advisor or the Service Manager at (425) 673-0505

TOTAL LABOR....	0.00
TOTAL PARTS....	0.00
TOTAL SUBLET...	0.00
TOTAL G.O.G....	0.00
TOTAL MISC CHG.	0.00
TOTAL MISC DISC	0.00
TOTAL TAX.....	0.00
TOTAL INVOICE \$	0.00

EXCELLENCE IS OUR GOAL

Thank you for this opportunity to serve you. It is our aim to perform all repairs requested on this repair order to your complete satisfaction. If our service was "EXCELLENT" tell your friends; if not, please tell us immediately. OUR GOAL IS THAT YOU WILL BE VERY SATISFIED WITH MERCEDES-BENZ of LYNNWOOD, AS A PLACE TO PURCHASE AND SERVICE A VEHICLE.

DISCLAIMER OF WARRANTIES

The only warranties applying to this part(s) are those which may be offered by the manufacturer. MERCEDES-BENZ of LYNNWOOD hereby expressly disclaims all warranties, either express or implied, including any implied warranties of merchantability or fitness for a particular purpose and neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of this part(s) and/or service. Buyer shall not be entitled to recover from MERCEDES-BENZ of LYNNWOOD any consequential damages, damages to property, damages for loss of use, loss of time, loss of profit or income, or any other incidental damages.

The information contained on the estimate, worksheet and/or repair order is incorporated herein by reference.

TERMS

NO RETURNS ON ELECTRICAL PARTS OR SPECIAL ORDER ITEMS. PARTS RETURNED SUBJECT TO 10% HANDLING CHARGE. NO RETURNS WITHOUT THIS INVOICE. NO REFUNDS AFTER 15 DAYS. SPECIAL ORDER PARTS MUST BE PAID FOR IN ADVANCE. PACKAGING MUST BE IN NEW OR LIKE NEW CONDITION.

A CHARGE HAS BEEN ADDED WHERE APPROPRIATE FOR THE DISPOSAL OF ENVIRONMENTAL WASTES SUCH AS ENGINE OIL, ANTIFREEZE, SOLVENTS, ATF, ETC.

Thank You

CLIENT SIGNATURE

The Reynolds and Reynolds Company ERANTINVE CC648427 Q (08/10)