

5094
- 5441 -

1995 Morooka MST 800

serial # 3468

Newer motor 4D34T3 older engine was 4D34T

Parts - 1-866-850-9898 Fax - 1-877-850-4747

Morooka
6199 SE Lake Front
Milwauki, Oregon 97222

Dominion Equip. Parts 800-365-7260
Parts 503-249-9898 Fax 503-249- 9898

Oil filter - Napa # 1675 Genuine parts # ME215002
Fuel filter - Napa # 3397 Genuine parts # MEO15254
Air Filter _ Napa # 2126 Duralife # P81-1800
Hyd. Filter Napa # 7119 Duramax P170089
Fan belts = Napa XL 7450

Date	Hours					
10/19/2006	1777.7	Repaired both back dump cyls. Meb # 21231				
10/19/2006	1777.7	Serviced, changed engine oil and filter, Fuel filter, air filter.				
10/24/2006		replaced oil sending unit				
1/5/2006		worked on wiring				
3/12/2007	18339	new fuel gauge				
8/12/2008	1969.2	oil and filter. Note- the existing gasket was left on, the next work day the gasket blew out then all the oil. We lost the engine.				
11/3/2008	1969.4	Installed different engine 4D34T3, had to take everthing off ours and put on this engine. Also installed new air filter, fuel filter and oil filter Mathew did all this work. # 517873 \$ 2,223.60 bought engine from System Seven Repair, Inc. # 392P 206-762-1318				
3/10/2009	1970.7	Intalled new elect. Fuel pump. Napa # P74016. Still starting hard. He Adj. the valves. He has no idea why it starting so hard, if we give it a quick shot of starting fluided why turning over. It starts rigjht up. He wants us to just run it, and see if it get any better.				
2/2/2010	2013.6	Installed new relays and tested. Hour meter is now working Parts from Dominion Equip. Parts 800-365-7260 # 0056252-IN				
3/2/2010	2013.6	Installed new Tach. And new oil pressure switch				
6/3/2010	2026.1	manual fuel pump bad, Unhooked pump and by-pass it. Mathew.				
8/4/2010	2026.2	broken wire				
7/26/2011		new electrical fuel pump Napa part # P74016. Mathew installed				
6/9/2012	2061	new throttle cable				
3/4/2013	2123.1	new kill switch installed				
10/26/2014	2126	2 new battery's				
1/15/2015	2133.7	2 new fan belts.				
2/28/2016	2223.5	Full service by Mathew, welding up box and fixed floor board, fixed leak in Hyd. Tank. Oil, fuel & air filters				
10/7/2016	2228	new kill switch installed				
4/16/2020	2404.3	Serviced, changed engine oil and filter, Fuel filter, air filter. Exhaust repair				
8/19/2020	2406	Bottom rollers shafts, bearings, seals and new top rollers.				
6/9/2021	2425	New fuel filter, new 24 volt fuel pump, belts, shut off cable. Installed track that came off				