



Porsche Seattle North
 18600 Hwy 99
 Lynnwood, WA 98037
 www.porscheseatlenorth.com

John K. Swickard

SWICKARD AUTO GROUP

| | | | | | |
|-------------------------------|--|-------------|------------------------------|---------------------------------|----------------------------------|
| CUSTOMER NO 1759964 | ADVISOR JOE K | 1365278 | TAG NO. 258 | INVOICE DATE 10/31/24 | INVOICE NO. P3CS817733 |
| | LABOR RATE | LICENSE NO. | MILEAGE 16,501 | COLOR / | STOCK NO. |
| | YEAR / MAKE / MODEL 14/PORSCHE/911/2DR CAB CARRERA S | | | DELIVERY DATE | DELIVERY MILES |
| | VEHICLE I.D. NO. W P 0 C B 2 A 9 7 E S 1 5 4 4 5 7 | | | SELLING DEALER NO. | PRODUCTION DATE |
| | F.T.E. NO. | P.O. NO. | R.O. DATE 10/30/24 | | |
| RESIDENCE PHONE | | | BUSINESS PHONE | | |
| COMMENTS | | | | | MO: 16502 |

JOB# 1 CHARGES-----
 LABOR-----
 J# 1 62PSZ-20 BATTERY TECH(S):1365350 0.00
 CLIENT STATES THEIR VEHICLE IS DEAD. STATES THE CAR SAT FOR ABOUT 3 YEARS. PLEASE CHECK AND ADVISE.
 Verified battery does not hold charge. replace battery.

JOB# 1 TOTALS-----
 JOB# 1 JOURNAL PREFIX P3CS JOB# 1 TOTAL 0.00

JOB# 2 CHARGES-----
 LABOR-----
 J# 2 05PSZ-90 DRIVEABILITY CAMPAIG TECH(S):1365350 WARRANTY
 AMCO
 Re-programming DME and transmission control units
 Performed and completed campaign. Performed scope 1

JOB# 2 TOTALS-----
 JOB# 2 JOURNAL PREFIX P3CS JOB# 2 TOTAL 0.00

JOB# 3 CHARGES-----
 LABOR-----
 J# 3 05PSZ-91 DRIVEABILITY CAMPAIG TECH(S):1365350 WARRANTY
 WLA4
 Retrofit heat shield
 Performed and completed campaign. Performed scope 1

| PARTS | QTY | FP-NUMBER | DESCRIPTION | UNIT PRICE | WARRANTY |
|-------|-----|----------------|---------------------|---------------|----------|
| | 1 | PKWLA4 | RETROFIT HEATSHEILD | | WARRANTY |
| | 1 | 000-043-304-75 | CROSS MEMBER | | WARRANTY |
| | 1 | 000-043-304-77 | POP RIVET | | WARRANTY |
| | | | | TOTAL - PARTS | 0.00 |

JOB# 3 TOTALS-----
 JOB# 3 JOURNAL PREFIX P3CS JOB# 3 TOTAL 0.00

JOB# 4 CHARGES-----
 LABOR-----
 J# 4 05PSZ-95 DRIVEABILITY RECALL TECH(S):1365350 INTERNAL
 WLC8
 Replacing tank leakage diagnostic module
 campaign not feasible at time. Do not have parts in stock.

| PARTS | QTY | FP-NUMBER | DESCRIPTION | UNIT PRICE | INTERNAL |
|-------------------------------------|-----|----------------|----------------|------------|----------|
| | 0 | 000-043-210-07 | AIR FILTER | | INTERNAL |
| PART ON SPECIAL ORDER | | | | | |
| ** QUANTITY 1 IS SPECIAL ORDERED ** | | | | | |
| | 0 | 000-043-211-10 | PRESSURE SWITC | | INTERNAL |
| PART ON SPECIAL ORDER | | | | | |

DISCLAIMER OF WARRANTIES AND LIMITATION OF LIABILITY

All parts and services provided in connection with this transaction are provided **AS IS**. Dealership expressly disclaims all warranties, either express or implied, including implied warranties of merchantability or fitness for a particular purpose. Dealership is not responsible for any damage or loss that may occur to your vehicle or its contents during or after repair. You agree that by using our services you release Dealership from any liability for damages, injury, or losses. The only warranties that may apply are those provided by the manufacturer. Dealership does not assume or authorize any other person to assume for it any liability in connection with this transaction.

LIMITATION OF LIABILITY

DEALERSHIP WILL NOT BE LIABLE FOR ANY DIRECT, INDIRECT, INCIDENTAL, CONSEQUENTIAL, SPECIAL, OR PUNITIVE DAMAGES ARISING FROM THIS TRANSACTION, INCLUDING DAMAGES FOR LOSS OF USE OR LOST PROFIT, WHETHER BASED IN CONTRACT OR TORT, INCLUDING NEGLIGENCE. IN NO EVENT WILL DEALERSHIP'S TOTAL LIABILITY ON ALL CLAIMS, IF ANY, EXCEED THE AMOUNT OF THE REPAIR ORDER.

By signing below, you authorize the Dealership to perform the services/repairs itemized in this invoice and that you received (or had the opportunity to inspect) any replaced parts if you made such a request. The vehicle is being returned to you in exchange for your payment of amounts owed.

DATE CUSTOMER SIGNATURE

*SHOP SUPPLY COSTS: We have added a charge equal to 3.5% of the total cost of labor and parts, not to exceed \$35.00, to the Repair Order for shop supplies used in connection with this repair.

ALL PARTS ARE NEW UNLESS OTHERWISE INDICATED.

John K. Swickard

SWICKARD AUTO GROUP



Porsche Seattle North
 18600 Hwy 99
 Lynnwood, WA 98037
 www.porscheseattlenorth.com

W.K. Swickard
 SWICKARD AUTO GROUP

| | | | | | |
|--------------------------------|--|-------------|--------------------------|---------------------------------|----------------------------------|
| CUSTOMER NO. 1759964 | ADVISOR JOE K | 1365278 | TAG NO. 258 | INVOICE DATE 10/31/24 | INVOICE NO. P3CS817733 |
| | LABOR RATE | LICENSE NO. | MILEAGE 16,501 | COLOR / | STOCK NO. |
| | YEAR / MAKE / MODEL 14/PORSCHE/911/2DR CAB CARRERA S | | | DELIVERY DATE | DELIVERY MILES |
| | VEHICLE I.D. NO. W P O C B 2 A 9 7 E S 1 5 4 4 5 7 | | | SELLING DEALER NO. | PRODUCTION DATE |
| | F.T.E. NO. | P.C. NO. | | R.O. DATE 10/30/24 | |
| BUSINESS PHONE | | | COMMENTS | | |
| | | | MO: 16502 | | |

| PARTS | QTY | FP-NUMBER | DESCRIPTION | UNIT PRICE |
|--|-----|---------------|--------------------------------------|---------------|
| ** QUANTITY 1 IS SPECIAL ORDERED ** | | | | |
| | | | | TOTAL - PARTS |
| | | | | 0.00 |
| JOB# 4 TOTALS | | | | |
| | | | | 0.00 |
| JOB# 4 JOURNAL PREFIX P3CS JOB# 4 TOTAL | | | | |
| JOB# 5 CHARGES | | | | |
| LABOR | | | | |
| J# 5 00PSZ-00 | | | MULTIPOINT INSPECT TECH(S):1365350 | INTERNAL |
| PERFORM MULTIPOINT VEHICLE SAFETY INSPECTION. INCLUDES VISUAL INSPECTION OF ENGINE, SUSPENSION, DRIVETRAIN, BRAKING SYSTEM, COOLING, AND SAFETY SYSTEMS AS ITEMIZED IN THE MPI REPORT CARD. | | | | |
| | | | | 0.00 |
| JOB# 5 TOTALS | | | | |
| | | | | 0.00 |
| JOB# 5 JOURNAL PREFIX P3CS JOB# 5 TOTAL | | | | |
| JOB# 6 CHARGES | | | | |
| LABOR | | | | |
| J# 6 00PSZ-01 | | | TIRE PRESSURE CHECK TECH(S):1365350 | INTERNAL |
| CHECK TIRE PRESSURES-ALL TIRES. complete | | | | |
| | | | | 0.00 |
| JOB# 6 TOTALS | | | | |
| | | | | 0.00 |
| JOB# 6 JOURNAL PREFIX P3CS JOB# 6 TOTAL | | | | |
| JOB# 7 CHARGES | | | | |
| LABOR | | | | |
| J# 7+62PSZZBATT1 | | | BATTERY CONCERN TECH(S):1365350 | 446.95 |
| Added Operation (33JK5278 @ 10/30/2024 15:12) CLIENT REQUESTS TO INSTALL NEW BATTERY. removed and replaced 12volt engine start battery. programmed battery to vehicle after installing new battery. works as designed. | | | | |
| | | | | 234.76 |
| PARTS | | | | |
| 1 | | 992-915-105-A | BATTERY | 234.76 |
| | | | | 234.76 |
| JOB# 7 TOTALS | | | | |
| | | | | 446.95 |
| | | | | 234.76 |
| JOB# 7 JOURNAL PREFIX P3CS JOB# 7 TOTAL | | | | |
| | | | | 681.71 |
| JOB# 8 CHARGES | | | | |
| LABOR | | | | |
| J# 8+05PSZ-01 | | | DRIVEABILITY CONCERN TECH(S):1365350 | 295.00 |
| Added Operation (33JK5278 @ 10/30/2024 16:53) CLIENT REQUESTS TO PERFORM STEERING ANGLE SENSOR RECALIBRATION. | | | | |

DISCLAIMER OF WARRANTIES AND LIMITATION OF LIABILITY

All parts and services provided in connection with this transaction are provided **AS IS**. Dealership expressly disclaims all warranties, either express or implied, including implied warranties of merchantability or fitness for a particular purpose. Dealership is not responsible for any damage or loss that may occur to your vehicle or its contents during or after repair. You agree that by using our services you release Dealership from any liability for damages, injury, or losses. The only warranties that may apply are those provided by the manufacturer. Dealership does not assume or authorize any other person to assume for it any liability in connection with this transaction.

LIMITATION OF LIABILITY

DEALERSHIP WILL NOT BE LIABLE FOR ANY DIRECT, INDIRECT, INCIDENTAL, CONSEQUENTIAL, SPECIAL, OR PUNITIVE DAMAGES ARISING FROM THIS TRANSACTION, INCLUDING DAMAGES FOR LOSS OF USE OR LOST PROFIT, WHETHER BASED IN CONTRACT OR TORT, INCLUDING NEGLIGENCE. IN NO EVENT WILL DEALERSHIP'S TOTAL LIABILITY ON ALL CLAIMS, IF ANY, EXCEED THE AMOUNT OF THE REPAIR ORDER.

By signing below, you authorize the Dealership to perform the services/repairs itemized in this invoice and that you received (or had the opportunity to inspect) any replaced parts if you made such a request. The vehicle is being returned to you in exchange for your payment of amounts owed.

DATE _____ CUSTOMER SIGNATURE _____

***SHOP SUPPLY COSTS:** We have added a charge equal to 3.5% of the total cost of labor and parts, not to exceed \$35.00, to the Repair Order for shop supplies used in connection with this repair.

ALL PARTS ARE NEW UNLESS OTHERWISE INDICATED.

W.K. Swickard
 SWICKARD AUTO GROUP



Porsche Seattle North
 18600 Hwy 99
 Lynnwood, WA 98037
 www.porscheseatlenorth.com

John K. Swickard

SWICKARD AUTO GROUP

| | | | | | | |
|-------------------------------|--|-------------|--------------------------|---------------------------------|----------------------------------|------------------|
| CUSTOMER NO 1759964 | ADVISOR JOE K | 1365278 | TAG NO. 258 | INVOICE DATE 10/31/24 | INVOICE NO. P3CS817733 | |
| [REDACTED] | LABOR RATE | LICENSE NO. | MILEAGE 16,501 | COLOR / | STOCK NO. | |
| | YEAR / MAKE / MODEL 14/PORSCHE/911/2DR CAB CARRERA S | | | DELIVERY DATE | DELIVERY MILES | |
| | VEHICLE I.D. NO. W P 0 C B 2 A 9 7 E S 1 5 4 4 5 7 | | | SELLING DEALER NO. | PRODUCTION DATE | |
| | F.T.E. NO. | | P.O. NO. | R.O. DATE 10/30/24 | | |
| RESIDENCE PHONE | BUSINESS PHONE | COMMENTS | | | | MO: 16502 |

after installing new battery fault code for steering angle sensor calibration was active. performed steering angle sensor calibration.

| | | |
|---|---|--------|
| JOB# 8 TOTALS----- | LABOR | 295.00 |
| | JOB# 8 JOURNAL PREFIX P3CS JOB# 8 TOTAL | 295.00 |
| MISC-----CODE-----DESCRIPTION-----CONTROL NO----- | | |
| JOB # A | F15 THANK YOU ! | 30.00 |
| JOB # A | F14 THANK YOU! | -30.00 |
| JOB # A | F05 PORSCHE SHOP SUPPLIES | 34.18 |
| | TOTAL - MISC | 34.18 |

| | | |
|---|---------------|-----------|
| COMMENTS----- | | |
| TOW IN 10/29 NO VIN NO QUOTES OR TIME -LOCATION VERIFIED LA | | |
| RECOMMENDED NOT DONE/ DECLINED SERVICES----- | | |
| 94PSZ00004Y 4 YEAR SVC | TECH: 1365350 | \$4808.84 |

| | | |
|-------------|-------------------------|----------------|
| TOTALS----- | | |
| | TOTAL LABOR.... | 741.95 |
| | TOTAL PARTS.... | 234.76 |
| | TOTAL SUBLET.... | 0.00 |
| | TOTAL G.O.G.... | 0.00 |
| | TOTAL MISC CHG. | 64.18 |
| | TOTAL MISC DISC | -30.00 |
| | TOTAL TAX..... | 107.15 |
| | TOTAL INVOICE \$ | 1118.04 |

CUSTOMER SIGNATURE

DISCLAIMER OF WARRANTIES AND LIMITATION OF LIABILITY

All parts and services provided in connection with this transaction are provided **AS IS**. Dealership expressly disclaims all warranties, either express or implied, including implied warranties of merchantability or fitness for a particular purpose. Dealership is not responsible for any damage or loss that may occur to your vehicle or its contents during or after repair. You agree that by using our services you release Dealership from any liability for damages, injury, or losses. The only warranties that may apply are those provided by the manufacturer. Dealership does not assume or authorize any other person to assume for it any liability in connection with this transaction.

LIMITATION OF LIABILITY
DEALERSHIP WILL NOT BE LIABLE FOR ANY DIRECT, INDIRECT, INCIDENTAL, CONSEQUENTIAL, SPECIAL, OR PUNITIVE DAMAGES ARISING FROM THIS TRANSACTION, INCLUDING DAMAGES FOR LOSS OF USE OR LOST PROFIT, WHETHER BASED IN CONTRACT OR TORT, INCLUDING NEGLIGENCE. IN NO EVENT WILL DEALERSHIP'S TOTAL LIABILITY ON ALL CLAIMS, IF ANY, EXCEED THE AMOUNT OF THE REPAIR ORDER.

By signing below, you authorize the Dealership to perform the services/repairs itemized in this invoice and that you received (or had the opportunity to inspect) any replaced parts if you made such a request. The vehicle is being returned to you in exchange for your payment of amounts owed.

DATE CUSTOMER SIGNATURE

*SHOP SUPPLY COSTS: We have added a charge equal to 3.5% of the total cost of labor and parts, not to exceed \$35.00, to the Repair Order for shop supplies used in connection with this repair.

ALL PARTS ARE NEW UNLESS OTHERWISE INDICATED.

John K. Swickard

SWICKARD AUTO GROUP

Porsche Seattle North Multipoint

Vehicle Year/Model: 14 PORSCHE 911

VIN: WP0CB2A97ES154457

Technician: MIKE MORALES

Printed: 10/31/2024 09:08:06

Odometer: 18001

RO: 817733

Tag: 258

Service Advisor: JOE K

| | | |
|------------------------|--------------------------------|------------------------------|
| INSPECTION RESULT - OK | WILL REQUIRE FURTHER ATTENTION | REQUIRES IMMEDIATE ATTENTION |
|------------------------|--------------------------------|------------------------------|

Green Yellow Red Serviced


| | |
|--|--------------------------|
| <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> Horn operation | <input type="checkbox"/> |
| <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> Headlights / tail lights / turn signals / brake lights | <input type="checkbox"/> |
| <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> Windshield wiper and washer operation | <input type="checkbox"/> |
| <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> Windshield glass | <input type="checkbox"/> |
| <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> Fuel tank cap gasket | <input type="checkbox"/> |
| <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> Dome light / amp light / dimmer combination meter | <input type="checkbox"/> |
| <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> Cabin air filter | <input type="checkbox"/> |
| <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> Parking brake operation | <input type="checkbox"/> |
| <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> Check installation of driver's floor mat | <input type="checkbox"/> |
| <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> Air filter | <input type="checkbox"/> |
| <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> Battery condition (cables / clamps / corrosion) | <input type="checkbox"/> |
| <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> Cooling system (leaks) | <input type="checkbox"/> |
| <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> Hoses (cracks / damage / leaks) | <input type="checkbox"/> |
| <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> Drive belts (cracks / damage / leaks) | <input type="checkbox"/> |
| <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> Radiator core / air condition condenser (if equipped) | <input type="checkbox"/> |
| <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> Windshield washer | <input type="checkbox"/> |
| <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> Coolant | <input type="checkbox"/> |
| <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> Power steering (if equipped) | <input type="checkbox"/> |
| <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> Brake reservoir | <input type="checkbox"/> |
| <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> Clutch reservoir (if equipped) | <input type="checkbox"/> |
| <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> Transmission / transaxle | <input type="checkbox"/> |
| <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> Differential (if equipped) | <input type="checkbox"/> |
| <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> Propeller / driveshaft (damage / leaks / U-joints) | <input type="checkbox"/> |
| <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> Drive/CV shaft (damage / leaks / boots) | <input type="checkbox"/> |
| <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> Axle hub and bearing (damage / leaks / noise) | <input type="checkbox"/> |
| <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> Steering linkage (damage / leaks / worn components) | <input type="checkbox"/> |
| <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> Suspension (damage / leaks / worn components) | <input type="checkbox"/> |
| <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> Fluid leaks (engine / transmission / differential) | <input type="checkbox"/> |
| <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> Exhaust system (damage / leaks / corrosion) | <input type="checkbox"/> |
| <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> Fuel lines & connections / fuel tank bands / fuel tank vapor | <input type="checkbox"/> |
| <input checked="" type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> Recommended maintenance | <input type="checkbox"/> |

Brake Lining Measurements: LF: 8 mm RF: 8 mm LR: 8 mm RR: 8 mm

Tire Tread Measurements: LF: 10/32" RF: 10/32" LR: 8/32" RR: 8/32"

Tire Pressure Measurements: LF: 36psi RF: 36psi LR: 44psi RR: 44psi


Front / Rear Brake Linings

| | | |
|---|---|---|
| LF | | RF |
| <input checked="" type="checkbox"/> Green |  | <input checked="" type="checkbox"/> Green |
| <input type="checkbox"/> Yellow | | <input type="checkbox"/> Yellow |
| <input type="checkbox"/> Red | | <input type="checkbox"/> Red |
| LR | | RR |
| <input checked="" type="checkbox"/> Green | | <input checked="" type="checkbox"/> Green |
| <input type="checkbox"/> Yellow | | <input type="checkbox"/> Yellow |
| <input type="checkbox"/> Red | | <input type="checkbox"/> Red |
| <input type="checkbox"/> Serviced | | |
| <input type="checkbox"/> Inspection Not Taken | | |
| 6MM AND HIGHER | | |
| 4MM TO 5MM | | |
| 3MM AND LOWER | | |

Check Tires / Tread Depth

| | | |
|---|---|---|
| LF | | RF |
| <input checked="" type="checkbox"/> Green |  | <input checked="" type="checkbox"/> Green |
| <input type="checkbox"/> Yellow | | <input type="checkbox"/> Yellow |
| <input type="checkbox"/> Red | | <input type="checkbox"/> Red |
| LR | | RR |
| <input checked="" type="checkbox"/> Green | | <input checked="" type="checkbox"/> Green |
| <input type="checkbox"/> Yellow | | <input type="checkbox"/> Yellow |
| <input type="checkbox"/> Red | | <input type="checkbox"/> Red |
| <input type="checkbox"/> Serviced | | |
| 6MM AND HIGHER | | |
| 4MM TO 5MM | | |
| 3MM AND LOWER | | |

Check Battery Performance

| | | |
|---|--|-----------------------------------|
|  | <input checked="" type="checkbox"/> Good | <input type="checkbox"/> Serviced |
| | <input type="checkbox"/> Fair | |
| | <input type="checkbox"/> Bad | |
| Actual Cold Cranking Amps | <input type="text"/> | |
| Factory Cold Cranking Amps | <input type="text"/> | |



Porsche Seattle North
 18600 Hwy 99
 Lynnwood, WA 98037
 www.porscheseatlenorth.com

JMK Swickard

SWICKARD AUTO GROUP

| | | | | | |
|--------------------------------|--|-------------|------------------------------|---------------------------------|----------------------------------|
| CUSTOMER NO. 1759964 | ADVISOR JOE K | 1365278 | TAG NO. 258 | INVOICE DATE 10/31/24 | INVOICE NO. P3CS817733 |
| | LABOR RATE | LICENSE NO. | MILEAGE 16,501 | COLOR / | STOCK NO. |
| | YEAR / MAKE / MODEL 14/PORSCHE/911/2DR CAB CARRERA S | | | DELIVERY DATE | DELIVERY MILES |
| | VEHICLE I.D. NO. W P 0 C B 2 A 9 7 E S 1 5 4 4 5 7 | | | SELLING DEALER NO. | PRODUCTION DATE |
| | F.T.E. NO. | P.O. NO. | R.O. DATE 10/30/24 | | |
| COMMENTS | | | MO: 16502 | | |

R E C E I P T

RECEIPT DATE: 10/31/24
 CUSTOMER NUMBER: 1759964

PAY TYPE:CREDIT CARD DATE/TIME:2024-10-31 09:10:08 CARD:Visa XXXXXXXXXXXX2815
 EM:ContactlessIcc AC:ARQC 38C9F723C70106 ATC:0412 AID:A000000031010 VISA CREDIT
 RC:00 / Approved APP:00931D TRN ID:0D0001 BILLING NAME:CARDHOLDER/VISA
 APPROVED TOTAL:\$1118.04 ORDER ID:457732900

CARDHOLDER AUTHORIZATION

**DISCLAIMER OF WARRANTIES AND
 LIMITATION OF LIABILITY**

All parts and services provided in connection with this transaction are provided **AS IS**. Dealership expressly disclaims all warranties, either express or implied, including implied warranties of merchantability or fitness for a particular purpose. Dealership is not responsible for any damage or loss that may occur to your vehicle or its contents during or after repair. You agree that by using our services you release Dealership from any liability for damages, injury, or losses. The only warranties that may apply are those provided by the manufacturer. Dealership does not assume or authorize any other person to assume for it any liability in connection with this transaction.

LIMITATION OF LIABILITY
DEALERSHIP WILL NOT BE LIABLE FOR ANY DIRECT, INDIRECT, INCIDENTAL, CONSEQUENTIAL, SPECIAL, OR PUNITIVE DAMAGES ARISING FROM THIS TRANSACTION, INCLUDING DAMAGES FOR LOSS OF USE OR LOST PROFIT, WHETHER BASED IN CONTRACT OR TORT, INCLUDING NEGLIGENCE. IN NO EVENT WILL DEALERSHIP'S TOTAL LIABILITY ON ALL CLAIMS, IF ANY, EXCEED THE AMOUNT OF THE REPAIR ORDER.

By signing below, you authorize the Dealership to perform the services/repairs itemized in this invoice and that you received (or had the opportunity to inspect) any replaced parts if you made such a request. The vehicle is being returned to you in exchange for your payment of amounts owed.

DATE CUSTOMER SIGNATURE

*SHOP SUPPLY COSTS: We have added a charge equal to 3.5% of the total cost of labor and parts, not to exceed \$35.00, to the Repair Order for shop supplies used in connection with this repair.

ALL PARTS ARE NEW UNLESS OTHERWISE INDICATED.

JMK Swickard

SWICKARD AUTO GROUP