

CUSTOMER #: 3023164

403738



Bowen Scarff in Kent



The Believable No-dicker Sticker™

CRANE TECHNOLOGY INC
831 S 176TH ST
BURIEN, WA 98148-1548

HOME:206-300-7120 CONT:206-248-8146
BUS: 206-248-8146 CELL:

PAGE 1

1157 Central Ave N, Kent, WA 98032
Parts-Service: 253-852-3340 Sales: 253-852-1480
www.bowenscarff.com

SERVICE ADVISOR: 609 MONICA FREED

COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN/ OUT	TAG	
WHITE	01	FORD F-450	1FDXF46F71EC91502	B08640Y	322089/322089	T8586	
DEL DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE
01JAN01 DD			17:00 16NOV18			CHG	16NOV18

R.O. OPENED	READY	OPTIONS:
09:01 09NOV18	12:19 16NOV18	W-COMP:W DLR:74B026 ENG:7.3_Liter_D-TURBO-DI

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
------	--------	------	------	-------	------	-----	-------

A REPLACE ENGINE PER REQUEST							
DS100 REPLACE ENGINE PER REQUEST							
				1396	CFF	3234.00	3234.00
				1	XC3Z*6007*CARM REMAN ENGINE ASY	9251.53	9251.53
				1	SHIPPING FEDEX SHIPPING	90.00	90.00
				1	F81Z*6038*CB INSULATOR ASY	237.93	237.93
				1	F81Z*6038*CA INSULATOR ASY - ENGINE SUPPORT	80.60	80.60
				2	PM*4*A PARTS/BRAKE CLEANER	6.95	13.90
				5	VC*5DIL* ANTI-FREEZE	15.03	75.15
				2	VC*8* ADDITIVE - COOLANT	7.53	15.06
PARTS:					9764.17	LABOR:	3234.00
OTHER:					0.00	TOTAL LINE A:	12998.17

322089 REMOVED THE ENGINE AND TRANSMISSION FROM THE VEHICLE, CLEANED COMPONENTS, FOUND THE FLEX PLATE RING GEAR TEETH DAMAGED AND THE STARTER PINION TEETH WORN, ALSO FOUND THE PTO DRIVE BELT COMING APART AND MISSING BELT RIBS, CHECKED PULLEYS, ALL PULLEYS MOVE SMOOTH AND ARE FREE OF DAMAGE, DOWN PIPE TO INTERMEDIATE PIPE STUDS BROKE OFF FROM THE INTERMEDIATE PIPE DUE TO CORROSION WHEN REMOVING THE DOWN PIPE, M- TIME TO DRILL OUT THE BROKEN STUDS FROM THE INTERMEDIATE PIPE FLANGE, REPLACED THE ENGINE WITH A COMPLETE REMANUFACTURED ENGINE REPLACING ALL COOLANT HOSES AND BELTS, INSTALLED A NEW FLEX PLATE AND STARTER MOTOR, FOUND THE ENGINE OIL DIPSTIC TUBE RUBBED THROUGH NEAR THE BOTTOM, REPLACED THE DIPSTICK, TUBE, FILLED WITH NEW ENGINE OIL, NEW COOLANT AND COOLANT ADDITIVE, TOPPED OFF POWER STEERING AND TRANSMISSION FLUID, RAN ENGINE FULL HOT, PERFORMED KOEO AND KOER SELF TESTS, PASS, TEST DROVE, ENGINE PERFORMED NORMALLY, INSPECTED FOR LEAKS, NONE AT THIS TIME, HAD AN ASSISTANT DRIVE, VEHICLE PERFORMED NORMALLY, CHECKED FOR LEAKS, NONE PRESENT

 B Perform a thorough inspection of diesel maintenance items, fluids, wipers, battery, tires, brakes, safety systems, and components.
 D99P Perform a thorough inspection of diesel maintenance items, fluids, wipers, battery, tires, brakes, safety systems, and components.

ON BEHALF OF SERVICING DEALER, I HEREBY CERTIFY THAT THE INFORMATION CONTAINED HEREON IS ACCURATE UNLESS OTHERWISE SHOWN. SERVICES DESCRIBED WERE PERFORMED AT NO CHARGE TO OWNER THERE WAS NO INDICATION FROM THE APPEARANCE OF THE VEHICLE OR OTHERWISE, THAT ANY PART REPAIRED OR REPLACED UNDER THIS CLAIM HAD BEEN CONNECTED IN ANY WAY WITH ANY ACCIDENT, NEGLIGENCE OR MISUSE. RECORDS SUPPORTING THIS CLAIM ARE AVAILABLE FOR (1) YEAR FROM THE DATE OF PAYMENT NOTIFICATION AT THE SERVICING DEALER FOR INSPECTION BY MANUFACTURER'S REPRESENTATIVE.	CROSS REFERENCE	PROGRAM	It is understood that this Company assumes no responsibility for Loss or Damage by Theft or Fire to vehicles placed with them for Storage, Sale or Repair, or Damage to vehicle when Called for and Delivered, or while Road Testing. *The below bill for labor and material is approved, and an express mechanic's lien is granted on said vehicle to secure the payment thereof, and in event of default, I agree to pay in addition thereto a reasonable attorney's fee; permission is granted to you to drive said vehicle on any street or road for the purpose of testing and inspecting same.* THE INFORMATION ON THE ESTIMATE, WORKSHEET AND/OR REPAIR ORDER IS INCORPORATED HEREIN BY REFERENCE.	DESCRIPTION	TOTALS
	COMMIT. CODE	P.A. CODE 08588-1		LABOR AMOUNT	
<i>Thank You!</i>				PARTS AMOUNT	
				GAS, OIL, LUBE	
				SUBLET AMOUNT	
				MISC. CHARGES	
				TOTAL CHARGES	
				LESS INSURANCE	
			SALES TAX		
			PLEASE PAY THIS AMOUNT		

X _____ (SIGNATURE)
 _____ (DATE)
 DEALER, GENERAL MANAGER OR AUTHORIZED PERSON

CUSTOMER #: 3023164

403738



Bowen Scarff in Kent



The Believable No-dicker Sticker™

CRANE TECHNOLOGY INC
831 S 176TH ST
BURIEN, WA 98148-1548
HOME:206-300-7120 CONT:206-248-8146
BUS: 206-248-8146 CELL:

INVOICE

PAGE 2

1157 Central Ave N, Kent, WA 98032

Parts-Service: 253-852-3340 Sales: 253-852-1480

www.bowenscarff.com

SERVICE ADVISOR: 609 MONICA FREED

Table with columns: COLOR, YEAR, MAKE/MODEL, VIN, LICENSE, MILEAGE IN/ OUT, TAG. Row 1: WHITE, 01, FORD F-450, 1FDXF46F71EC91502, B08640Y, 322089/322089, T8586

Table with columns: DEL DATE, PROD. DATE, WARR. EXP., PROMISED, PO NO., RATE, PAYMENT, INV. DATE. Row 1: 01JAN01 DD, 09NOV18, 12:19 16NOV18, 17:00 16NOV18, CHG, 16NOV18

Table with columns: LINE, OPCODE, TECH, TYPE, HOURS, LIST, NET, TOTAL. Includes items like GBK BRAKES, GTIRE TIRES, GBATT BATTERY.

PARTS: 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE B: 0.00
322089 PERFORMED INSPECTION, THE PTO BELT IS MISSING SOME RIBS, FLUID LEVELS AND CONDITIONS ARE GOOD, BRAKES HAVE GREATER THAN 5MM, TIRES HAVE 7-12/32" TREAD

C CUST STATES VEHICLE PULLS LEFT
CH100 CUST STATES VEHICLE PULLS LEFT

PARTS: 0.00 LABOR: 147.00 OTHER: 0.00 TOTAL LINE C: 147.00
322089 SET TIRE PRESSURES, TEST DROVE AND VERIFIED A PULL TO THE LEFT AND AN UN CENTERED STEERING WHEEL, INSPECTED THE FRONT END, NO WORN OUT COMPONENTS, CHECKED 4 WHEEL ALIGNMENT, ALL WITHIN SPEC WITH THE STEERING WHEEL OFF TO THE RIGHT, CENTERED THE STEERING WHEEL, CROSS ROTATED THE FRONT TIRES AND TEST DROVE, VEHICLE NOW PULLS TO THE RIGHT, VEHICLE PULL IS CAUSED BY THE RIGHT FRONT TIRE

D** ADDITIONAL PARTS LINE FOR ENGINE REPLACEMENT
RM00 ADDITIONAL PARTS LINE FOR ENGINE REPLACEMENT

Table with columns: Description, Amount, Net, Total. Lists parts like KM*4495* HOSE ASY, KH*260* HOSE - HEATER WATER, etc.

ON BEHALF OF SERVICING DEALER, I HEREBY CERTIFY THAT THE INFORMATION CONTAINED HEREON IS ACCURATE UNLESS OTHERWISE SHOWN. SERVICES DESCRIBED WERE PERFORMED AT NO CHARGE TO OWNER THERE WAS NO INDICATION FROM THE APPEARANCE OF THE VEHICLE OR OTHERWISE, THAT ANY PART REPAIRED OR REPLACED UNDER THIS CLAIM HAD BEEN CONNECTED IN ANY WAY WITH ANY ACCIDENT, NEGLIGENCE OR MISUSE. RECORDS SUPPORTING THIS CLAIM ARE AVAILABLE FOR (1) YEAR FROM THE DATE OF PAYMENT NOTIFICATION AT THE SERVICING DEALER FOR INSPECTION BY MANUFACTURER'S REPRESENTATIVE.

CROSS REFERENCE PROGRAM, COMMIT. CODE, P.A. CODE 08588-1. Includes handwritten 'Thank You!' note.

It is understood that this Company assumes no responsibility for Loss or Damage by Theft or Fire to vehicles placed with them for Storage, Sale or Repair, or Damage to vehicle when Called for and Delivered, or while Road Testing. THE INFORMATION ON THE ESTIMATE, WORKSHEET AND/OR REPAIR ORDER IS INCORPORATED HEREIN BY REFERENCE.

Table with columns: DESCRIPTION, TOTALS. Includes rows for LABOR AMOUNT, PARTS AMOUNT, GAS, OIL, LUBE, SUBLET AMOUNT, MISC. CHARGES, TOTAL CHARGES, LESS INSURANCE, SALES TAX, PLEASE PAY THIS AMOUNT.

CUSTOMER #: 3023164

403738



Bowen Scarff in Kent



The Believable No-dicker Sticker™

CRANE TECHNOLOGY INC
831 S 176TH ST
BURIEN, WA 98148-1548
HOME:206-300-7120 CONT:206-248-8146
BUS: 206-248-8146 CELL:

INVOICE

PAGE 3

1157 Central Ave N, Kent, WA 98032
Parts-Service: 253-852-3340 Sales: 253-852-1480
www.bowenscarff.com

SERVICE ADVISOR: 609 MONICA FREED

Table with columns: COLOR, YEAR, MAKE/MODEL, VIN, LICENSE, MILEAGE IN/OUT, TAG. Includes details for a white Ford F-450 with VIN 1FDXF46F71EC91502.

Table with columns: LINE, OPCODE, TECH, TYPE, HOURS, LIST, NET, TOTAL. Lists parts like NUT - HEX and GASKET.

Table for E** FLEX PLATE AND STARTER. Includes RM00 FLEX PLATE AND STARTER and parts like FLYWHEEL ASY and STARTER MOTOR ASY.

Table for F** SVC PART WARRANTY CROSS THREAD EXHAUST PIPE BOLT AND NUT. Includes RM00 SVC PART WARRANTY CROSS THREAD EXHAUST PIPE BOLT AND NUT and parts like NUT - HEX - FLANGED and BOLT.

Table for G** COOLANT GAUGE NOT WORKING AFTER ENGINE REPLACEMENT. Includes RM00 COOLANT GAUGE NOT WORKING AFTER ENGINE REPLACEMENT and parts like SENDER ASY - TEMPERATURE.

Service agreement form with sections for CROSS REFERENCE, PROGRAM, COMMIT. CODE, P.A. CODE, and a list of charges including LABOR AMOUNT, PARTS AMOUNT, GAS, OIL, LUBE, etc.

Thank You!

CUSTOMER #: 3023164

Lg Truck

403738



Bowen Scarff in Kent



The Believable No-dicker Sticker™

CRANE TECHNOLOGY INC
831 S 176TH ST
BURIEN, WA 98148-1548
HOME: 206-300-7120 CONT: 206-248-8146
BUS: 206-248-8146 CELL:

INVOICE

PAGE 4

1157 Central Ave N, Kent, WA 98032
Parts-Service: 253-852-3340 Sales: 253-852-1480
www.bowenscarff.com

SERVICE ADVISOR: 609 MONICA FREED

COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN/ OUT	TAG	
WHITE	01	FORD F-450	1FDXF46F71EC91502	B08640Y	322089/322089	T8586	
DEL DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE
01JAN01 DD			17:00 16NOV18			CHG	16NOV18
R.O. OPENED	READY	OPTIONS: W-COMP:W DLR:74B026 ENG:7.3_Liter_D-TURBO-DI					
09:01 09NOV18	12:19 16NOV18						

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
REPLACED THE SENDER, REFILLED THE COOLING SYSTEM WITH DRAINED COOLANT, CHECKED GAUGE OPERATION, GAUGE NOW READS NORMAL							

CUSTOMER PAY SHOP SUPPLIES FOR REPAIR ORDER							49.99

CUSTOMER COPY

ON BEHALF OF SERVICING DEALER, I HEREBY CERTIFY THAT THE INFORMATION CONTAINED HEREON IS ACCURATE UNLESS OTHERWISE SHOWN. SERVICES DESCRIBED WERE PERFORMED AT NO CHARGE TO OWNER THERE WAS NO INDICATION FROM THE APPEARANCE OF THE VEHICLE OR OTHERWISE, THAT ANY PART REPAIRED OR REPLACED UNDER THIS CLAIM HAD BEEN CONNECTED IN ANY WAY WITH ANY ACCIDENT, NEGLIGENCE OR MISUSE. RECORDS SUPPORTING THIS CLAIM ARE AVAILABLE FOR (1) YEAR FROM THE DATE OF PAYMENT NOTIFICATION AT THE SERVICING DEALER FOR INSPECTION BY MANUFACTURER'S REPRESENTATIVE.

CROSS REFERENCE	PROGRAM
COMMIT. CODE	P.A. CODE
	08588-1

It is understood that this Company assumes no responsibility for Loss or Damage by Theft or Fire to vehicles placed with them for Storage, Sale or Repair, or Damage to vehicle when Called for and Delivered, or while Road Testing. "The below bill for labor and material is approved, and an express mechanic's lien is granted on said vehicle to secure the payment thereof, and in event of default, I agree to pay in addition thereto a reasonable attorney's fee; permission is granted to you to drive said vehicle on any street or road for the purpose of testing and inspecting same. THE INFORMATION ON THE ESTIMATE, WORKSHEET AND/OR REPAIR ORDER IS INCORPORATED HEREIN BY REFERENCE.

Thank You!

X

(SIGNED) (DATE)
DEALER, GENERAL MANAGER OR AUTHORIZED PERSON

X
[Signature]

DESCRIPTION	TOTALS
LABOR AMOUNT	3381.00
PARTS AMOUNT	11141.63
GAS, OIL, LUBE	0.00
SUBLET AMOUNT	0.00
MISC. CHARGES	49.99
TOTAL CHARGES	14572.62
LESS INSURANCE	0.00
SALES TAX	1457.26
PLEASE PAY THIS AMOUNT	16029.88

CUSTOMER COPY