

PHN: 360-825-7731 • FAX: 360-825-1043

09/28/2021 1:56:04 PM

TOLL FREE: 1-800-539-7595 • WWW.FUGATEFORD.COM

#### **SERVICE DEPARTMENT HOURS:**

7:00 AM - 6:00 PM **MONDAY** 7:00 AM - 7:00 PM **TUES - FRIDAY** 8:00 AM - 4:30 PM **SATURDAY** 

#### SO # 457218

## SERVICE ORDER

**Customer No** 

145648

**CUSTOMER COPY** 

User

VINCE

Page

Attn: MIKE ANDROSKO 206 379 7054 JR HAYES CONSTRUCTION 22430 SE 231 ST

MAPLE VALLEY, WA 98038

Home Cell

Printed

(425) 392-5722 Bus

(206) 379-7054 **Today** (425) 392-5722

**Term CHARGE** 

Email mandrosko@jrhayes.com

Advisor Vince Swanson Shop S2 13

**Promised** Opened Cashiered 09/28/2021 5:00 PM 09/24/2021 8:27 AM

Tag B784 Location PO#

**FOOTHILLS** 

License No C02599N/P119

**Priority** 

Odometer In 68897

**Odometer Out** 68899

**InServ Date** 

**Extended Warranty** 

Stock No

Year Make 2018 **FORD** Vehicle ID No

Model F-150 **Selling Dealer**  Model No F1C

Color RACE RED

1FTMF1CP4JKE67362

**Engine Size** 2.7L V6 ECOBOOST Fleet # P119

**Delivery Date** 

Request 607RT

Description PERFORM REAR BRAKE SERVICE, REPLACE BRAKE PADS, CLEAN AND LUBE CALIPER

SLIDE PINS, MACHINE ROTORS, INSPECT CALIPERS, AND ROAD TEST FOR PROPER

Job 1 CSR **Status** 792 Original

**OPERATION** 

Labor Description

PERFORM REAR BRAKE SERVICE, REPLACE BRAKE PADS, CLEAN AND LUBE CALIPER SLIDE PINS,

Type **Amount** CF 225.00

MACHINE ROTORS, INSPECT CALIPERS, AND ROAD TEST FOR PROPER OPERATION

Part

607RT

Description PAD - BRAKE Shp

Rin Type 114 CRO Price Amount

80.50

Type

IF

IF

IF

IF

**BRF 1951** Technician

Correction

0013 -PERFORM REAR BRAKE SERVICE, REPLACE BRAKE PADS, CLEAN AND LUBE CALIPER SLIDE PINS, MACHINE ROTORS, INSPECT CALIPERS, AND

ROAD TEST FOR PROPER OPERATION. REAR PADS 10MM NOW.

Parts Total Labor Total Request Total

80.50 225.00 305.50

80.50

Request

Description PERFORM MULTI-POINT INSPECTION - FORD XPRESS, ROTATE TIRES WHILE OFF FOR

**CSR Status** 792 Original

99PX

DOING BRAKES

Job 2

Amount

Labor 99PX

**RBK** 

Description PERFORM MULTI-POINT INSPECTION - FORD XPRESS

**GBATT GREEN BATTERY STATUS GOOD GTIRE** 

**GREEN TIRES 7/32 OR GREATER** 

RED BRAKES REQUIRE IMMEDIATE ATTENTION LESS THAN 3M) REAR BRAKES DONE AT THIS VISIT

0.00

Technician Correction

0013 -

Preform inspection. Rotate tires.

Parts Total Labor Total Request Total

0.00 0.00

Request

Description

MULTIPOINT INSPECTION-CAR

Job

**CSR** Status

99PX

3

792 Approved

TERMS CASH: UNLESS ARRANGEMENTS MADE. LABOR RATE BASED ON PER FLAT RATE HOUR.

QUALITY CARE FOR QUALITY CARS.

We have made a commitment to quality customer service. We pledge to do our best to ensure your satisfaction with your vehicle from pre-delivery through warranty and retail service. If you should experience difficulty with your vehicle, please let us know. We'll correct it to the best of our ability.

Behind this pledge is the dedication and commitment of the professional team of people working in this dealership. Whether you're dealing with our sales, parts or service department, you'll be taken care of.

PARTS RETURN POLICY: No return on all electrical parts. Special order parts must be pre-paid and will be held for 45 days from receipt and then returned to the manufacturer, reordering fees may apply. Returns-Cores- Must have original invoice and be in factory package. Restock fee is 25%.

Signature:				
Signature:				



PHN: 360-825-7731 • FAX: 360-825-1043

TOLL FREE: 1-800-539-7595 • WWW.FUGATEFORD.COM

#### **SERVICE DEPARTMENT HOURS:**

7:00 AM - 6:00 PM MONDAY 7:00 AM - 7:00 PM TUES - FRIDAY 8:00 AM - 4:30 PM **SATURDAY** 

#### SO # 457218

## SERVICE ORDER

Printed

09/28/2021 1:56:04 PM

**Customer No** 145648 Attn: MIKE ANDROSKO 206 379 7054 JR HAYES CONSTRUCTION 22430 SE 231 ST MAPLE VALLEY, WA 98038

(425) 392-5722 Bus

Home Cell Email

(206) 379-7054 Today (425) 392-5722

mandrosko@jrhayes.com

**Term CHARGE** 

**CUSTOMER COPY** 

Odometer In

F-150

68897

User

VINCE

Page

Advisor Vince Swanson Promised 09/28/2021 5:00 PM Tag B784 Shop S2 09/24/2021 8:27 AM Opened Location **FOOTHILLS Priority** 13 Cashiered **PO#** 

**Odometer Out** 

License No C02599N/P119 Year Make

2018

68899 Model

**Selling Dealer** 

**Model No** F1C **Extended Warranty** 

InServ Date

Color RACE RED

Stock No

Vehicle ID No 1FTMF1CP4JKE67362

**FORD** 

**Engine Size** 2.7L V6 ECOBOOST Fleet # P119

**Delivery Date** 

Correction	Preform inspection,		Parts Total Labor Tota				0.00
			Request T				0.00
Request 626	Description REPLACE ENGINE AIR FILTER				Job 4	<b>CSR</b> 792	Status Approved
<b>Labor</b> 626	Description REPLACE ENGINE AIR FILTER					<b>Type</b> CF	Amount 8.11
Part FA 1883	<b>Description</b> ELEMENT ASY - AIR CLEANER	ě	Shp 1	Bin LB5	<b>Type</b> CRO	<b>Price</b> 20.99	Amount 20.99
Technician Correction	0013 - Replace engine air filter.		Parts Total Labor Total <b>Request T</b>	ľ			20.99 8.11 <b>29.10</b>
Request SUBLET	Description SUBLET FOOTHILLS AUTO GLASS TO INSTALL WINDSHIELD				<b>Job</b> 5	<b>CSR</b> 792	Status Approved
<b>Labor</b> SUBLET	<b>Description</b> SUBLET FOOTHILLS AUTO GLASS TO INSTALL WINDSHIELD					Type CF	Amount 0.00
Sublet 47482.1	<b>Description</b> 674/FOOTHILLS AUTO GLASS LLC/REPLACE WINDSHIELD			×	<b>Type</b> CSUB	<b>CSR</b> 792	Amount 308.00
Technician Correction	999 - DONE		Parts Total Labor Total Request To	otal			0.00 308.00 <b>308.00</b>

#### TERMS CASH: UNLESS ARRANGEMENTS MADE. LABOR RATE BASED ON PER FLAT RATE HOUR.

QUALITY CARE FOR QUALITY CARS.

We have made a commitment to quality customer service. We pledge to do our best to ensure your satisfaction with your vehicle from pre-delivery through warranty and retail service. If you should experience difficulty with your vehicle, please let us know. We'll correct it to the best of our ability. Behind this pledge is the dedication and commitment of the professional team of people working in this dealership. Whether you're dealing with our sales, parts or service department, you'll be taken care of.

PARTS RETURN POLICY: No return on all electrical parts. Special order parts must be pre-paid and will be held for 45 days from receipt and then returned to the manufacturer, reordering fees may apply. Returns-Cores- Must have original invoice and be in factory package. Restock fee is 25%. PRIVACY STATEMENT: Ask us if you would like information about our Privacy Policy, including our service providers and their data processing in the U.S., which may be accessible to U.S. law enforcement and

national security authorities. We provide this personal and transaction information to Ford Motor Company of Canada, Limited to enable Ford to administer your transaction, provide you with requested services, improve automotive related products and services by conducting customer surveys, and provide you with marketing material which may be of interest to you, as permitted by applicable laws. For the Ford Privacy Policy (www.ford.ca) including use of service providers and U.S. data storage or if you do not want to receive marketing or survey materials from Ford please call 1-800-565-FORD (3673).

Signature:			

# FUGATE FORD

PO BOX 217 • 526 ROOSEVELT AVE • ENUMCLAW, WA 98022 PHN: 360-825-7731 • FAX: 360-825-1043

TOLL FREE: 1-800-539-7595 • WWW.FUGATEFORD.COM

New window

7:00 AM - 6:00 PM MONDAY 7:00 AM - 7:00 PM **TUES - FRIDAY** 8:00 AM - 4:30 PM SATURDAY

SERVICE DEPARTMENT HOURS:



SO # 457218

SERVICE ORDER

**Customer No** 

**Printed** 

09/28/2021 1:56:05 PM

145648

Attn: MIKE ANDROSKO 206 379 7054 JR HAYES CONSTRUCTION

22430 SE 231 ST

MAPLE VALLEY, WA 98038

Home Cell

(425) 392-5722 Bus

(206) 379-7054 Today (425) 392-5722

Email mandrosko@jrhayes.com

**Term CHARGE** 

CUSTOMER COPY

Vince Swanson

User

VINCE

Page

Advisor Shop **Priority** 

**S2** 13

**Promised** Opened Cashiered 09/28/2021 5:00 PM 09/24/2021 8:27 AM

Tag Location

B784 **FOOTHILLS** 

PO#

**License No** C02599N/P119

68897

Odometer In

**Odometer Out** 

Model No

Stock No

Year Make 2018 **FORD** 

Model F-150

Selling Dealer

F1C **Extended Warranty** 

InServ Date

Color RACE RED **Delivery Date** 

Vehicle ID No 1FTMF1CP4JKE67362

**Engine Size** 2.7L V6 ECOBOOST

Fleet # P119

Labor **Parts** 

Supplies

101.49 13.38 308.00

Sublet/Tow SUB-TOTAL

655.98 57.73

233.11

**TOTAL INVOICE** 

713.71

02 6211 PII9 05P

TERMS CASH: UNLESS ARRANGEMENTS MADE. LABOR RATE BASED ON PER FLAT RATE HOUR.

QUALITY CARE FOR QUALITY CARS.

We have made a commitment to quality customer service. We pledge to do our best to ensure your satisfaction with your vehicle from pre-delivery through warranty and retail service. If you should experience difficulty with your vehicle, please let us know. We'll correct it to the best of our ability. Behind this pledge is the dedication and commitment of the professional team of people working in this dealership. Whether you're dealing with our sales, parts or service department, you'll be taken care of.

PARTS RETURN POLICY: No return on all electrical parts. Special order parts must be pre-paid and will be held for 45 days from receipt and then returned to the manufacturer, reordering fees may apply. Returns-Cores- Must have original invoice and be in factory package. Restock fee is 25%.

Signature:	
0.8	

			k n	
14:1				



145648

PHN: 360-825-7731 • FAX: 360-825-1043

TOLL FREE: 1-800-539-7595 • WWW.FUGATEFORD.COM

#### **SERVICE DEPARTMENT HOURS:**

7:00 AM - 6:00 PM MONDAY 7:00 AM - 7:00 PM TUES - FRIDAY 8:00 AM - 4:30 PM **SATURDAY** 

### SO # 453694

05/19/2021 11:45:11 AM **Printed** 

**Customer No** Attn: MIKE ANDROSKO 206 379 7054

JR HAYES CONSTRUCTION

22430 SE 231 ST

MAPLE VALLEY, WA 98038

Home

(425) 392-5722 Bus

Cell

(206) 379-7054 **Today** (425) 392-5722

Email

mandrosko@jrhayes.com

SERVICE ORDER CUSTOMER COPY

User

VINCE

Page

Advisor	Vince Swanson	Promised	05/19/2021 5:00 PM	Tag	B290
Shop	S2	Opened	05/19/2021 6:02 AM	Location	5.19
Priority	10	Cashiered		PO#	x p119

License No Odometer In **Odometer Out** InServ Date Stock No C02599N/P119 61875 61875 Year Make Model **Model No** Color 2018 **FORD** F-150 F1C RACE RED Vehicle ID No **Selling Dealer Extended Warranty Delivery Date** 1FTMF1CP4JKE67362 Float # D110

	Term CHARGE	Engine Size	2.7L V6 ECOBOOST		Fleet#			
Request PATS	Description CUT AND PROGRAM ADDITIONAL	PATS KEY				<b>Job</b> 1	<b>CSR</b> 792	Status Original
<b>Labor</b> PATS	Description CUT AND PROGRAM ADDITIONAL	PATS KEY					<b>Type</b> CF	Amount 59.95
Part	Description			Req	Bin	Туре	Price	Amount
164-R8130	3 BUTTON SIDE MILL KEY 8	& FOB		1	126	CRO	139.95	139.95
KEY	MANUFACTURE KEY CODE	RETRIEVAL		1		CRO	40.00	40.00
Technician	350 -			Parts Tota	ıl		×	179.95
Cause	CUT AND PROGRAM ADDITIONAL I	PATS KEY	27	Labor Tota	al			59.95
Correction	PROGRAMMED PATS KEY.		20	Request 1	Γotal			239.90
Request	Description					Job	CSR	Status
99PX	PERFORM MULTI-POINT INSPECTI	ON - FORD XP	RESS			2	792	Original
<b>Labor</b> 99PX	Description PERFORM MULTI-POINT INSPECTI	ON - FORD XP	RESS				Type IF	Amount
GBATT	GREEN BATTERY STATUS GOOD						CF	0.00
GTIRE	GREEN TIRES 7/32 OR GREATER						CF	0.00
GBK	GREEN BRAKES GOOD AT THIS TH	ME					CF	0.00
Technician	350 -			Parts Tota	l a			0.00
Cause	PERFORM MULTI-POINT INSPECTION	ON - FORD XP	RESS	Labor Tota	al			0.00
Correction	PERFORMED INSPECTION			Request 1	Γotal			0.00
Request	Description					Job	CSR	Status
626	REPLACE ENGINE AIR FILTER					3	792	Approved
<b>Labor</b> 626	<b>Description</b> REPLACE ENGINE AIR FILTER						<b>Type</b> CF	Amount 8.11

TERMS CASH: UNLESS ARRANGEMENTS MADE, LABOR RATE BASED ON PER FLAT RATE HOUR.

QUALITY CARE FOR QUALITY CARS.

We have made a commitment to quality customer service. We pledge to do our best to ensure your satisfaction with your vehicle from pre-delivery through warranty and retail service. If you should experience difficulty with your vehicle, please let us know. We'll correct it to the best of our ability.

Behind this pledge is the dedication and commitment of the professional team of people working in this dealership. Whether you're dealing with our sales, parts or service department, you'll be taken care of

PARTS RETURN POLICY: No return on all electrical parts. Special order parts must be pre-paid and will be held for 45 days from receipt and then returned to the manufacturer, reordering fees may apply. Returns-Cores- Must have original invoice and be in factory package. Restock fee is 25%.

Signature:			



PHN: 360-825-7731 • FAX: 360-825-1043

05/19/2021 11:45:11 AM

TOLL FREE: 1-800-539-7595 • WWW.FUGATEFORD.COM

#### **SERVICE DEPARTMENT HOURS:**

7:00 AM - 6:00 PM MONDAY 7:00 AM - 7:00 PM TUES - FRIDAY 8:00 AM - 4:30 PM **SATURDAY** 

#### SO # 453694

## **CUSTOMER COPY**

Vince Swanson

B290

**Customer No** 

Attn: MIKE ANDROSKO 206 379 7054

JR HAYES CONSTRUCTION

22430 SE 231 ST

MAPLE VALLEY, WA 98038

Home

**Printed** 

(425) 392-5722 Bus

Cell

Part

(206) 379-7054 Today (425) 392-5722

Email

mandrosko@jrhayes.com

**Term CHARGE** 

SERVICE ORDER

User

VINCE

Tag

Page

S2

10

Odometer In

**Odometer Out** InServ Date

05/19/2021 5:00 PM

05/19/2021 6:02 AM

Location 5.19 PO# x p119

License No C02599N/P119

Advisor

**Priority** 

Shop

Year

145648

61875 Model

61875

**Promised** 

Cashiered

Opened

**Model No** 

Stock No Color

**FORD** 2018 Vehicle ID No

F-150 **Selling Dealer** 

F<sub>1</sub>C **Extended Warranty**  RACE RED **Delivery Date** 

1FTMF1CP4JKE67362

Make

**Engine Size** 2.7L V6 ECOBOOST Fleet # P119

FA 1883

Description

**ELEMENT ASY - AIR CLEANER** 

Rea Bin LB5

Type **CRO** 

Job

**Price Amount** 20.99 20.99

Technician

350 -

REPLACE ENGINE AIR FILTER

Cause Correction

REPLACED AIR FILTER

Parts Total Labor Total 20.99 8.11

Request

Description

MULTIPOINT INSPECTION-CAR

**Request Total** 

29.10

792 Approved

Status

99PX

Parts Total Labor Total **Request Total**  0.00 0.00 0.00

**CSR** 



68.06 Labor Parts 200.94 10.76 Supplies 40.35 Discount 239.41 SUB-TOTAL 21.07 260.48 TOTAL INVOICE

TERMS CASH: UNLESS ARRANGEMENTS MADE. LABOR RATE BASED ON PER FLAT RATE HOUR.

QUALITY CARE FOR QUALITY CARS.

We have made a commitment to quality customer service. We pledge to do our best to ensure your satisfaction with your vehicle from pre-delivery through warranty and retall service. If you should experience difficulty with your vehicle, please let us know. We'll correct it to the best of our ability.

Behind this pledge is the dedication and commitment of the professional team of people working in this dealership. Whether you're dealing with our sales, parts or service department, you'll be taken care of

PARTS RETURN POLICY: No return on all electrical parts. Special order parts must be pre-paid and will be held for 45 days from receipt and then returned to the manufacturer, reordering fees may apply. Returns-Cores- Must have original invoice and be in factory package. Restock fee is 25%.

Signature:			
Signature.			



FUGATE FORD

PO BOX 217 • 526 ROOSEVELT AVE • ENUMCLAW, WA 98022

PHN: 360-825-7731 • FAX: 360-825-1043

TOLL FREE: 1-800-539-7595 • WWW.FUGATEFORD.COM

7:00 AM - 6:00 PM MONDAY 7:00 AM - 7:00 PM TUES - FRIDAY

SERVICE DEPARTMENT HOURS:

8:00 AM - 4:30 PM **SATURDAY** 

07/28/2020 05:09 PM

Page: 1

Color

RACE RED

Fleet #

Cashiered Date:

Tag B623 \* Service Invoice Customer Copy

SO #: 445023

**Customer No:** 

Attn: MIKE ANDROSKO 206 379 7054

Promised: 07/28/2020 5:00:00 PM

JR HAYES CONSTRUCTION 22430 SE 231 ST

MAPLE VALLEY, WA 98038

TAX: A17857321 TAX: 600-020-786

Home: (425) 392-5722 Bus:

Cell: (206) 379-7054 Today:(425) 392-5722

Advisor:	Doug Schripsema	invoice Date:	07/28/2020	term:	CHARGE
License N	Vo Odome	ter In Odometer O	ut Deli	very Date	Stock No

License No C02599N/P119 45358 45345 Model **Model No** Year Make **FORD** F-150 F<sub>1</sub>C 2018

Vehicle ID No Selling Dealer SO Date InServ Date Location

1FTMF1CP4JKE67362 07/28/2020 2.7L V6 ECOROOST Engine Size Fleet # P110

Email	l: mandro	sko@jrha	ayes.com	gine Size 2.7L V6 ECOB	0081		leet# P119		
Rec	quest/Concer	'n				Type	CSR		Amount
Orig	jinal								
1	WRKS			ORKS-OIL CHANGE, TIRE ILTI-POINT INSPECTION - U DL QTS	P				
) <del>**** = *****</del>	WRKS			ORKS-OIL CHANGE, TIRE RO INSPECTION - UP TO 6 QTS		CF	774		32.19
	99PX		PERFORM MULTI-F	OINT INSPECTION - FORD	XPRESS	CF	774		0.00
	GBATT		GREEN BATTERY	STATUS GOOD		CF	774		0.00
	GTIRE		<b>GREEN TIRES 7/32</b>	OR GREATER		CF	774		0.00
	GBK		GREEN BRAKES G	OOD AT THIS TIME		CF	774		0.00
Qty								Price	<u>Ext</u>
1	6.00	LB0	FL 2062	FILTER ASY - OIL		CRO		6.00	6.00
6	3.20	BULK	XO 5W30 BSP	OIL - ENGINE		CRO		3.20	19.20

Name

488

Request Total

57.39

Correction:

PERFORMED OIL CHANGE 5W30 6Q OLR PERFORMED TIRE ROTATION TIRES TORQUED TO 150FT LBS AND SET TO 36PSI FRONT AND REAR

PERFORMED MPI

Original

611M

TRANSMISSION SERVICE CAR, SUV AND F150 TRUCK - PERFORM TRANSMISSION FLUID SERVICE USING UP TO 15 QUARTS OF MERCON 5 TRANSMISSION FLUID, VERIFY PROPER FLUID LEVEL AND ROAD TEST TO VERIFY PROPER TRANSMISSION OPERATION. (ADDITIONAL COST FOR SYNTHETIC OIL OR

TERMS CASH: UNLESS ARRANGEMENTS MADE. LABOR RATE BASED ON PER FLAT RATE HOUR.

Cores- Must have original invoice and be in factory package. Restock fee is 25%.

QUALITY CARE FOR QUALITY CARS.

We have made a commitment to quality customer service. We pledge to do our best to ensure your satisfaction with your vehicle from pre-delivery through warranty and retail service. If you should experience difficulty with your vehicle, please let us know. We'll correct it to the best of our ability.

Behind this pledge is the dedication and commitment of the professional team of people working in this dealership. Whether you're dealing with our sales, parts or service department, you'll be taken care of PARTS RETURN POLICY: No return on all electrical parts. Special order parts must be pre-paid and will be held for 45 days from receipt and then returned to the manufacturer, reordering fees may apply. Returns-

PRIVACY STATEMENT: Ask us if you would like information about our Privacy Policy, including our service providers and their data processing in the U.S., which may be accessible to U.S. law enforcement and national security authorities. We provide this personal and transaction information to Ford Motor Company of Canada, Limited to enable Ford to administer your transaction, provide you with requested services, improve automotive related products and services by conducting customer surveys, and provide you with marketing material which may be of interest to you, as permitted by applicable laws. For the Ford Privacy Policy (www.ford.ca) including use of service providers and U.S. data storage or if you do not want to receive marketing or survey materials from Ford please call 1-800-565-FORD (3673).

Signature:



PHN: 360-825-7731 • FAX: 360-825-1043

TOLL FREE: 1-800-539-7595 • WWW.FUGATEFORD.COM

mandrosko@jrhayes.com

**SERVICE DEPARTMENT HOURS:** 

7:00 AM - 6:00 PM MONDAY 7:00 AM - 7:00 PM TUES - FRIDAY 8:00 AM - 4:30 PM SATURDAY

Promised: 07/28/2020 5:00:00 PM

Printed

07/28/2020 05:09 PM

Fleet #

Page:

225.24

PO Fleet #

Email:

Cashiered Date:

**Engine Size** 

Tag B623

\* Service Invoice Customer Copy \*

SO #:

P119

Request Total

445023

Customer No:	145648	Advisor	: Doug S	Schripsema Ir	voice Date: (	07/28/2020	Term: CH	ARGE
Attn: MIKE ANDROSKO 206 3	79 7054	License	e No	Odometer In	Odometer Out	Deliv	erv Date	Stock No
JR HAYES CONSTRUCTION 22430 SE 231 ST		C02599		45345	45358		,	
MAPLE VALLEY, WA 98038		Year	Make	Mode	I	Model No		Color
i i	0-020-786	2018	FORD	F-150		F1C		RACE RED
Home: (425) 392-5722 Bus:		Vehicle	ID No	Selling Deale	r	SO Date	InServ Date	Location
Cell: (206) 379-7054 Today:	(425) 392-5722	1FTMF1	CP4JKE67	362		07/28/2020		

2.7L V6 ECOBOOST

Request/Concern		Type	CSR		Amount
	ADDITIONAL OIL.)(WITH JUSTICE BROTHERS ADDITIVE)				
611M	TRANSMISSION SERVICE CAR, SUV AND F150 TRUCK - PERFORM TRANSMISSION FLUID SERVICE USING UP TO 15 QUARTS OF MERCON 5 TRANSMISSION FLUID, VERIFY PROPER FLUID LEVEL AND ROAD TEST TO VERIFY PROPER TRANSMISSION OPERATION. (ADDITIONAL COST FOR SYNTHETIC OIL OR ADDITIONAL OIL.)(WITH JUSTICE BROTHERS ADDITIVE)	CF	774		107.15
Othe				Price	Fxt

Qty						Price	EXT
15	5.56	B/RM	XT 10 QLVC	OIL - AUTOMATIC TRANSMISSION	CRO	5.56	83.40
1	34.69	LB2	59P	ATF SUPPLEMENT	CRO	34.69	34.69

Name

488

Cause:

TRANSMISSION SERVICE CAR, SUV AND F150 TRUCK - PERFORM TRANSMISSION FLUID SERVICE

USING UP TO 15 QUARTS OF MERCON 5
TRANSMISSION FLUID, VERIFY PROPER FLUID
LEVEL AND ROAD TEST TO VERIFY PROPER
TRANSMISSION OPERATION. (ADDITIONAL COST
FOR SYNTHETIC OIL OR ADDITIONAL OIL.)(WITH

JUSTICE BROTHERS ADDITIVE)

Correction:

PERFORMED TRANSMISSION SERVICE F150 TRUCK
- PERFORMED TRANSMISSION FLUID SERVICE
USING 15 QUARTS OF MERCON LV TRANSMISSION
FLUID AND JB TREATMENT, VERIFYED PROPER
FLUID LEVEL AND ROAD TESTED TO VERIFY

PROPER TRANSMISSION OPERATION.

Original

TERMS CASH: UNLESS ARRANGEMENTS MADE. LABOR RATE BASED ON PER FLAT RATE HOUR.

QUALITY CARE FOR QUALITY CARS.

We have made a commitment to quality customer service. We pledge to do our best to ensure your satisfaction with your vehicle from pre-delivery through warranty and retail service. If you should experience difficulty with your vehicle, please let us know. We'll correct it to the best of our ability.

Behind this pledge is the dedication and commitment of the professional team of people working in this dealership. Whether you're dealing with our sales, parts or service department, you'll be taken care of.

PARTS RETURN POLICY: No return on all electrical parts. Special order parts must be pre-paid and will be held for 45 days from receipt and then returned to the manufacturer, reordering fees may apply. Returns-Cores- Must have original invoice and be in factory package. Restock fee is 25%.

Signature:					



PHN: 360-825-7731 • FAX: 360-825-1043

TOLL FREE: 1-800-539-7595 • WWW.FUGATEFORD.COM

#### **SERVICE DEPARTMENT HOURS:**

7:00 AM - 6:00 PM MONDAY 7:00 AM - 7:00 PM TUES - FRIDAY 8:00 AM - 4:30 PM **SATURDAY** 

Promised: 07/28/2020 5:00:00 PM

Printed

07/28/2020 05:09 PM

PO

Cashiered Date:

Fleet # Tag

**B623** 

\* Service Invoice Customer Copy \*

SO #:

**Delivery Date** 

**Customer No:** Attn: MIKE ANDROSKO 206 379 7054 JR HAYES CONSTRUCTION

22430 SE 231 ST

MAPLE VALLEY, WA 98038

TAX: A17857321 TAX: 600-020-786

Home: (425) 392-5722 Bus:

(206) 379-7054 Today:(425) 392-5722

3

mandrosko@jrhayes.com

Advisor: Doug Schripsema

Invoice Date:

**Odometer Out** 

07/28/2020 Term:

CHARGE

**Price** 

445023

License No C02599N/P119 Year Make

45345 45358 Model

Model No

Color

**FORD** 2018 F-150 F1C Vehicle ID No Selling Dealer SO Date

2.7L V6 ECOBOOST

Odometer In

07/28/2020

RACE RED InServ Date Location

Stock No

Fleet # P119

**CSR** 

Request/Concern **FSA** 

**FSA** 

**FIELD SERVICE ACTION - 18S27 CARPET** 

**Engine Size** 

INSULATION

FIELD SERVICE ACTION - 18S27 CARPET INSULATION

1FTMF1CP4JKE67362

WE

Type

774

Ext

Amount

Qty 1

NPN

wheilding

Name

488

Cause:

FIELD SERVICE ACTION - 18S27 CARPET

INSULATION

Request Total

0.00

Correction:

PERFORMED FIELD SERVICE ACTION - 18S27

CARPET INSULATION

NO PROBLEMS FOUND FSA CAN BE CLOSED.

Approved

4 99PX **MULTIPOINT INSPECTION-CAR** 

Request Total

0.00

TERMS CASH: UNLESS ARRANGEMENTS MADE, LABOR RATE BASED ON PER FLAT RATE HOUR.

QUALITY CARE FOR QUALITY CARS.

We have made a commitment to quality customer service. We pledge to do our best to ensure your satisfaction with your vehicle from pre-delivery through warranty and retail service. If you should experience difficulty with your vehicle, please let us know. We'll correct it to the best of our ability. Behind this pledge is the dedication and commitment of the professional team of people working in this dealership. Whether you're dealing with our sales, parts or service department, you'll be taken care of.

PARTS RETURN POLICY: No return on all electrical parts. Special order parts must be pre-paid and will be held for 45 days from receipt and then returned to the manufacturer, reordering fees may apply. Returns-Cores- Must have original invoice and be in factory package. Restock fee is 25%.

٠



PHN: 360-825-7731 • FAX: 360-825-1043

TOLL FREE: 1-800-539-7595 • WWW.FUGATEFORD.COM

**SERVICE DEPARTMENT HOURS:** 

7:00 AM - 6:00 PM MONDAY 7:00 AM - 7:00 PM TUES - FRIDAY 8:00 AM - 4:30 PM **SATURDAY** 

Promised: 07/28/2020 5:00:00 PM

PO Fleet # Tag

Cashiered Date:

\* Service Invoice Customer Copy \*

SO #: 445023

07/28/2020 05:09 PM

**Customer No:** 

Attn: MIKE ANDROSKO 206 379 7054 JR HAYES CONSTRUCTION

22430 SE 231 ST

**B623** 

MAPLE VALLEY, WA 98038

TAX: A17857321 TAX: 600-020-786

Home: (425) 392-5722 Bus:

Cell: (206) 379-7054 Today:(425) 392-5722

mandrosko@jrhayes.com

Advisor:	Doug Schripsema	Invoice Date:	07/28/2020	Term:	CHARGE
License	No Odomoto	r In Odomotor O	ut Doli	vone Data	Stool

Stock No License No Odometer in Odometer Out Delivery Date C02599N/P119 45345 45358 Make Model **Model No** Color Year 2018 **FORD** F-150 F1C RACE RED Vehicle ID No Selling Dealer SO Date InServ Date Location

1FTMF1CP4JKE67362 07/28/2020 Engine Size 2.7L V6 ECOBOOST Fleet # P119

Request/Concern	Type CSR	Amount
	LABOR	\$139.34
	PARTS	\$143.29
	SUPPLIES	\$11.31
	SUB-TOTAL	\$293.94
	TAX	\$25.57
	TOTAL INVOICE	\$319.51

#### TERMS CASH: UNLESS ARRANGEMENTS MADE. LABOR RATE BASED ON PER FLAT RATE HOUR.

QUALITY CARE FOR QUALITY CARS.

We have made a commitment to quality customer service. We pledge to do our best to ensure your satisfaction with your vehicle from pre-delivery through warranty and retail service. If you should experience difficulty with your vehicle, please let us know. We'll correct it to the best of our ability. Behind this pledge is the dedication and commitment of the professional team of people working in this dealership. Whether you're dealing with our sales, parts or service department, you'll be taken care of.

PARTS RETURN POLICY: No return on all electrical parts. Special order parts must be pre-paid and will be held for 45 days from receipt and then returned to the manufacturer, reordering fees may apply. Returns-Cores- Must have original Invoice and be in factory package. Restock fee is 25%.

Cianabases		
Signature:		

Custome	er	
	JR HAYES CONSTRUCTION 22430 SE 231 ST MAPLE VALLEY, WA 98038 (206) 379-7054(c) mandrosko@jrhayes.com	
Inspection	on	
Service Order Advisor Tech	457218 Vince Swanson RICHARD PADGETT	
LIGHTS		
	FEXTERIOR LIGHT BULBS, AND TURN SIGNALS	ок 🗹 📙
	IELD WIPER OPER	ATION
	/IPER AND WASHER	OK 🗾 📕
Comments: WINDSHIELD W Comments:	/IPER BLADES	OK 🗸 📗
HORN		The Type States
HORN OPERAT	ION	OK 🗸 📘
WARNIN	G LIGHTS	
WARNING LIGH Comments:	ITS ON THE DASH	OK 🗾 📘
<b>BATTER</b>	Y	
BATTERY COLE	CRANKING AMPS	OK 🗸 📙
CORROSION	ES AND TERMINAL	OK 🗾 📙
Comments:		

real	2016			
Make	FORD			
Model	F-150			
Engine	2.7L V6 ECOBOOST			
Fuel				
Stock Number				
License/Stock	C02599N/P119			
Date In	09/24/2021 3:08:02 PM			
	09/24/2021 3.00.02 PM			
Completed Date	00007			
Odom	68897			
UNDER HO	DOD INSPECT			4.8
ENGINE OIL LEVEL	AND CONDITION	OK	1	
Comments:				
ENGINE COOLANT CONDITION	LEVEL AND	OK	1	
Comments:				
ENGINE COOLING RADIATOR VISUAL		OK	<b>/</b>	
Comments:				
TRANSMISSION FL CONDITION (IF EQ DIPSITCK)		OK	1	
Comments:				
POWER STEERING CONDITION	FLUID LEVEL AND	N/A		<b>V</b>
Comments:				
BRAKE FLUID LEVE	EL AND CONDITION	OK	1	
Comments:			in the same	
ENGINE AIR FILTE	R CONDITION	REQUIRES		1
The second secon	P 4 9			-
SERPENTINE BELT		OK	1	
Comments:	CONDITION	OK	- Daniel	1000
	"To say 2" - 10 mg	trainer in		
TIRES				
ALIGNMENT CHEC BALANCE NEEDED		OK	V	
Comments:				
LEFT FRONT TIRE PATTERN	TREAD DEPTH / WEAR	7/32 OR	1	
Comments:				
RIGHT FRONT TIRE WEAR PATTERN	TREAD DEPTH /	7/32 OR	V	
Comments:				
LEFT REAR TIRE TO PATTERN	READ DEPTH / WEAR	7/32 OR	1	
Comments:				
RIGHT REAR TIRE PATTERN	TREAD DEPTH / WEAR	7/32 OR	1	
Comments:				
TIRE PRESSURE S SPECS	ET TO FACTORY	SET TO SPECS	1	
Comments: 40psi all 4 tir	es			

1FTMF1CP4JKE67362

2018

Vehicle

VIN

Year

ADDITIONAL COMMENTS  Comments: 1, Drivers door check is worn out. 2. Cracks on RS of glass. (Pasenger side).  UNDER VEHICLE INSPECTION  SHOCKS / STRUTS  OK  STEERING LINKAGE COMPONENTS  OK  STEERING LINKAGE COMPONENTS  Comments:  SUSPENSION COMPONENTS AND BALL  JOINTS  Comments:  EXHAUST LEAKS AND EXHAUST SYSTEM  VISUAL INSPECTION  Constant Velocity (CV) BOOTS  VISUAL INSPECTION  Comments:  DRIVE SHAFT UNIVERSAL JOINTS AND  CONSTANT VELOCITY (CV) BOOTS  VISUAL INSPECTION  Comments:  TRANSMISSION / AWD FLUID LEAKS  Comments:  DRIVE AXLE LEAKS  Comments:  DRIVE AXLE LEAKS  COMMENTS  RESET OIL CHANGE REMINDERS  RESET OIL CHANGE REMINDER  NEW LUBE STICKER FOR WINDSHIELD  BRAKES  BRAKES NOT CHECKED ON THIS VISIT  Comments:  LEFT FRONT BRAKE PAD THICKNESS  6MM OR  STEERING SILICKER FOR WINDSHIELD  COMMENTS:  COMENTS:  COMMENTS:  C	ANY ADDITIONAL COMM	<b>JENTS</b>		
UNDER VEHICLE INSPECTION  SHOCKS / STRUTS  Comments:  STEERING LINKAGE COMPONENTS  OK  STEERING LINKAGE COMPONENTS  Comments:  SUSPENSION COMPONENTS AND BALL  JOINTS  Comments:  EXHAUST LEAKS AND EXHAUST SYSTEM  VISUAL INSPECTION  Comments:  DRIVE SHAFT UNIVERSAL JOINTS AND  CONSTANT VELOCITY (CV) BOOTS  VISUAL INSPECTION  Comments:  ENGINE OIL, COOLANT LEAKS, OR A/C  LEAKS  Comments:  TRANSMISSION / AWD FLUID LEAKS  Comments:  DRIVE AXLE LEAKS  Comments:  POWER STEERING FLUID LEAKS  Comments:  OIL CHANGE REMINDERS  RESET OIL CHANGE REMINDER  NEW LUBE STICKER FOR WINDSHIELD  RETRAIN TPMS AFTER TIRE ROTATE - IF  REQUIRED  BRAKES  BRAKES  BRAKES NOT CHECKED ON THIS VISIT  Comments:  LEFT FRONT BRAKE PAD THICKNESS  6MM OR	ADDITIONAL COMMENTS	REQUIRES		1
SHOCKS / STRUTS  Comments:  STEERING LINKAGE COMPONENTS  OK   STEERING LINKAGE COMPONENTS  Comments:  SUSPENSION COMPONENTS AND BALL JOINTS  Comments:  EXHAUST LEAKS AND EXHAUST SYSTEM VISUAL INSPECTION  Comments:  DRIVE SHAFT UNIVERSAL JOINTS AND CONSTANT VELOCITY (CV) BOOTS VISUAL INSPECTION  Comments:  ENGINE OIL, COOLANT LEAKS, OR A/C LEAKS  Comments:  TRANSMISSION / AWD FLUID LEAKS  Comments:  DRIVE AXLE LEAKS  Comments:  POWER STEERING FLUID LEAKS  Comments:  OIL CHANGE REMINDERS  RESET OIL CHANGE REMINDER  NEW LUBE STICKER FOR WINDSHIELD  RETRAIN TPMS AFTER TIRE ROTATE - IF REQUIRED  BRAKES  BRAKES NOT CHECKED ON THIS VISIT  Comments:  LEFT FRONT BRAKE PAD THICKNESS  GMM OR  Comments: 7mm.	Comments: 1. Drivers door check is worn out 2. Cracks	on RS of glass.(Pase	nger :	side).
Comments:  STEERING LINKAGE COMPONENTS  OK  STEERING LINKAGE COMPONENTS  Comments:  SUSPENSION COMPONENTS AND BALL JOINTS  Comments:  EXHAUST LEAKS AND EXHAUST SYSTEM VISUAL INSPECTION  Comments:  DRIVE SHAFT UNIVERSAL JOINTS AND CONSTANT VELOCITY (CV) BOOTS VISUAL INSPECTION  Comments:  ENGINE OIL, COOLANT LEAKS, OR A/C LEAKS  Comments:  TRANSMISSION / AWD FLUID LEAKS  Comments:  DRIVE AXLE LEAKS  Comments:  POWER STEERING FLUID LEAKS  Comments:  OIL CHANGE REMINDERS  RESET OIL CHANGE REMINDER  NEW LUBE STICKER FOR WINDSHIELD  RETRAIN TPMS AFTER TIRE ROTATE - IF REQUIRED  BRAKES  BRAKES NOT CHECKED ON THIS VISIT  Comments:  LEFT FRONT BRAKE PAD THICKNESS  Comments: 7mm.	UNDER VEHICLE INSPE	CTION		
STEERING LINKAGE COMPONENTS  Comments:  SUSPENSION COMPONENTS AND BALL JOINTS  Comments:  EXHAUST LEAKS AND EXHAUST SYSTEM VISUAL INSPECTION  Comments:  DRIVE SHAFT UNIVERSAL JOINTS AND CONSTANT VELOCITY (CV) BOOTS VISUAL INSPECTION  Comments:  ENGINE OIL, COOLANT LEAKS, OR A/C LEAKS  Comments:  TRANSMISSION / AWD FLUID LEAKS  Comments:  DRIVE AXLE LEAKS  Comments:  POWER STEERING FLUID LEAKS  OIL CHANGE REMINDERS  RESET OIL CHANGE REMINDER  NEW LUBE STICKER FOR WINDSHIELD  RETRAIN TPMS AFTER TIRE ROTATE - IF REQUIRED  BRAKES  BRAKES NOT CHECKED ON THIS VISIT  Comments:  LEFT FRONT BRAKE PAD THICKNESS  6MM OR	SHOCKS / STRUTS	ОК	1	
Comments:  SUSPENSION COMPONENTS AND BALL JOINTS  Comments:  EXHAUST LEAKS AND EXHAUST SYSTEM VISUAL INSPECTION  Comments:  DRIVE SHAFT UNIVERSAL JOINTS AND CONSTANT VELOCITY (CV) BOOTS VISUAL INSPECTION  Comments:  ENGINE OIL, COOLANT LEAKS, OR A/C LEAKS  Comments:  TRANSMISSION / AWD FLUID LEAKS OK  Comments:  DRIVE AXLE LEAKS OK  Comments:  POWER STEERING FLUID LEAKS  COMMENTS:  OIL CHANGE REMINDERS  RESET OIL CHANGE REMINDER  NEW LUBE STICKER FOR WINDSHIELD  RETRAIN TPMS AFTER TIRE ROTATE - IF REQUIRED  BRAKES  BRAKES NOT CHECKED ON THIS VISIT  Comments:  LEFT FRONT BRAKE PAD THICKNESS  6MM OR  COMMENTS: 7mm.	Comments:			
SUSPENSION COMPONENTS AND BALL JOINTS  Comments:  EXHAUST LEAKS AND EXHAUST SYSTEM VISUAL INSPECTION  Comments:  DRIVE SHAFT UNIVERSAL JOINTS AND CONSTANT VELOCITY (CV) BOOTS VISUAL INSPECTION  Comments:  ENGINE OIL, COOLANT LEAKS, OR A/C LEAKS  Comments:  TRANSMISSION / AWD FLUID LEAKS  Comments:  DRIVE AXLE LEAKS  Comments:  POWER STEERING FLUID LEAKS  Comments:  OIL CHANGE REMINDERS  RESET OIL CHANGE REMINDER  NEW LUBE STICKER FOR WINDSHIELD  RETRAIN TPMS AFTER TIRE ROTATE - IF REQUIRED  BRAKES  BRAKES  BRAKES NOT CHECKED ON THIS VISIT  Comments:  LEFT FRONT BRAKE PAD THICKNESS  6MM OR	STEERING LINKAGE COMPONENTS	OK	1	
JOINTS Comments:  EXHAUST LEAKS AND EXHAUST SYSTEM VISUAL INSPECTION Comments:  DRIVE SHAFT UNIVERSAL JOINTS AND CONSTANT VELOCITY (CV) BOOTS VISUAL INSPECTION Comments:  ENGINE OIL, COOLANT LEAKS, OR A/C LEAKS Comments:  TRANSMISSION / AWD FLUID LEAKS Comments:  DRIVE AXLE LEAKS Comments:  POWER STEERING FLUID LEAKS Comments:  OIL CHANGE REMINDERS RESET OIL CHANGE REMINDER NEW LUBE STICKER FOR WINDSHIELD RETRAIN TPMS AFTER TIRE ROTATE - IF REQUIRED  BRAKES BRAKES NOT CHECKED ON THIS VISIT Comments:  LEFT FRONT BRAKE PAD THICKNESS GMM OR COMMENTS: 7mm.	Comments:			
EXHAUST LEAKS AND EXHAUST SYSTEM VISUAL INSPECTION  Comments:  DRIVE SHAFT UNIVERSAL JOINTS AND CONSTANT VELOCITY (CV) BOOTS VISUAL INSPECTION  Comments:  ENGINE OIL, COOLANT LEAKS, OR A/C LEAKS  Comments:  TRANSMISSION / AWD FLUID LEAKS  Comments:  DRIVE AXLE LEAKS  Comments:  POWER STEERING FLUID LEAKS  Comments:  OIL CHANGE REMINDERS  RESET OIL CHANGE REMINDER  NEW LUBE STICKER FOR WINDSHIELD  RETRAIN TPMS AFTER TIRE ROTATE - IF REQUIRED  BRAKES  BRAKES NOT CHECKED ON THIS VISIT  Comments:  LEFT FRONT BRAKE PAD THICKNESS  GMM OR  COMMENTS: 7mm.		OK	V	
VISUAL INSPECTION  Comments:  DRIVE SHAFT UNIVERSAL JOINTS AND  CONSTANT VELOCITY (CV) BOOTS VISUAL INSPECTION  Comments:  ENGINE OIL, COOLANT LEAKS, OR A/C  LEAKS  Comments:  TRANSMISSION / AWD FLUID LEAKS  Comments:  DRIVE AXLE LEAKS  Comments:  POWER STEERING FLUID LEAKS  Comments:  OIL CHANGE REMINDERS  RESET OIL CHANGE REMINDER  NEW LUBE STICKER FOR WINDSHIELD  RETRAIN TPMS AFTER TIRE ROTATE - IF  REQUIRED  BRAKES  BRAKES NOT CHECKED ON THIS VISIT  Comments:  LEFT FRONT BRAKE PAD THICKNESS  6MM OR	Comments:			
DRIVE SHAFT UNIVERSAL JOINTS AND CONSTANT VELOCITY (CV) BOOTS VISUAL INSPECTION Comments:  ENGINE OIL, COOLANT LEAKS, OR A/C LEAKS Comments:  TRANSMISSION / AWD FLUID LEAKS Comments:  DRIVE AXLE LEAKS OK Comments:  POWER STEERING FLUID LEAKS Comments:  OIL CHANGE REMINDERS RESET OIL CHANGE REMINDER NEW LUBE STICKER FOR WINDSHIELD RETRAIN TPMS AFTER TIRE ROTATE - IF REQUIRED  BRAKES BRAKES NOT CHECKED ON THIS VISIT Comments:  LEFT FRONT BRAKE PAD THICKNESS GMM OR Comments: 7mm.		ОК	<b>V</b>	
CONSTANT VELOCITY (CV) BOOTS VISUAL INSPECTION  Comments:  ENGINE OIL, COOLANT LEAKS, OR A/C LEAKS  Comments:  TRANSMISSION / AWD FLUID LEAKS  Comments:  DRIVE AXLE LEAKS  Comments:  POWER STEERING FLUID LEAKS  Comments:  OIL CHANGE REMINDERS  RESET OIL CHANGE REMINDER  NEW LUBE STICKER FOR WINDSHIELD  RETRAIN TPMS AFTER TIRE ROTATE - IF REQUIRED  BRAKES  BRAKES NOT CHECKED ON THIS VISIT  Comments:  LEFT FRONT BRAKE PAD THICKNESS  6MM OR	Comments:			
ENGINE OIL, COOLANT LEAKS, OR A/C LEAKS Comments: TRANSMISSION / AWD FLUID LEAKS Comments: DRIVE AXLE LEAKS Comments: POWER STEERING FLUID LEAKS Comments:  OIL CHANGE REMINDERS RESET OIL CHANGE REMINDER NEW LUBE STICKER FOR WINDSHIELD YES RETRAIN TPMS AFTER TIRE ROTATE - IF REQUIRED  BRAKES BRAKES NOT CHECKED ON THIS VISIT Comments: LEFT FRONT BRAKE PAD THICKNESS COMMENTS: 7mm.	CONSTANT VELOCITY (CV) BOOTS	OK	<b>V</b>	
LEAKS Comments:  TRANSMISSION / AWD FLUID LEAKS Comments:  DRIVE AXLE LEAKS Comments:  POWER STEERING FLUID LEAKS Comments:  OIL CHANGE REMINDERS RESET OIL CHANGE REMINDER NEW LUBE STICKER FOR WINDSHIELD RETRAIN TPMS AFTER TIRE ROTATE - IF REQUIRED  BRAKES BRAKES NOT CHECKED ON THIS VISIT Comments:  LEFT FRONT BRAKE PAD THICKNESS COMMENTS: 7mm.				
TRANSMISSION / AWD FLUID LEAKS  Comments:  DRIVE AXLE LEAKS  Comments:  POWER STEERING FLUID LEAKS  Comments:  OIL CHANGE REMINDERS  RESET OIL CHANGE REMINDER  NEW LUBE STICKER FOR WINDSHIELD  RETRAIN TPMS AFTER TIRE ROTATE - IF  REQUIRED  BRAKES  BRAKES  BRAKES NOT CHECKED ON THIS VISIT  Comments:  LEFT FRONT BRAKE PAD THICKNESS  Comments: 7mm.		OK	/	
Comments:  DRIVE AXLE LEAKS  Comments:  POWER STEERING FLUID LEAKS  Comments:  OIL CHANGE REMINDERS  RESET OIL CHANGE REMINDER  NEW LUBE STICKER FOR WINDSHIELD  RETRAIN TPMS AFTER TIRE ROTATE - IF  REQUIRED  BRAKES  BRAKES NOT CHECKED ON THIS VISIT  Comments:  LEFT FRONT BRAKE PAD THICKNESS  Comments: 7mm.				
DRIVE AXLE LEAKS  Comments:  POWER STEERING FLUID LEAKS  Comments:  OIL CHANGE REMINDERS  RESET OIL CHANGE REMINDER  NEW LUBE STICKER FOR WINDSHIELD  RETRAIN TPMS AFTER TIRE ROTATE - IF  REQUIRED  BRAKES  BRAKES NOT CHECKED ON THIS VISIT  Comments:  LEFT FRONT BRAKE PAD THICKNESS  Comments: 7mm.	TRANSMISSION / AWD FLUID LEAKS	OK	/	
POWER STEERING FLUID LEAKS  Comments:  OIL CHANGE REMINDERS  RESET OIL CHANGE REMINDER  NEW LUBE STICKER FOR WINDSHIELD  RETRAIN TPMS AFTER TIRE ROTATE - IF REQUIRED  BRAKES  BRAKES  BRAKES NOT CHECKED ON THIS VISIT  Comments:  LEFT FRONT BRAKE PAD THICKNESS  Comments: 7mm.		OK	1	
Comments:  OIL CHANGE REMINDERS  RESET OIL CHANGE REMINDER  NEW LUBE STICKER FOR WINDSHIELD  RETRAIN TPMS AFTER TIRE ROTATE - IF REQUIRED  BRAKES  BRAKES  BRAKES NOT CHECKED ON THIS VISIT  Comments:  LEFT FRONT BRAKE PAD THICKNESS  Comments: 7mm.	Comments:			
OIL CHANGE REMINDERS  RESET OIL CHANGE REMINDER  NEW LUBE STICKER FOR WINDSHIELD  RETRAIN TPMS AFTER TIRE ROTATE - IF REQUIRED  BRAKES  BRAKES  BRAKES NOT CHECKED ON THIS VISIT  Comments:  LEFT FRONT BRAKE PAD THICKNESS  Comments: 7mm.	POWER STEERING FLUID LEAKS	N/A		<b>V</b>
RESET OIL CHANGE REMINDER  NEW LUBE STICKER FOR WINDSHIELD  RETRAIN TPMS AFTER TIRE ROTATE - IF REQUIRED  BRAKES  BRAKES  BRAKES NOT CHECKED ON THIS VISIT  Comments:  LEFT FRONT BRAKE PAD THICKNESS  Comments: 7mm.	Comments:			
NEW LUBE STICKER FOR WINDSHIELD  RETRAIN TPMS AFTER TIRE ROTATE - IF REQUIRED  BRAKES  BRAKES NOT CHECKED ON THIS VISIT  Comments:  LEFT FRONT BRAKE PAD THICKNESS  Comments: 7mm.	OIL CHANGE REMINDER	RS		
RETRAIN TPMS AFTER TIRE ROTATE - IF REQUIRED  BRAKES  BRAKES NOT CHECKED ON THIS VISIT  Comments:  LEFT FRONT BRAKE PAD THICKNESS  Comments: 7mm.			1	
REQUIRED  BRAKES  BRAKES NOT CHECKED ON THIS VISIT  Comments:  LEFT FRONT BRAKE PAD THICKNESS  Comments: 7mm.		YES	/	
BRAKES NOT CHECKED ON THIS VISIT  Comments:  LEFT FRONT BRAKE PAD THICKNESS  Comments: 7mm.				
Comments:  LEFT FRONT BRAKE PAD THICKNESS 6MM OR Comments: 7mm.	BRAKES		Y)	
LEFT FRONT BRAKE PAD THICKNESS 6MM OR Comments: 7mm.	BRAKES NOT CHECKED ON THIS VISIT			
Comments: 7mm.	Comments:			
	LEFT FRONT BRAKE PAD THICKNESS	6MM OR	/	
DICUT EDON'T DRAVE DAD TUICVNIECE CMM OR WILLIAM			(10)	
	RIGHT FRONT BRAKE PAD THICKNESS	6MM OR	/	
Comments: 7mm.				line I
LEFT REAR BRAKE PAD THICKNESS 3MM OR LESS		3MM OR LESS		1
Comments: 3mm.  RIGHT REAR BRAKE PAD THICKNESS 3MM OR LESS	·	2MM OD LECC		
Comments: 3MM		SIVIIVI ON LESS		Me

Dono



J.r. Hayes And Sons 22430 Se 231st P119 Maple Valley, WA 98038 425-392-5722

O2 6211 P119 120

Ab-

LICENSE	YEAR	MAK	(E	MODEL		ENGINE	MILEAGE	DATE	TIME
WA-C02599N	2018	Ford Truck		Pickup	E-p 6-c 2.	7I (164) Turbo	40030	5/12/2020	04:08 PM
				510 5			050/4050	OCHADI ETED	
			IANCE SCHE		ACE DUE	Full Service	SERVICES	COMPLETED	45 OF
RECOMME Cooling System	NDED SE	TVICE	DATE DU	every 10	AGE DUE	1.0 - M9015 (			45.95
Engine Oil*			6 months	every 50	000	Premium -Oil 5.0 - GTX530			8.00
Front Differential Rear Differential			See Recs. See Recs.	\$ee Red		Premium -Oil			2.55
Transfer Case				every 60		Extra 1.00 -0 Environment Fe	GTX530 @ 4.95 ee (T)		4.95 2.65
							. ,		
		CHECH	CUST						
CHECK	LIST ITEM			STATUS	University (4)				
					M.	V.			
						( , (	. Ke		
							Λ		
				0	2200		/4		
			6					,	
					U		PII	1	
						2			
					:si				
						SUBTOTAL			64.10
MANAGER:T			ECH: Marlin			TAX (PST)			5.52
COURTES Samuel		LOWER TE	ECH: Marlin	T/V	: 8	TOTAL			69.62
							(Fleet Charge,	6000)	69.62
					SINCHISTON PROF	AMOUNT TENDERED CHANGE	(, look offargo,	,	.00
							***NEXT SCHE	DULED VISIT***	
	parts and wo	orkmanship.	If you do have a	problem, we m	nust be given				
ve quarantee all our									
ve guarantee all our ne first opportunity to ervice packages incl				sume responsi	ibility. All our				



Rock Creek Lube Center (2) (2) IT PIG 12 (5) INVOICE

26157 Maple VIy Hwy SE
MAPLE VALLEY, WA, 98038
425-413-0165

79961(REPRINT)

J.r. Hayes And Sons 22430 Se 231st P119 Maple Valley, WA 98038 425-392-5722

LICENSE	YEAR	MAKE	MC	ODEL		ENGINE	MILEAGE	DATE	TIME
WA-C02599N		Ford Trucks	-150 Pic			71 (164) Turbo	35212	2/18/2020	02:26 PM
	1	4415	05.00:		L		055111053	OOMBI STEE	White Control of
			CE SCHEDU	_	. 7 11 330	Full Service	SERVICES	COMPLETED	45.95
RECOMME	NDED SEP		DATE DUE		GE DUE	1.0 - M9015	Oil Filters		45.95
Cooling System Engine Oil*			nonths	every 100 every 500	0	Premium -Oil			8.00
Front Differential		Ber	e Recs.	\$ee Recs		5.0 - GTX520 Premium -Oil			2.55
Rear Differential Transfer Case		Sec	e Recs.	See Recs every 600		Extra 1.00 -	-GTX520 @ 4.95		4.95
mansier Case				every 600	00	Environment F	ee (T)		2.65
		377							
				100					
		4							
				100	1743			27	
	<del>, -</del>	CHECK LI	ST		Some Elli				
CHECK	CLIST ITEM			ATUS					
							(		
							\'\		
							_ \ \ \		
						(		/ /	
						,	\ / \ \		
							$\vee$	9.	
							1		
						7)			
						SUBTOTAL			64.10
ANAGER:T		UPPER TECH	Marlin	OPEI	9.7	TAV (PST)			5.52
COURTESYSamuel				T/V:		TAX (PSI)			
		LOWER TECH		ſ/V:		M. He			69.62
	ARKS:					TOTAL			
SERVICE REMA						AMOUNT TENDERED	(Fleet Charge,	6000)	69.62
ERVICE REMA			1 - 6 - 6		Control of the Contro				.00
ERVICE REMA						CHANGE	***NEVT COLU	DILLED VICIT	CONTRACTOR OF THE STREET
ERVICE REMA			THE DOLLAR OF THE PERSON NAMED IN				""NEXT SCHE	DULED VISIT***	
SERVICE REMA									
SERVICE REMA									
Ve guarantee all our	parts and wo	rkmanship. If yo	u do have a prot	olem, we mu	st be given				
Ve guarantee all our ne first opportunity to	o correct the	problem in ordei	u do have a prot r for us to assum	olem, we mu	st be given ility. All our				
/e guarantee all our	o correct the plude both parts	problem in order s and labor.	r for us to assum	olem, we mu	st be given lity. All our	X		R SIGNATURE	

12-19-19



J.r. Hayes And Sons 22430 Se 231st P119 Maple Valley, WA 98038 425-392-5722

2018	-						
1010	Ford Trucks	F150 Pic	ckup <b>E</b> -p	6-c 2.7l (164) Turbo	30311	12/18/2019	03:33 PM
					SERVICES	COMPLETED	
DED SEF	RVICE				Oil Filters		45.95
				Premium -C	il Filters		8.00
Engine Oil* Front Differential Rear Differential		See Recs. See Recs.					2.55
Rear Differential Transfer Case				Extra 1.00	-GTX520 @ 4.95		4.95
				Environment	Fee (T)		2.65
				i i			
	OUEOK	NOT.		-	11		
ICT ITEN			TATUS				
TO HEN	И	5	IAIUS	— \ \-\'	1 1 .		
				7			
				1			
				}			
				1			
				1			
					(0)	3	
				İ	611		
					6		
						4 11	
						Ų	
				SUBTOTAL			64.10
	UPPER TE	CH: <sup>Marlin</sup>	OPER.01	TAX (PST)			5.52
	LOWER TE	CH: Marlin	<sub>T/V:</sub> 6				
		ASSESS FATTURE	Section 1	TOTAL	agiai , ii ite		69.62
					(Elast Chara	6000)	
				AMOUNT   TENDERED	(Fleet Charge	, 6000)	69.62
							.00
					***NEXT SCH	EDULED VISIT***	Trivicia 84
nada and	orkenneshin !	f you do have a see	phon we must be	given			
			obtem, we must be me responsibility. A			11 / 21 V 2V 1	
correct the	problem in o	ruei ioi us io assui					
ide both part			, ,,,,,	.,			
	IDED SEF	CHECK LIST ITEM  UPPER TE LOWER TE	CHECK LIST  IST ITEM S  UPPER TECH: Marlin LOWER TECH: Marlin LOWER TECH: Marlin	CHECK LIST  IST ITEM STATUS  CHECK LIST  UPPER TECH: Marlin LOWER TECH: Marlin T/V: 6  CHECK LIST  UPPER TECH: Marlin T/V: 6	DED SERVICE    DATE DUE   MILEAGE DUE   72 months   every 100000   see Recs.   See Recs.   See Recs.   See Recs.   every 60000   Environment	DED SERVICE  DATE DUE    Z months	DED SERVICE  DATE DUE  Wery 100000  every 100000  See Recs. See Re

9-19-19

77123

J.r. Hayes And Sons 22430 Se 231st P119 Maple Valley, WA 98038 425-392-5722

LICENSE	YEAR	MAKE	MO	DEL	8	ENGINE	MILEAGE	DATE	TIME
WA-C02599N	2018	Ford Trucks	F150 Pick	кир	E-p 6-c 2.	7I (164) Turbo	25051	9/17/2019	04:58 PM
	VEHIC! E	MAINTENANC	SCHEDU	F	J		SERVICES	COMPLETED	
RECOMME			ATE DUE		GE DUE	Full Service	32		45.95
Cooling System	NDED SE		2 months every 100000			1.0 - M9015	8.00		
Engine Oil*		5 moi	6 months every 5000 See Recs. See Recs. See Recs. See Recs.			Premium -Oi 5.0 - GTX520			
Front Differential Rear Differential						Premium -Oi	OTV500 @ 4.05		2.55 4.95
Transfer Case		42		every 600	000	Environment I	-GTX520 @ 4.95 Fee (T)		2.65
	2				100		, ,		
				13.7					
					0 1				
	P.								
		CHECK LIS							
CHECK	KLIST ITE	М	ST	ATUS					
							101		
						( )			
						X			
						_			
					7				
		d d				00			
					(		DIVI		
						901			
							' U		
		II.							
							gn .		
								2	
								*1	
								20	
						SUBTOTAL			
			<i>M</i> arlin	000	-n1	SUBTOTAL	21	,,	64.10
MANAGER: <sup>T</sup>		UPPER TECH: <sup>I</sup>			ER <sup>1</sup>	SUBTOTAL  TAX (PST)	al al		64.10 5.52
	el	UPPER TECH: LOWER TECH:			ER <sup>.1</sup> : 5	TAX (PST)		,,	5.52
COURTES\Samu								,	
COURTES\Samu						TAX (PST) TOTAL AMOUNT	(Fleet Charg	e, 6000)	5.52
COURTES\Samu						TAX (PST) TOTAL AMOUNT TENDERED		e, 6000)	5.52 69.62
COURTES\Samu						TAX (PST) TOTAL AMOUNT	(Fleet Charge		5.52 69.62 69.62
MANAGER: <sup>T</sup> COURTES\ <sup>©</sup> ,amu SERVICE REM						TAX (PST) TOTAL AMOUNT TENDERED	(Fleet Charg	e, 6000)	5.52 69.62 69.62
COURTES Samu SERVICE REM	ARKS:	LOWER TECH: I	Marlin	T/V	: 5	TAX (PST) TOTAL AMOUNT TENDERED	(Fleet Charg		5.52 69.62 69.62
COURTES Samu	ARKS:	LOWER TECH:	Marlin	T/V	: 5	TAX (PST) TOTAL AMOUNT TENDERED	(Fleet Charg		5.52 69.62 69.62
COURTES\Samu SERVICE REM	ur parts and v	LOWER TECH: workmanship. If you be problem in order f	Marlin	T/V	: 5	TAX (PST) TOTAL AMOUNT TENDERED	(Fleet Charg		5.52 69.62 69.62

6-28-19 A

75393(REPRINT)

J.r. Hayes And Sons 22430 Se 231st P119 Maple Valley, WA 98038 425-392-5722

LICENSE WA-C02599N	YEAR 2018	MAKI Ford Trucks		ODEL		ENGINE 7I (164) Turbo	MILEAGE 20118	<b>DATE</b> 6/27/2019	TIME 03:34 PM
			ANCE SCHED			Full Service		COMPLETED	42.95
RECOMMEN Cooling System	IDED SEF		DATE DUE 72 months	MILEA every 100	GE DUE	1.0 - M901	5 Oil Filters		
Engine Oil*			6 months every 5000		00	Premium - 5.0 - GTX5			8.00
Front Differential Rear Differential			See Recs. See Recs.	See Recs	S	Premium -			2.55 4.95
Transfer Case				every 600	000	Parts - 1 - A	2883 - Air Filter		21.95
						Environmen	t Fee (T)		2.65
		or to red					. (	)	
					757		115	+	
		OHEOK	LICT				1) \ \	1	
CHECKI	LIST ITEN	CHECK		TATUS	a discount of		7 , 0		
Onzon	LIOT II LI						.,		
					_				
				(	3				
				0	0				
			_		$(\mathcal{O})$	Si .			
					9/1				
					0	U <sub>N</sub>			
						15			
					9				
						SUBTOTAL			83.05
ANAGER: T		UPPER TE	CH: Marlin	OPE	:R: <sup>1</sup>	TAX (PST	7)		7.15
OURTESY Samuel		LOWER TE	CH: Marlin	T/V:	4				
ERVICE REMA				T07/11		TOTAL			90.20
					95 13	AMOUNT	(Fleet Charge	, 6000)	90.20
					( U )	TENDERED	_		.00
						CHANGE	***NEVT COU	EDULED VISIT***	
Control of the Contro	A 70						MEXI SCH	EDOPED AIGHT	
Type II II II II			11/1/18/19	Carlot Harris	2 5 8				
Ve guarantee all our ne first opportunity to									
ervice packages incl	ude both par	ts and labor.		·		Х			
ertify that all work has									

73786

J.r. Hayes And Sons 22430 Se 231st P119 Maple Valley, WA 98038 425-392-5722

WA-C02599N

2018

Ford Trucks

F150 Pickup

E-p 6-c 2.7l (164) Turbo

14943

4/5/2019

05:15 PM

Cooling System Engine Oil\* Front Differential Rear Differential Transfer Case

72 months 6 months See Recs. See Recs.

every 100000 every 5000 See Recs. See Recs. every 60000

Full Service 1.0 - M9015 Oil Filters Premium -Oil Filters 5.0 - GTX520 Oil Premium -Oil Extra 1.00 -GTX520 @ 4.95 Environment Fee (T)

8.00 2.55 4.95 2.65

42.95

Т	Ma	rlin	1	(PST)	61.10 5.26
Samuel	Ma	rlin	3	*	
					66.36

(Fleet Charge, 6000) 66.36

.00

71791(REPRINT)

J.r. Hayes And Sons 22430 Se 231st P119 Maple Valley, WA 98038 425-392-5722

WA-C02599N	2018	Ford Trucks	F150 Pickup	E-p	6-c 2.7l (164) Turbo	10075	12/11/2018	04:41 PM
					Full Service			42.95
Cooling System Engine Oil*		72 mo 6 moi	nths every		1.0 - M9015 ( Premium -Oil 5.0 - GTX520	Filters		8.00
Front Differential Rear Differential		See F See F			Premium -Oil			2.55
Transfer Case	- 7	366 t		60000	Extra 1.00 -	GTX520 @ 4.95		4.95
Transier Case			every	00000	Environment Fe	ee (T)		2.65

7/9

02 6211 P119 120 COPY

Т	Marlin	1	(PST)	61.10 5.26
Samuel	Marlin	2		
				66.36
			(Fleet Charge, 6000)	66.36
				.00

10-5-18

70513(REPRINT)


J.r. Hayes And Sons 22430 Se 231st P119 Maple Valley, WA 98038 425-392-5722

LICENSE	YEAR	MAKE	MC	ODEL		ENGINE	MILEAGE	DATE	TIME
WA-C02599N	2018	Ford Trucks	F150 Pic	kup	E-p 6-c 2.	71 (164) Turbo	5102	10/1/2018	05:18 PM
	VEHICLE	 MAINTENAN	L CE SCHEDU	JLE			SERVICES	COMPLETED	
RECOMME			DATE DUE	$\overline{}$	AGE DUE	Full Service			42.95
Cooling System			months	every 10	0000	1.0 - M9015 ( Premium -Oil			8.00
Engine Oil* Front Differential			onths Recs.	every 50 See Rec		5.0 - GTX520	Oil		
Rear Differential			See Recs. See Recs.		s.	Premium -Oil	GTX520 @ 4.95		2.55 4.95
Transfer Case				every 60	000	Parts - 1 - A288	83 - Air Filter		21.95
						Environment F	ee (T)		2.65
MP Investigation		CHECK LI	ST						
CHECK	KLIST ITEN	И	ST	ATUS			rse del 1:Xe Ar	- 4	-0
							1 1	, ver	. •
						$\bigcirc$	a de	/ 0	
	(4)					h/60	とって	, LIKO	
							1/ 0	4200	
						. ^	ive H		
						1/2	( ) .		
					- 1				
					1				
							6211 P	110	7
					- 1	$\bigcirc$	(2)11 P	1119 120	
						07			
					-				
					1				
						SUBTOTAL			83.05
MANAGER:T		UPPER TECH	Mariin	OPE	ER:1	TAX (PST)			7.15
COURTESYSamue	el	LOWER TECH	Marlin	T/V:					
SERVICE REMA		7 7		-		TOTAL		W -05 00/2	90.20
						AMOUNT	(Fleet Charge,	6000)	90.20
						TENDERED	, 5-,		.00
						CHANGE	4444		
							""NEXT SCHE	DULED VISIT***	
We guarantee all our									
the first opportunity to service packages incl			tor us to assum	ne responsil	oility. All our				
I certify that all work ha	· ·					X			
			MANAGE	R'S SIGNATI	JRE		CUSTOMER	R SIGNATURE	

g.

Fugate Ford P.O. BOX 217

ENUMCLAW, WA, 98022





N/A

N/A

OK V

OK 🔽

OK 🗸

7/32 OR 🗸 📗

7/32 OR 🔽

7/32 OR 🗸 📉

7/32 OR

### Customer

Name JR HAYES CONSTRUCTION

22430 SE 231 ST Address MAPLE VALLEY, WA City

98038 Zip Code

PhoneNumber (206) 379-7054(c)

mandrosko@jrhayes.com Email

## Inspection

Service Order 445023

Doug Schripsema Advisor Tech Matthew Beyer

### LIGHTS

OPERATION OF EXTERIOR LIGHT BULBS, BRAKE LIGHTS AND TURN SIGNALS

Comments:

### WINDSHIELD WIPER OPERATION

WINDSHIELD WIPER AND WASHER SQUIRTER OPERATION



OK 🗸

OK 📝 🧱

Comments:

WINDSHIELD WIPER BLADES OK 🗸

Comments:

### HORN

OK V HORN OPERATION

Comments:

### WARNING LIGHTS

OK 🗾 WARNING LIGHTS ON THE DASH

Comments:

### **BATTERY**

OK V BATTERY COLD CRANKING AMPS

Comments:

BATTERY CABLES AND TERMINAL CORROSION

Comments:

Vehicle

VIN 1FTMF1CP4JKE67362

2018 Year **FORD** Make F-150 Model

Engine 2.7L V6 ECOBOOST

Fuel

Stock Number

License/Stock C02599N/P119 Date In 07/28/2020

Completed Date

45345 Odom

# UNDER HOOD INSPECTION

ENGINE OIL LEVEL AND CONDITION	OK 🔽 📙
Comments:	
ENGINE COOLANT LEVEL AND	OK V

Comments:

ENGINE COOLING SYSTEM HOSES, OK V RADIATOR VISUAL INSPECTION

Comments:

TRANSMISSION FLUID LEVEL AND CONDITION (IF EQUIPPED WITH A DIPSITCK)

Comments: POWER STEERING FLUID LEVEL AND

CONDITION

Comments: BRAKE FLUID LEVEL AND CONDITION

**ENGINE AIR FILTER CONDITION** 

SERPENTINE BELT CONDITION

Comments:

# TIRES

ALIGNMENT CHECK OR WHEEL **BALANCE NEEDED** 

Comments

LEFT FRONT TIRE TREAD DEPTH / WEAR **PATTERN** 

Comments: 19/32

RIGHT FRONT TIRE TREAD DEPTH / WEAR PATTERN

Comments: 19/32

LEFT REAR TIRE TREAD DEPTH / WEAR PATTERN

Comments: 19/32 RIGHT REAR TIRE TREAD DEPTH / WEAR

**SPECS** 

**PATTERN** Comments: 19/32

Comments: 36PSI FRONT AND REAR

TIRE PRESSURE SET TO FACTORY

SET TO SPECS 💹



ANY ADDITIONAL COMM	ENTS
ADDITIONAL COMMENTS	OK 🗾
Comments:	
<b>UNDER VEHICLE INSPEC</b>	TION
SHOCKS / STRUTS	OK 🕢 📕
Comments:	
STEERING LINKAGE COMPONENTS	OK 🔽 📕
Comments:	
SUSPENSION COMPONENTS AND BALL JOINTS	OK 🔽 📙
Comments:	
EXHAUST LEAKS AND EXHAUST SYSTEM VISUAL INSPECTION	OK 🗸 📕
Comments:	
DRIVE SHAFT UNIVERSAL JOINTS AND CONSTANT VELOCITY (CV) BOOTS VISUAL INSPECTION	OK 🗾 📕
Comments:	
ENGINE OIL, COOLANT LEAKS, OR A/C LEAKS	OK V
Comments:	
TRANSMISSION / AWD FLUID LEAKS	OK V
Comments:	
DRIVE AXLE LEAKS	OK V
Comments:	
POWER STEERING FLUID LEAKS	N/A
Comments:	
OIL CHANGE REMINDERS	
RESET OIL CHANGE REMINDER	YES 🗾 📕
NEW LUBE STICKER FOR WINDSHIELD	YES 🗹 🧾
RETRAIN TPMS AFTER TIRE ROTATE - IF REQUIRED	
BRAKES	
BRAKES NOT CHECKED ON THIS VISIT	
Comments:	
LEFT FRONT BRAKE PAD THICKNESS	6MM OR
Comments: 10MM	
RIGHT FRONT BRAKE PAD THICKNESS	6MM OR
Comments: 10MM	
LEFT REAR BRAKE PAD THICKNESS	6MM OR
Comments: 6MM	0.01.05
RIGHT REAR BRAKE PAD THICKNESS	6MM OR
Comments: 6MM	

Rock Creek Lube Center 26157 Maple Vly Hwy SE MAPLE VALLEY, WA, 98038 425-413-0165 852 1(REPRINT)

J.r. Hayes And Sons 22430 Se 231st P119 Maple Valley, WA 98038 425-392-5722


02 6211 P119 120 AS

LICENSE	YEAR	MAKE		ODEL	1000	ENGINE	MILEAGE	DATE	TIME
WA-C02599N	2018	Ford Trucks	F150 Pic	kup I	E-p 6-c 2.	.7l (164) Turbo	55284	1/29/2021	05:02 PM
Tool Tool Street	EHICLE	MAINTENAN	CE SCHEDI	D F	450,000	Santa Marine	SERVICES	COMPLETED	ones a collision
RECOMMEN			DATE DUE		GE DUE	Full Service	OLITIOLO	00,III	49.95
Cooling System		721	months	every 100	000	1.0 - M9015 C Premium -Oil I			8.00
Engine Oil* Front Differential			onths Recs.	every 500 See Recs		5.0 - GTX530			
Rear Differential Transfer Case			Recs.	See Recs every 600		Premium -Oil Extra 1.00 -0	GTX530 @ 4.95		2.55 4.95
Transier Case				every 600	00	Environment Fe	e (T)		2.65
						0			
		CHECK LI	ST						
CHECKL	IST ITEM			TATUS		6			
		1						/	
		1							
		ì							
		}					(	1	
		1					. , ) '	$\rightarrow$	
							)	1	
		1					$\vee$ $\setminus$ $\setminus$	` `	
		1					1		
		1							
		1							
		1							
		-							
		1							
						SUBTOTAL			
MANAGER. <sup>T</sup>		UPPER TECH:	. Marlin	OPE	 R <sup>1</sup>				68.10 5.86
COURTESSamuel		LOWER TECH:		T/V:		TAX (PST)			3,00
SERVICE REMA	DVC.	LOWER TECH:		1/V:		TOTAL			73.96
SERVICE NEMA	n <b>no.</b>						(Clast Chass	6000)	
						AMOUNT TENDERED	(Fleet Charge,	0000)	73.96 .00
						CHANGE			
							***NEXT SCH	DULED VISIT	
We guarantee all our pathe first opportunity to									
service packages inclu	ide both par	ts and labor.			,	v			
I certify that all work has	been perfor	med satisfactorily.	MANAGE	R'S SIGNATU	RE	X	CUSTOME	R SIGNATURE	

COPY

Rock Creek Lube Center 26157 Maple Viy Hwy SE MAPLE VALLEY, WA, 98038 425-413-0165





J.r. Hayes And Sons 22430 Se 231st P119 Maple Valley, WA 98038 425-392-5722

02 6211 P119 120

LICENSE	YEAR	MAH	KE MO	DDEL	41, 312	ENGINE	MILEAGE	DATE	TIME
WA-C02599N	2018	Ford Truck	s F150 Pic	kup I	-p 6-c 2.	7I (164) Turbo	50096	10/27/2020	04:57 PM
	/EHICLE	MAINTEN	ANCE SCHEDL	ILE		ewillian with	SERVICES	COMPLETED	
RECOMMEN			DATE DUE		GE DUE	Full Service			49.95
Cooling System	,	A 7 5 P	72 months	every 100	000	1.0 - M9015 Premium -Oil			8.00
Engine Oil* Front Differential			6 months See Recs.	see Recs		5.0 - GTX530	Oil		
Rear Differential			See Recs.	\$ee Recs.		Premium -Oil Extra 1.00 -	GTX530 @ 4.95		2.55 4.95
Transfer Case				every 600	00	Environment F	ee (T)		2.65
		CHEC	CHST						
CHECK	LIST ITEN			ATUS					
OFILOR	CIOTITEN	,,	3,	A100				€	
2.									
							1	X	
							1 /		
						_	$\neg \mid \mid \mid$		
			1			(0	. ) \	X.	
					_	-1 "	V ,		
				$\square$	17		1		-
									- 1
				u i	J				
			Ì						
						1			
			1						
			L .						
						SUBTOTAL			68.10
MANAGER:T		UPPER TE	CH: Marlin	OPE	R!	TAX (PST)			5.86
COURTES Samuel		I OWER TE	CH: Marlin	T/V:	9				
SERVICE REMA		LOWERT		MAISTER OF	SIVE YES	TOTAL			73.96
SERVICE REMA	inko.							Name of the last	STATEMENT
						AMOUNT TENDERED	(Fleet Charge	, 6000)	73.96
						CHANGE			.00
							***NEXT SCH	EDULED VISIT**	
We guarantee all our	parts and wo	orkmanship.	If you do have a prol	olem, we mus	st be given				
the first opportunity to service packages inclu	correct the	problem in o						ET PARCON UNITED AND	INSULATION OF THE PERSON
I certify that all work has			orily:			X			
			MANAGE	R'S SIGNATU	RE	· · · · · · · · · · · · · · · · · · ·	CUSTOME	R SIGNATURE	

COPY

Rock Creek Lube Center 26157 Maple Vly Hwy SE MAPLE VALLEY, WA, 98038 425-413-0165





J.r. Hayes And Sons 22430 Se 231st P119 Maple Valley, WA 98038 425-392-5722

LICENSE	YEAR	MAK	EVE AND A	MOD	EL		ENGINE	MILEAGE	DATE	TIME
WA-C02599N	2018	Ford Truc	ks 👢 F15	0 Picku	ib.	-р 6-с2	7l (16 <u>4)</u> Turbo	60,067	4/12/2021	03:04 PM
V	EHICLE	MAINTEN	ANCE SCH	EDULE	E 41.5		July 1	SERVICES	COMPLETED	
RECOMMEN			DATE D			GE DUE	Full Service			49.95
Cooling System Engine Oil* Front Differential Rear Differential Transfer Case*			72 Months 6 Months See Recs. See Recs.		EVERY 1 EVERY 5 See Recs See Recs EVERY 6	000 i. i.	1.0 - M9015 Oi Premium -Oil Fi 5.0 - GTX530 ( Premium -Oil Extra 1.00 -G Environment Fee	Iters Dil TX530 @ 4.95		8.00 2.55 4.95 2.65
							F. A.		*	
7. 1. 3. 4. CW		CHECK	LIST	<b>H</b> .	6. JA	4	3 N 8	Ŷ.	W.	
CHECKL	IST ITEM	VI STATE		STA	TUS	- 17	5 1 1			
				k:		W 44	TAX	H		
						=	P	19	i,	
			×			3 ,			307 156	
		4	30						ű e	×
				18						
T		P.	Marlin		- 4	01	SUBTOTAL	g)		68.10 5.86
ANAGER: Samue	el	UPPER TE	CH: Marlin		OPE	R#1	TAX			
OURTESY:		LOWER TE	CH:		T/V:					73.96
ERVICE REMAI	RKS:	y 1911.971	5 5 5 5	N. E.	ASSES.		TOTAL	(Fleet Charge,	5000)	73.96
Front B Rear B	rake	25 7	5%				AMOUNT TENDERED	HENEW RANG		.00
			- 35	10.0			CHANGE	***NEXT SCH	EDULED VISIT***	
e guarantee all our pe first opportunity to ervice packages inclu-	correct the de both par	problem in o	rder for us to a				X			

### Fugate Ford P.O. BOX 217

\* ENUMCLAW, WA, 98022





OK V

### Customer

JR HAYES CONSTRUCTION

22430 SE 231 ST Address MAPLE VALLEY, WA City

98038 Zip Code

(206) 379-7054(c) PhoneNumber

mandrosko@jrhayes.com Email

# Inspection

Service Order 453694

Advisor Vince Swanson Jim Ellison Tech

### LIGHTS

OPERATION OF EXTERIOR LIGHT BULBS, BRAKE LIGHTS AND TURN SIGNALS

: No Comments:

# WINDSHIELD WIPER OPERATION

WINDSHIELD WIPER AND WASHER

SQUIRTER OPERATION

Comments:

WINDSHIELD WIPER BLADES Comments:

HORN

HORN OPERATION

Comments:

### WARNING LIGHTS

WARNING LIGHTS ON THE DASH

Comments:

**BATTERY** 

BATTERY COLD CRANKING AMPS

Comments:

BATTERY CABLES AND TERMINAL

CORROSION

Comments:

## Vehicle

VIN 1FTMF1CP4JKE67362

Year 2018 Make **FORD** Model F-150

2.7L V6 ECOBOOST Engine

Fuel

Stock Number

License/Stock C02599N/P119

Date In 05/19/2021 11:02:57 AM

Completed Date

Odom 61875

## UNDER HOOD INSPECTION

ENGINE OIL LEVEL AND CONDITION OK V Comments:

**ENGINE COOLANT LEVEL AND** CONDITION

OK 🗸 📕

OK 🗸

OK 🗾

OK V

OK 🔽

OK V

OK 🗸

CONDITION (IF EQUIPPED WITH A

Comments:

Comments:



ANY ADDITIONAL COMM	ENTS		34
ADDITIONAL COMMENTS	OK	1	
Comments:			
UNDER VEHICLE INSPEC	TION		
SHOCKS / STRUTS	OK	<b>V</b>	
Comments:			
STEERING LINKAGE COMPONENTS	OK	1	
Comments:			
SUSPENSION COMPONENTS AND BALL JOINTS	OK	1	
Comments:			
EXHAUST LEAKS AND EXHAUST SYSTEM VISUAL INSPECTION	OK	1	
Comments:			
DRIVE SHAFT UNIVERSAL JOINTS AND CONSTANT VELOCITY (CV) BOOTS VISUAL INSPECTION	OK	1	
Comments:			
ENGINE OIL, COOLANT LEAKS, OR A/C LEAKS	OK	1	
Comments:			
TRANSMISSION / AWD FLUID LEAKS	OK	1	
Comments:			
DRIVE AXLE LEAKS	OK	<b>V</b>	
Comments:		Total Control	
POWER STEERING FLUID LEAKS	OK		
Comments:			
OIL CHANGE REMINDERS	S		
RESET OIL CHANGE REMINDER			
NEW LUBE STICKER FOR WINDSHIELD			
RETRAIN TPMS AFTER TIRE ROTATE - IF REQUIRED			
BRAKES	200		
BRAKES NOT CHECKED ON THIS VISIT			
Comments:			
LEFT FRONT BRAKE PAD THICKNESS	6MM OR	1	
Comments: 8MM-WHEEL			
RIGHT FRONT BRAKE PAD THICKNESS	6MM OR	1	
Comments:			
LEFT REAR BRAKE PAD THICKNESS	6MM OR	V	
Comments: 8MM-WHEEL			
RIGHT REAR BRAKE PAD THICKNESS  Comments:	6MM OR	1	
o o minion to .			

# Rock Creek Lube Center

26157 Maple Vly Hwy SE MAPLE VALLEY, WA, 98038 425-413-0165

(11	NV	0	ICI	E'
8897	7			

J.r. Hayes And Sons 22430 Se 231st P119 Maple Valley, WA 98038 425-392-5722

02 6211 P119 120 At

	YEAR	MAK	(E	МО	DEL		ENGINE	MILEAGE	DATE	TIME
WA-C02599N	2018	Ford True	cks	F150 Pic	kup	E-p 6-c 2.	7l (164) Turbo	68,202	9/14/2021	04:12 PM
V	EHICLE	MAINTEN	IANCE S	CHEDU	LE			SERVICES	COMPLETED	1
RECOMMEN	DED SE	RVICE	DAT	E DUE	MILEA	GE DUE	Full Service			55.95
Cooling System			72 Mon		EVERY 1		1.0 - M9015 C Premium -Oil F			8.00
Engine Oil* Front Differential			6 Monti See Re		EVERY 5 See Recs		5.0 - GTX530	Oil		1
Rear Differential Transfer Case*			See Re	cs.	See Recs EVERY 6		Premium -Oil Extra 1.00 -0	GTX530 @ 4.95		2.55 4.95
Walloto, Gaog					LVLIKI	.0000	Environment Fe	e (T)		2.65
										,
										-1
										, \$
OUEOW	IOT ITC	CHECI	LIST	Tall Mag	ATUC					
CHECKL	.151 HE	IVI	-	51/	ATUS					
				Y						
				Y						
				<b>Y</b>			QUIDTOTAL			74 10
T				<b>M</b>		01	SUBTOTAL (PST)			74.10 6.45
	ēl	UPPER TI			OPE		SUBTOTAL (PST)			
IANAGER: Samue		UPPER TI LOWER TI	ECH: Ma		OPEI T/V:	R <sub>12</sub>	(PST)			
			ECH: Ma			R <sub>12</sub>	(PST)	(Fleet Charge,	5000)	6.45
IANAGER: Samue	RKS:	LOWER TI	ECH: <sub>Ma</sub>	rlin	T/V:	R <sub>12</sub>	TAX  TOTAL  AMOUNT TENDERED	(Fleet Charge, t	5000)	6.45
MANAGER: Samue COURTESY:	RKS:	LOWER TI	ECH: <sub>Ma</sub>	rlin	T/V:	R <sub>12</sub>	TAX  TOTAL  AMOUNT		5000)	80.55 80.55 .00
IANAGER: Samue OURTESY: ERVICE REMA	RKS:	LOWER TI	ECH: <sub>Ma</sub>	rlin	T/V:	R <sub>12</sub>	TAX  TOTAL  AMOUNT TENDERED		1800-00-	80.55 80.55 .00
ANAGER: Samue OURTESY: ERVICE REMA	PRKS:	LOWER TI	ECH: Ma	ound nave a prob	T/V:	R <sub>12</sub>	TAX  TOTAL  AMOUNT TENDERED		1800-00-	80.55 80.55 .00



# www.jiffylube.com

Jiffy Lube # 2929 TEAM CAR CARE WEST, LLC 24001 KENT KANGLEY RD MAPLE VALLEY, IVA 98038 (425) 432-9759

DATE: 09/22/22 04:33 PM DAVIDICE # 447932316

02 6209 PIL9 120

### CUSTOMER INFORMATION

JR HAYES JR HAYES COMP

MAPLE VALLEY, WA, 98038

VEHICLE INFORMATION

2018

FORD TRUCKS F150 PICKUP

2,7L 6Cyl Turbo ((PI) Fuel injected

LICENSE PLATE WA-C02599W VIN: 1FTMF1CP4JKE67362

MILEAGE: 75,135

DIL CHANGE INTERVAL 4000

FLEET INFORMATION

FLEET.

JRHS224 JR HAYES AND SONS INC

AUTHORIZER NAME:

TONY

DRIVER NAME:

CORY

VEHICLE/UNIT NUMBER

P119

VIN NUMBER:

1FTMF1CP4JKE67362

Remit To: Local Fleets

PO BOX 11407 DEPT# 5938 BIRMRIGHAM, AL 35246

DESCRIPTION

SIGNATURE SERVICE HIGH MILEAGE OIL FILTER CF8154

PZL HIGH MILEAGE SAE 5W30 SP SHOP SUPPLY/WASTE DISPOSAL

1.0 QT. LOW

QTY

1.00 6.00

1.00

PRICE

8 99

4.99

SERVICE CHECKLIST

OIL LEVEL PRIOR TO SERVICE

TIRE PRESSURE

F35 R36

SERVACE COMMENTS

DUA TY MERECTION BY X THOMPSON THANKS FOR CHOOSING JIFFY LUBE

HAVE A RECEDAY!!!

FILTER LOCATION PREVENTS 100% CLEANUP TAMPER SEAL APPLIED TO DRAIN PLUG WE SINGERELY APPRECIATE YOUR BUSINESS

SERVICES PERFORMED BY:

CSA UPPER BAY

COURTESY

XAVIER T.

ANDREWR XAMER L

TEAM LEAD

XAVIER T

LOWER BAY CASHIER

ANDREW K XAVIER T



### PAYMENT INFORMATION

TAXABLE	71 98
NONTAXABLE	17.99
GROSS SALES	89.97
FLB20%	-17-09
NETSALES	71.98
SALES TAX	6 26
TOTAL DUE	USD3 78 24
Local Fleet	USD\$ 78 24

### AUTHORIZED AND RECEIVED BY

Corolle del advine vietges receipt of good, such or le vices in the serioush of the Fittel one in his and gyress to perform the obligations set illust in the Catanoiders agreement with the loss

MESSAGES

JOIN OUR TEAM TODAY BY TEXTING "JIFFY" TO 92711 PLEASE STAY SAFE AND REMEMBER TO RATE US ON GOOGLE!!' DISPOSAL FEE HELPS OFFSET COST INCURRED TO DISPOSE AND RECYCLE WASTE FLUIDS AND MAY INCLUDE PROFIT

BY SIGNING, GUEST AGREES TO TERMS AND CONDITIONS ON THE BACK OF THIS INVOICE.

39672495

MADO



www.jiffylube.com

Jiffy Lube # 2585 TEAM CAR CARE WEST, LLC 17317 Smokey Point Blvd Arlington, WA 98223 (360) 658-7968

WORK ORDER #: 11 DATE: 06/03/22 11:20 AM INVOICE #: 20389279

02 6209 PIL9 120 AC

CUSTOMER INFORMATION

VEHICLE INFORMATION

JR HAYES

JR HAYES COMP

MAPLE VALLEY, WA, 98038

(206) 595-9443

FORD TRUCKS

F150 PICKUP

2.7L 6Cyl Turbo ([P]) Fuel Injected

LICENSE PLATE: WA-C02599W

VIN: 1FTMF1CP4JKE67362

MILEAGE: 81,920

OIL CHANGE INTERVAL: 4000

**FLEET INFORMATION** 

FLEET:

JRHS224 JR HAYES AND SONS INC

DRIVER NAME:

**NOLAN** 

1FTMF1CP4JKE67362

VEHICLE/UNIT NUMBER:

P119

VIN NUMBER:

Remit To: Local Fleets

PO BOX 11407 DEPT# 5938 BIRMINGHAM, AL 35246

QTY DESCRIPTION SIGNATURE SERVICE HIGH MILEAGE 1.00 ECO OIL FILTER X10387 6.00 PZL HIGH MILEAGE SAE 5W30 SP 1.00 SHOP SUPPLY/WASTE DISPOSAL 1.00 OIL DRAIN PLUG

SERVICE CHECKLIST

OIL LEVEL PRIOR TO SERVICE

FIIII

TIRE PRESSURE

F35 R35

75.99

8.99

4.99

5.99

SERVICE COMMENTS

QUALITY INSPECTION BY A. MILLER

WE SINCERELY APPRECIATE YOUR BUSINESS

TAMPER SEAL APPLIED TO DRAIN PLUG

FILTER LOCATION PREVENTS 100% CLEANUP

MOTOROIL EXTRACTED THROUGH EVAC PROCESS

GUEST PROVIDED WITH A REPAIR ESTIMATE

REPLACED PLASIC DRAIN PLUG

Local Fleet

SERVICE HISTORY

DATE

LOCATION

**MILEAGE** 

SERVICES

02/22/2022

UPPER BAY:

COURTESY:

2929

75135

SSH

SERVICES PERFORMED BY: CSA:

RACHEL M. SHANE P. RACHEL M. **TEAM LEAD:** 

ANDREW M.

RACHEL M.

LOWER BAY: CASHIER:

NATHANIEL H.

PAYMENT INFORMATION TAXABLE 76.77 19.19 NONTAXABLE 95.96 **GROSS SALES** -19.19 **FLB20%** 76.77 **NET SALES TAXABLE** 7.14 TOTAL DUE USD\$ 83.91

AUTHORIZED AND RECEIVED BY

dholder acknowledges receipt of goods and/or services in the amount of the Total shown hen and agrees to perform the obligations set forth in the Cardholder's agreement with the issuer

#### **MESSAGES**


IF YOU HAD YOUR WHEELS, TIRES, OR BRAKES SERVICED, PLEASE RETURN IN 50 MILES TO HAVE YOUR LUG NUTS RETORQUED THANK YOU FOR VISITING THE SMOKEY POINT JIFFY LUBE DONT FORGET ABOUT OUR FREE TOP OFF POLICY:)

DISPOSAL FEE HELPS OFFSET COST INCURRED TO DISPOSE AND RECYCLE WASTE FLUIDS AND MAY INCLUDE PROFIT

BY SIGNING, GUEST AGREES TO TERMS AND CONDITIONS ON THE BACK OF THIS INVOICE.

31320261

USD\$ 83.91



PRICE

79.99

10.99

6.99

www.jiffylube.com

Jiffy Lube # 2232 TEAM CAR CARE WEST, LLC 4000 S.W. Alaska Street Seattle, WA 98116

WORK ORDER #: 201 DATE: 10/21/22 02:34 PM INVOICE #: 42457027

2 6209 PIG 120 AB (206) 932-1592

**CUSTOMER INFORMATION** 

JR HAYES JR HAYES COMP

MAPLE VALLEY, WA, 98038

(206) 595-9443

**VEHICLE INFORMATION** 

2018

FORD TRUCKS F150 PICKUP

2.7L 6Cyl Turbo ([P]) Fuel Injected

LICENSE PLATE: WA-C02599W VIN: 1FTMF1CP4JKE67362

MILEAGE: 91,589

OIL CHANGE INTERVAL: 4000

FLEET INFORMATION

FLEET:

JRHS224 JR HAYES AND SONS INC

AUTHORIZER NAME: VEHICLE/UNIT NUMBER:

MIKE

P119

DRIVER NAME:

**NOLAN** 

VIN NUMBER:

1FTMF1CP4JKE67362

Remit To: Local Fleets

PO BOX 11407 DEPT# 5938

BIRMINGHAM, AL 35246 DESCRIPTION

SIGNATURE SERVICE HIGH MILEAGE OIL FILTER CF8154

PZL HIGH MILEAGE SAE 5W30 SP SHOP SUPPLY/WASTE DISPOSAL

SERVICE CHECKLIST OIL LEVEL PRIOR TO SERVICE

.5 QT LOW

TIRE PRESSURE

QTY

1.00

6.00

1.00

F50 R70

SERVICE COMMENTS

QUALITY INSPECTION BY J. SCHAIBLE

MOTOROIL EXTRACTED THROUGH EVAC PROCESS

FILTER LOCATION PREVENTS 100% CLEANUP

GUEST PROVIDED WITH A REPAIR ESTIMATE

SERVICE HISTORY

DATE

02/22/2022

COURTESY:

LOCATION

**MILEAGE** 

**SERVICES** 

2585 06/03/2022

2929

81920

PLG SSH

75135

SSH

SERVICES PERFORMED BY:

CSA:

JERIS.

JERIS.

TEAM LEAD:

JERIS.

AQEELAH W. UPPER BAY:

LOWER BAY:

MAX F.

CASHIER:

AQEELAH W.

PAYMENT INFORMATION

**GROSS SALES** FI B20%

**NET SALES** 

SALES TAX TOTAL DUE

8.03 USD\$ 86.41

97.97

-19.59

78.38

Local Fleet

USD\$ 86.41

**AUTHORIZED AND RECEIVED BY** 

Cardholder acknowledges receipt of goods and/or services in the amount of the Total shown here or and agrees to perform the obligations set forth in the Cardholder's agreement with the Issuer

### **MESSAGES**

OPEN

FULL SERVICE REPAIR FOR ALL OF YOUR VEHICLE NEEDS LEAVE US A REVIEW ON GOOGLE OR YELP DISPOSAL FEE HELPS OFFSET COST INCURRED TO DISPOSE AND RECYCLE WASTE FLUIDS AND MAY INCLUDE PROFIT